

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
514	Model 514 100 Mbps Fiber Optic Transceiver.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
515	Model 515 100 Mbps UTP Transceiver.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
525	PhoneNet Starconnector 16-Pack for Model 3394 LattisTalk Router/Repeater.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
557	Model 557 Token Ring Daughtercard for the Model 3486 LattisEngine/486. Bus mastering device connects internal Token Ring backplane of the System 3000 to Model 3486 16-bit ISA bus.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
559	Model 559 Embedded Management Tool (EMT) for Token Ring Host Modules (5502, 5505, 5505P, 5575-C, and 5575-F).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
600	Optivity Workgroup - EZ LAN Windows Entry Level Network Management Software 3.2, Requires Windows 95 or DOS/Windows 3.1 station*	FAIL	3.2	N/A	N/A	Upgrade to Optivity Workgroup 4.0
600	Optivity Workgroup - EZ LAN Windows Entry Level Network Management Software 3.3, Requires Windows 95 or DOS/Windows 3.1 station*	FAIL	3.3	N/A	N/A	Upgrade to Optivity Workgroup 4.0
655	Version 1.0 SNMP Transport Gateway for OS/2 Version 2.x - ISA (Industry Standard Architecture).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
656	Version 1.0 SNMP Transport Gateway for OS/2 Version 2.x - MC (MicroChannel). Includes 3.5" diskettes.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
670	Model 670 Release 1.0 FaultMan for UNIX (SunNet Manager). Model 637 Optivity for UNIX Release 2.1 or higher required. Includes 3 support staff clients.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
671	Model 671 Release 1.0 PolicyMan for UNIX (SunNet Manager). Model 637 Optivity for UNIX Release 2.1 or higher required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
672	Model 672 Release 1.0 TrendMan for UNIX (SunNet Manager). Model 637 Optivity for UNIX Release 2.1 or higher required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
673	Model 673 Release 2.0 MeterMan for UNIX (SunNet Manager). Model 637 Optivity for UNIX Release 2.1 or higher required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
680	Model 680 Version 1.0 MeterMan and MIBMan for DOS. Model 636-03 LNM Version 4.1 for DOS/Windows 3.1 required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
691	Model 691 LattisBoot Server Version 1.0 for DOS. Stand-alone BOOTP Server for use with Microsoft DOS/Windows 3.x.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
694	Model 694 Token Ring BridgeMan Version 1.0 for DOS. Manages Models 2722 and 3522 Token Ring Bridges. Model 636-03 or Model 600 required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
695	Model 695 Release 2.1 RouterMan for UNIX (Sun, HP, or IBM).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
696	Model 696 Release 2.0 PathMan for UNIX (SunNet Manager). Model 637-2 Optivity for UNIX Release 3.0 with SunNet Manager Release 2.0 required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
697	SwitchMan Version 1.0 for UNIX Ethernet Switching Engine Management. Sun OS required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
698	Release 2.0 Sun/UNIX Network Management Application for ATM. SunNet Manager 2.2.x required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
760	Model 760 Release 1.0 Permanent Virtual Channel Connection Management System (UNIX) for LattisCell ATM switches.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
761	ATM Control Software Rel. 2.1 - UNI 3.0 and net-side IISP Connection Management (CMS) and ATMF LANE 1.0 services (MCS) for standalone Sparc. Requires 975-248 SONET/SDH SBus card. Interoperates with ARE running LANE/1577	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
773	Model 773 2Mb SIMM Memory Option Kit for 3395A. Required if using TN3270, ARAP, IPX or XRemote options, or if enabling PPP or XPrinter. (Required if using SW version 5.3).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
800	Model 800 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI Port. (Includes North American power cord).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
804	Model 804 16 x 4 RJ-11 Patch Panel.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
807	DB-25 Female to RJ-45 DTE Adapter for Model 3395 Terminal Server.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
808	DB-25 Male to RJ-45 DCE Adapter for Model 3395 Terminal Server.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
809	DB-9 Female to RJ-45 DTE Adapter for Model 3395 Terminal Server.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
928	10BASE-T Transceiver	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
971	Router DTE RS232 Adapter Cable for Model 3386 or 3806 - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
972	Router DTE X.21 Adapter Cable for Model 3386 or 3806 - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2705	Model 2705 Token Ring 16-port Active Retiming STP/UTP Workgroup Concentrator with STP RI/RO (Can be stand-alone or expansion unit for Model 2715/2715-F cluster configuration). Includes Model 958 TR Workgroup Expansion Cable.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2722	Model 2722 Token Ring Local Bridge (Stand-alone unit).	FAIL	V2.0	N/A	N/A	Cannot set year to = 00. Agent v2.4 fixes problem, upgrade available via Customer Service.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
2803	LattisHub Model 2803 10BASE-T Workgroup Concentrator with AUI Interconnection Port. (Can be stand-alone or expansion-connected to a LattisHub Model 281x Managed 10BASE-T Concentrator.) Includes Model 988 10BASE-T Workgroup Concentrator Expansion Cable.*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2804	LattisHub Model 2804 10BASE-T Workgroup Concentrator with 10BASE-FL Interconnection Port. (Can be stand-alone or expansion-connected to a LattisHub Model 281x Managed 10BASE-T Concentrator.) Includes Model 988 10BASE-T Workgroup Conc. Expansion Cable.*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3002	460 Watt Power Supply Module for Model 3000 Premises Concentrator.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3174	Model 3174 Workstation Controller Module for 3270 and Token Ring SNA Users.					IBM
3302	Shielded Twisted Pair (STP) Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3305	Unshielded Twisted Pair (UTP) Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3328	Model 3328 Ethernet Switching Engine (ESE) providing switching between six Ethernet segments.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3394	LattisTalk Router/Repeater.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3486	Model 3486 LattisEngine with i486DX2-66MHz, 170Mb IDE HDD, 16Mb DRAM, 256KB L2 cache, 1.44Mb 3.5" floppy drive, and 2 integrated 32-bit CPU Local Bus Ethernet controllers.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3513	Model 3513 Token Ring Network Management Module with Shielded Twisted Pair (STP) Repeater. Includes License for Basic Network Management Agent. (Order SL351X-A for Advanced Agent).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3522	Token Ring Local Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3532	Model 3532 Token Ring Shielded Twisted Pair (STP) Repeater Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3803	Model 3803 Ethernet Personality Module. Provides one Ethernet port configurable for chassis backplane or external AUI interface.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3806	Model 3806 Dual-Port Serial Personality Module. Provides two serial ports configurable for V.35, RS449, RS232 or X.21 operation via adapter cables.*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3809	FDDI Personality Module. Provides one FDDI port for external MIC interface.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3904	Model 3904 Fiber Optic FDDI Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3905	Unshielded Twisted Pair (UTP) FDDI Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4290	V.35 Adapter Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4590	Dual Ethernet/DSDE High Speed Filters Expansion Option	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5001	Model 5001 950W AC Power Supply (Minimum one supply required per 5000 chassis).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5054	Model 5054 Upgrade Kit Option - AFN Flash Memory Card Upgrade, Flash Card not included.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5110	Model 5110 Supervisory Module (One required per 5000 chassis).	FAIL	N/A	1.1.1	N/A	Upgrade to firmware v1.1.3, order number AD0011011.
5115	Model 5115 Supervisory Module (One required per 5005 chassis).	FAIL	N/A	1.1.1	N/A	Upgrade to firmware v1.1.3, order number AD0011011.
5200	Dual Port T1 Framer/Multiplexer Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5201	Dual Port T1 Framer/Multiplexer Link Module - DACS 56K	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5307	Model 5307 24-Port 10BASE-T Ethernet Host Module with two 50 pin Telco D-Connectors.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5308	Model 5308 24-Port 10BASE-T Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5311	Model 5311 Ethernet Data Collection Engine (DCE) for Model 5310 Ethernet Network Management Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5390	Model 5390 Communications Server base unit with TCP/IP dial up routing and terminal service software CD version 9.0. 24 Asynchronous, 115.2 Kbps, RS-232 Ports. PPP and SLIP link layer protocol support. Includes Tech. Pubs on CD-ROM.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5431	Dual Ethernet/Dual Sync Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5455	Quad Port Ethernet High Speed Filters Daughterboard	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
550B	Token Ring Unshielded Twisted Pair (UTP) Media Filter w/Shielded RJ45 (EN 55 022 Class B)	PASS	N/A	N/A	N/A	
5502	Model 5502 24-Port Passive STP/UTP Token Ring Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5505	Model 5505 24-Port Active Retiming STP/UTP Token Ring Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
5511	Model 5511 Token Ring Data Collection Engine (DCE) for Model 5510 Token Ring Network Management Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5531	Dual Ethernet/Dual Sync - Std.Filters Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5904	Model 5904 6-Port FDDI Multimode Fiber Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5905	Model 5905 6-Port FDDI UTP Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5935	FDDI High Speed Filters Daughterboard	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
10114	16-Port ATM Switch with SONET/SDH 155Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10115	16-Port ATM Switch with 12 SONET/SDH 155Mb/s UTP Ports and 4 SONET/SDH 155 Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
24000	AN/12-port ANH ISDN BRI S/T (without NT1) Adapter Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
24001	AN/12-port ANH 3rd Synchronous Adapter Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
28015	10 Mbps UTP Switched Ethernet Workgroup Concentrator. Includes License for Core Switching Software.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
28104	LattisSwitch Model 28104 100Mbps Fiber Optics Switched Ethernet Concentrator.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
28115	10/100 Mbps UTP Fast Ethernet Switch.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
30001	ASN 8M DRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
30002	ASN 16M DRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
30003	ASN 32M DRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
34008	Quad BRI Net Module for ASN	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34010	Single 100BASE-T Net module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34013	ASN Hot Swap Stack Starter 8MDRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
34014	ASN Hot Swap Stack Starter 16MDRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
34015	ASN Hot Swap Stack Starter 32MDRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50007	1M to 2M Flash SIMM Spare/Upgrade	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50022	AN/12-port ANH ISDN BRI S/T (without NT1) Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
50025	AN/12-port ANH 3rd Synchronous Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
71000	BLN-2 Base Unit - Dual Power Supplies	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
71001	BLN-2 DC Base Unit - Dual Power Supplies	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
71004	BLN-2 Base Unit - Single Power Supply	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
72000	BLN Base Unit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
73000	BCN Base Unit*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
73001	BCN DC Base Unit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
75010	BLN/BCN System Resource Module (SRM-F)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
75151	FRE2-040 Spare 8MB *	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
75153	FRE2-040 Spare 16MB *	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
75157	FRE2-040 Spare 32MB *	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
76024	EZ Internetwork Windows Entry Level Router Network Management Console Software Version 1.2, Requires DOS/Windows 3.1 or Windows 95 Station*	FAIL	V1.2	N/A	N/A	Upgrade to Optivity Workgroup 4.0
76024	EZ Internetwork Windows Entry Level Router Network Management Console Software Version 1.3, Requires DOS/Windows 3.1 or Windows 95 Station*	FAIL	V1.3	N/A	N/A	Upgrade to Optivity Workgroup 4.0
77005	BLN-2 AC Base Unit - Single Power Supply	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
77010	BLN-2 AC Base Unit - Dual Power Supplies	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
77011	BLN-2 DC Base Unit - Dual Power Supplies	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
77012	BCN Base Unit**	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
77013	BCN DC Base Unit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
77016	BLN AC Base Unit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
90028	Version 8.1 On-Line Doc CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90029	Version 8.1 Connecting BayStack AN and ANH Systems to a Network	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1000*	SNAPS	PASS	N/A	N/A	N/A	Dates/Year not used in product. No action required.
10000	FN: LAN/WAN - 2x2 Hi Perf (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10001	Flash/Floppy FN: LAN/WAN - 2x2 Hi Perf (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10002	FN: LAN/WAN - 2x2 Hi Perf (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10003	Flash/Floppy FN: LAN/WAN - 2x2 Hi Perf (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114A	Model 10114A 16-Port ATM Switch with SONET/SDH 155Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114A-SM	Model 10114A-SM 16-Port ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 SONET/SDH 155Mb/s Single Mode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114-DS3	16-Port ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 DS3 45Mb/s Coax Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114-E3	Model 10114-E3 16-Port ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 E3 34Mb/s Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114-EV	Model 10114-EV LattisCell ATM Evaluator's Kit comprised of Model 10114 16-Port ATM Switch with SONET/SDH 155Mb/s Multi Mode Fiber Ports, (2) Model 975-192 SBus Adapter Cards, Model 698 NMA, and Model 761 CMS.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114R	16-Port Redundant Power Supply ATM Switch with SONET/SDH 155Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114R-DS3	16-Port Redundant Power Supply ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 DS3 45Mb/s Coax Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114R-E3	16-Port Redundant Power Supply ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 E3 34Mb/s Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114R-SM	16-Port Redundant Power Supply ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 SONET/SDH 155Mb/s Single Mode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10114-SM	16-Port ATM Switch with 14 SONET/SDH 155Mb/s Multimode Fiber Ports and 2 SONET/SDH 155Mb/s Single Mode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10115A	16-Port ATM Switch with 12 SONET/SDH 155Mb/s UTP Ports and 4 SONET/SDH 155 Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10115R	16-Port Redundant Power Supply ATM Switch with 12 SONET/SDH 155Mb/s UTP Ports and 4 SONET/SDH 155 Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10124	Model 10124 16-Port ATM Switch with 4B/5B 100Mb/s Multi Mode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10124-S	16-Port ATM Switch with 12 4B/5B 100Mb/s Multimode Fiber Ports and 4 SONET/SDH 155Mb/s Multimode Fiber Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1029	Flash/Floppy FN: LAN/WAN - 2 x 2 Hi Perf/Filters (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1032	Flash/Floppy FN: LAN/WAN - 2 x 2 Hi Perf/Filters (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10324-F	EtherCell Ethernet-to-ATM Switch with 8 10Base-F Ethernet Ports, and one 155Mb/s SONET OC-3c Multi-Mode Fiber Port	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10328-F	EtherCell Ethernet-to-ATM Switch with 12 10BASE-T Ethernet Ports, and 1 155Mb/s SONET OC-3c Multimode Fiber Port.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
10328-SM	EtherCell Ethernet-to-ATM Switch with 12 10BASE-T Ethernet Ports, and one 155Mb/s SONET OC-3c Single Mode Fiber Port.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1045-8	FN: LAN/WAN - 2 x 2 Hi Perf/Filters (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1047-8	FN: LAN/WAN - 2 x 2 Hi Perf/Filters (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1101	FN Base Unit (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1102	FN Base Unit (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1103	Flash/Floppy FN Base Unit (110V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1104	Flash/Floppy FN Base Unit (220V)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15000	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (V.35, V.28, & RS232 interface options)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15001	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (X.21 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
15002	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15003	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (RS449/RS422 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15004	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (V.35, V.28, & RS232 interface options)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15005	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (X.21 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15006	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15007	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (RS449/RS422 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15008	Token Ring AFN w/ floppy disk drive: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15009	Token Ring AFN w/ floppy disk drive: LAN/WAN - 2 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15010	Token Ring AFN w/ Flash Memory Card: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
15011	Token Ring AFN w/ Flash Memory Card: LAN/WAN - 2 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1515	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (V.35, V.28, & RS232 interface options)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1516	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (X.21 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1517	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1518	Ethernet AFN w/ floppy disk drive: LAN/WAN - 1 x 2 (RS449/RS422 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1520	Token Ring AFN w/ floppy disk drive: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1521	Token Ring AFN w/ floppy disk drive: LAN/WAN - 2 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1525	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (V.35, V.28, & RS232 interface options)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1526	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (X.21 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1527	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1528	Ethernet AFN w/ Flash Memory Card: LAN/WAN - 1 x 2 (RS449/RS422 interface option)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1529	Token Ring AFN w/ Flash Memory Card: LAN/WAN - 1 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
1530	Token Ring AFN w/ Flash Memory Card: LAN/WAN - 2 x 2	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
20002	AN: 1 Ethernet x 2 Sync (4M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
20003	AN: 1 Ethernet x 2 Sync (8M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
20004	AN: 1 Ethernet x 2 Sync (16M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2010	LN Base Unit - 110V/220V (Floppy only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2020	LN Base Unit - 110V/220V (Floppy/Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
21002	AN: 1 Token Ring x 2 Sync (4M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
21003	AN: 1 Token Ring x 2 Sync (8M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
21004	AN: 1 Token Ring x 2 Sync (16M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
22002	AN: 1 Ethernet x 1 Token Ring x 2 Sync (4M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
22003	AN: 1 Ethernet x 1 Token Ring x 2 Sync (8M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
22004	AN: 1 Ethernet x 1 Token Ring x 2 Sync (16M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23002	ANH: 12-port Ethernet hub x 2 Sync (4M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23003	ANH: 12-port Ethernet hub x 2 Sync (8M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23004	ANH: 12-port Ethernet hub x 2 Sync (16M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23102	ANH: 8-port Ethernet hub x2 Sync (4M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23103	ANH: 8-port Ethernet hub x2 Sync (8M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
23104	ANH: 8-port Ethernet hub x2 Sync (16M DRAM)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
24000-S	AN/12-port ANH ISDN BRI	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
24001-S	AN/12-port ANH 3rd Synchronous	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2702B-C	Model 2702B-C Token Ring 16-Port Passive STP/UTP Workgroup Concentrator with Speed Detect (Can be stand-alone or expansion unit for Model 2712B/2712B-F cluster configuration). Includes Model 958 TR Workgroup Expansion Cable.*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2702-C	Model 2702-C Token Ring 16-port Passive STP/UTP Workgroup Concentrator (Can be stand-alone or expansion unit for Model 2712/2712-F cluster configuration). Includes Model 958 TR Workgroup Expansion Cable.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2705B	Model 2705B Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect and STP RI/RO (Can be stand-alone or expansion unit for Model 2715B/2715B-F cluster configuration). Includes Model 958 TR Workgroup Expansion Cable.*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2712-04	Model 2712 Option 04 Managed Token Ring 16-port Passive STP/UTP Workgroup Concentrator with STP RI/RO and Advanced IP Agent Firmware with Local Load Capability. Includes License for Advanced IP Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2712-05	Model 2712 Option 05 Managed Token Ring 16-port Passive STP/UTP Workgroup Concentrator with STP RI/RO and Basic IP/IPX Agent Firmware with Local Load Capability. Includes License for Basic IP/IPX Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2712B-04	Model 2712B-04 Managed Token Ring 16-Port Passive STP/UTP Workgroup Concentrator with Speed Detect, STP RI/RO and Advanced IP Agent Firmware and Local Load Capability. Includes License for Advanced IP Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2712B-05	Model 2712B-05 Managed Token Ring 16-Port Passive STP/UTP Workgroup Concentrator with Speed Detect, STP RI/RO and Basic IP/IPX Agent Firmware and Local Load Capability. Includes License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2712B-F-04	Model 2712B-F-04 Managed Token Ring 16-Port Passive STP/UTP Workgroup Concentrator with Speed Detect, Fiber RI/RO and Advanced IP Agent Firmware and Local Load Capability. Includes License for Advanced IP Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2712-F-04	Model 2712-F Option 04 Managed Token Ring 16-port Passive STP/UTP Workgroup Concentrator with Fiber RI/RO and Advanced IP Agent Firmware with Local Load Capability. Includes License for Advanced IP Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2715-04	Model 2715 Option 04 Managed Token Ring 16-port Active Retiming STP/UTP Workgroup Concentrator with STP RI/RO and Advanced IP Agent Firmware with Local Load Capability. Includes License for Advanced IP Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2715-05	Model 2715 Option 05 Managed Token Ring 16-port Active Retiming STP/UTP Workgroup Concentrator with STP RI/RO and Basic IP/IPX Agent Firmware with Local Load Capability. Includes License for Basic IP/IPX Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2715B-04	Model 2715B-04 Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect, STP RI/RO and Advanced IP Agent Firmware and Local Load Capability. Includes License for Advanced IP Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2715B-05	Model 2715B-05 Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect, STP RI/RO and Basic IP/IPX Agent Firmware and Local Load Capability. Includes License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2715B-F-04	Model 2715B-F-04 Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect, Fiber RI/RO and Advanced IP Firmware and Local Load Capability. Includes License for Advanced IP Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2715-F-04	Model 2715-F Option 04 Managed Token Ring 16-port Active Retiming STP/UTP Workgroup Concentrator with Fiber RI/RO and Advanced IP Agent Firmware with Local Load Capability. Includes License for Advanced IP Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2715SA-08	Model 2715SA-08 Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect and STP RI/RO. Includes License for Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2715SA-F-08	Model 2715SA-F-08 Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect and Fiber Optic RI/RO. Includes License for Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2800A	LattisLink Model 2800A 10BASE-T Workgroup Concentrator.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
28015-EVE	Evaluation kit includes LattisSwitch Model 28015, 1 Intel Pre-production EISA 10/100Mbps Ethernet adapter with Netware drivers, and a Model 515 Transceiver.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
28015-EVP	Evaluation kit includes LattisSwitch Model 28015, 1 Intel Pre-production PCI 10/100Mbps Ethernet adapter with Netware drivers, and a Model 515 Transceiver.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
28104R	BayStack 28104/ADV 100Mbps Fiber Optics Fast Ethernet Switch with redundant power supply connector and advanced software features.	FAIL	2.0.1	N/A	N/A	Upgrade to v2.1.1.1, available as of April 1, 1998, to be Year 2000 compliant.
28115-EVE	Evaluation kit includes LattisSwitch Model 28115 and 2 Intel Pre-production EISA 10/100Mbps Ethernet adapters with Netware drivers.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
28115-EVP	Evaluation kit includes LattisSwitch Model 28115 and 2 Intel Pre-production PCI 10/100Mbps Ethernet adapters with Netware drivers.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
28115R	BayStack 28115/ADV 10/100 Mbps UTP Fast Ethernet Switch with redundant power supply connector and advanced software features.	FAIL	2.0.1	N/A	N/A	Upgrade to v2.1.1.1 or subsequent version, available as of April 1, 1998, to be Year 2000 compliant.
2813-04	LattisHub Model 2813-04 Managed 10BASE-T Workgroup Concentrator with AUI Interconnection Port. Includes License for Advanced IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2813-05	LattisHub Model 2813-05 Managed 10BASE-T Workgroup Concentrator with AUI Interconnection Port. Includes License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2813SA	LattisHub Model 2813SA Managed Workgroup Concentrator with AUI interconnection Port. Includes Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2814-04	LattisHub Model 2814-04 Managed 10BASE-T Workgroup Concentrator with 10BASE-FL Interconnection Port. Includes License for Advanced IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2814-05	LattisHub Model 2814-05 Managed 10BASE-T Workgroup Concentrator with 10BASE-FL Interconnection Port. Includes License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2814SA	LattisHub Model 2814SA Managed Workgroup Concentrator with Fiber interconnection Port. Includes Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2912A-04	Model 2912A Option 04 SDDI Workgroup Concentrator with Local Load Capability. Includes License for Advanced Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
2914-04	Model 2914-04 Fiber Optic FDDI Workgroup Concentrator with Local Load Capability. Includes License for Advanced Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
2915-04	Unshielded Twisted Pair (UTP) FDDI Workgroup Concentrator with Local Load Capability. Includes License for Advanced Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
30004	Fast Packet Cache	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
30004-S	Fast Packet Cache Module Spare for use with 3000X or 340XX Base Units Only	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3000N	Model 3000N Premises Concentrator with Multi-Segment Ethernet Backplane and Model 3002 460W Power Supply.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3000NT	Model 3000NT Premises Concentrator with Multi-Segment Ethernet/Token Ring Backplane and Model 3002 460W Power Supply.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3000NTR	Model 3000NTR Premises Concentrator with Multi-Segment Ethernet/Token Ring Redundant Power Backplane, Summing Module and two Model 3002 460W Power Supplies.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3000S	Model 3000S Premises Concentrator with Multi-Segment Ethernet/Token Ring/FDDI Backplane and Model 3002 460W Power Supply.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3000SR	Model 3000SR Premises Concentrator with Multi-Segment Ethernet/Token Ring/FDDI Redundant Power Backplane, Summing Module and two Model 3002 460W Power Supplies.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3009	CN Base Unit - 220V - Single Power Supply (Floppy only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3010	CN Base Unit - 220V - Dual Power Supplies (Floppy only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3020	CN Base Unit - 220V - Single Power Supply (Floppy/Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3021	CN Base Unit - 220V - Dual Power Supplies (Floppy/Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3030-01-HW	Model 3030-01-HW Department Concentrator Chassis with 150W Power Supply and Ethernet Backplane (01). Installation and maintenance documentation included.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3030-04-HW	Model 3030-04-HW Department Concentrator Chassis with 150W Power Supply and Ethernet/Token Ring Backplane (04). Installation and maintenance documentation included.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3040S	Network Control Engine with SunOS and SunNet Manager Proxy Agent Software.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3100R	Redundant Power Supply Summing Module	PASS	N/A	N/A	N/A	
3299-C	Model 3299-C Coax/IBM Cabling System integrated multiplexor module for 8 3270-type devices. Works with the 3174 Workstation Controller Module. Includes connection cable to 3174.					IBM
3299-F	Model 3299-F Multimode Fiber integrated multiplexor module for 32 3270-type devices. Works with the 3174 Workstation Controller Module. Includes connection cable to 3174.					IBM
3299-U	Model 3299-U Unshielded Twisted Pair (UTP) integrated multiplexor module for 32 3270-type devices. Works with the 3174 Workstation Controller Module. Includes connection cable to 3174.					IBM

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
3301	Model 3301 8-port Thin Net Ethernet Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3301-75	Thin Net Ethernet Host Module for RG59 (75?) cabling.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3301-93	Thin Net Ethernet Host Module for RG62 (93?) cabling.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3303	4-Port Ethernet AUI Transceiver Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3304A	Model 3304A 8-port 10BASE-F Fiber Optic Ethernet Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3304-ST	Model 3304-ST FOIRL Fiber Optic Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3307	12-port 10BASE-T Ethernet Host Module with 50-pin Telco D-Connector.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3307HD	Model 3307HD 24-Port 10BASE-T Host Module with two 50 pin Telco D-Connectors and MDI-X Port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3308A	Model 3308A 10BASE-T Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3308B	Model 3308B 12-port 10BASE-T Ethernet Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3313A-03	Model 3313A-03 Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes AUI Port, RS-232 Port, IP/IPX Firmware, and License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3313A-04	Model 3313A-04 Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes AUI Port, RS-232 Port, IP/IPX Firmware, and License for Advanced IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3313S-04	Model 3313S Option 04 Advanced Ethernet Network Management Module with AUI interconnect port. Includes License for Advanced IP/IPX Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3313SA	Model 3313SA Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes AUI interconnection Port and Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3314A-03	Model 3314A-03 Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes 10BASE-FL Port, RS-232 Port, IP/IPX Firmware, and License for Basic IP/IPX Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3314A-04	Model 3314A-04 Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes 10BASE-FL Port, RS-232 Port, IP/IPX Firmware, and License for Advanced IP/IPX Network Mgmt Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3314S-04	Model 3314S Option 04 Advanced Ethernet Network Management Module with FOIRL fiber interconnect port. Includes License for Advanced IP/IPX Network Management Agent.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3314SA	Model 3314SA Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes 10BASE-FL interconnection Port and Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3323S	Ethernet High Speed Local Bridge with AUI Port.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3324S-ST	Ethernet High Speed Local Bridge with FOIRL Fiber Port.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3333	Model 3333 Ethernet Retiming Module with AUI Port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3334-ST	Model 3334-ST Ethernet Retiming Module with ST FOIRL Fiber Port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3356-00	Model 3356-00 Ethernet Remote Bridge Base Unit. Includes Right-to-Use License.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3368	Model 3368 12-port LattisSecure 10BASE-T Ethernet Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3383-02	Model 3383-02 Ethernet Local Router with AUI Port, Network Load, and 4 MB Memory. Includes Right-to-Use License. Requires router software kit or local load EPROM kit orderable separately.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3384-ST-02	Model 3384-ST-02 Ethernet Local Router with FOIRL Port, Network Load, and 4 MB Memory. Includes Right-to-Use License. Requires router software kit or local load EPROM kit orderable separately.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3386-02	Model 3386 Option 02 Ethernet Remote Router with Local Load and 4Mb Memory. Includes Right-to-Use License.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3395A-01	Model 3395A-01 Terminal Server with TCP/IP support. PPP and XPrinter supported with 2Mb Memory Option. Requires Flash EPROM Kit or Terminal Server Software Media Kit.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3395A-02	Model 3395A-02 Terminal Server with TCP/IP and LAT support. PPP and XPrinter supported with 2Mb Memory Option. Requires Flash EPROM Kit or Terminal Server Software Media Kit.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34000	Dual Ethernet Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
34000-S	Dual Ethernet Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34001	Dual Sync Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34001-S	Dual Sync Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34002	Dual Token Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34002-S	Dual Token Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34004	SPEX Net Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
34004-S	SPEX Net Module Spare for use with 3000X or 340XX Base Units only	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34005	ISDN BRI/Dual Sync Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34005-S	ISDN BRI/Dual Sync Net Module Spare (Boxed)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34007	SPEX-Hot Swap Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34007-K3	SPEX Hot Swap Field Stack Starter Kit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
34007-S	SPEX-Hot Swap Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34008-S	Quad BRI Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
34010-S	Single 100BASE-T Net module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3502B	Model 3502B Shielded/Unshielded Twisted Pair (STP/UTP) Token Ring Host Module with Speed Detect.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3504-ST	Model 3504-ST Token Ring Fiber Host Module (supports IEEE 802.5j).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3505B	Model 3505B Shielded/Unshielded Twisted Pair (STP/UTP) Token Ring Host Module with Per-Port Active Retiming and Speed Detect.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3514-ST	Model 3514-ST Token Ring Network Management Module with Fiber Optic Repeater. Includes License for Basic Network Management Agent. (Order SL351X-A for Advanced Agent).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3517SA-08	Model 3517SA-08 Token Ring Network Management Module with Shielded Twisted Pair (STP) and Fiber Optic Repeater. Includes License for Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3522A	Model 3522A Token Ring Local Bridge.	FAIL	v2.3	N/A	N/A	Cannot set year to = 00. Agent v2.4 fixes problem, upgrade available via Customer Service.
3534-ST	Model 3534-ST Token Ring Fiber Optic Repeater Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
354-ST	TR Fiber Optic Extender	PASS	N/A	N/A	N/A	
3800-03	Multi-Media Router Base Unit with one Ethernet Personality Module. Includes bridging/routing software and Router documentation set (727-04). Requires additional module(s) orderable separately.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3800-05	Multi-Media Router Base Unit with one Token Ring Personality Module. Includes bridging/routing software and Router documentation set (727-04). Requires additional module(s) orderable separately.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3800A	Model 3800A Multi-Media Router Base Unit with 16M of memory and version 10.0 software for routing and bridging. Requires personality modules, orderable separately. Does not include software configuration guide.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3805-01	Model 3805-01 Token Ring Personality Module. Provides one Token Ring Port configurable for chassis backplane or external DB-9 interface.**	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3805-02	Model 3805-02 Token Ring Personality Module. Provides one Token Ring port for external DB-9 interface.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3902A	Model 3902A SDDI Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3904-2SM	Fiber Optic Host Module with 2 Single Mode Fiber M-Ports and 2 Multimode Fiber M-Ports.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3910S-04	Model 3910S-04 FDDI Network Management Module with Local Load Capability. Includes License for Advanced Network Management Agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
3910S-SM-04	FDDI Network Management Module with Local Load. A and B Fiber Ports support Single Mode Fiber.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3C503-TP	3Com Etherlink II TP PC/XT/AT 10BASE-T Network Adapter Card.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
3C523-TP	3Com Etherlink/MC TP Microchannel 10BASE-T Network Adapter Card.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40011V081	VME Corp Suite - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40011V081	LN/CN Additional Protocols - Corp Suite - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
40011V090	LN/CN Version 9.0 Corp Suite - Additional Protocols - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40012V081	LN/CN System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40012V090	LN/CN Version 9.0 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40022V081	AFN Version 8.1 - Corporate Suite - Flash	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40022V090	AFN Version 9.0 Corp Suite - Flash	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40022V100	AFN Version 10.0 Corporate Suite - Flash	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
40022V110	AFN Version 11.0 Corporate Suite - Flash	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
40022V110	AFN Version 11.3 Corporate Suite - Flash	PASS	11.3	N/A	N/A	
40022V120	AFN Version 12.0 Corporate Suite - Flash	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/1998, to be Year2000 compliant.
40031V081	BN Version 8.1 Corp Suite Additional Protocols - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40032V081	BN Version 8.1 System Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40044V081	ASN Version 8.1 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40048V081	BN Version 8.1 Corp Suite Additional Protocols - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40052V081	VME Corp Suite - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40052V081	LN/CN Additional Protocols - Corp Suite - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40052V090	LN/CN Version 9.0 Corp Suite - Additional Protocols - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40052V100	LN/CN Version 10.0 Additional Protocols - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40053V081	ASN Version 8.1 Corp Suite Additional Protocol - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40058V081	ASN Version 8.1 Corp Suite Additional Protocol - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40059V081	AN/ANH Version 8.1 Corporate Suite Additional Protocol - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40062V081	ALN/FN Version 8.1 - Corporate Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40062V081	FN Corporate Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
40062V090	ALN/FN Version 9.0 Corp Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41010V081	LN/CN WAN Suite LN/CN System Suite plus ATM DXI, Frame Relay, LapB, X.25	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41010V090	LN/CN Version 9.0 WAN Suite LN/CN System Suite plus ATM DXI, Frame Relay, LapB, X.25*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41016V081	AN/ANH Version 8.1 Corporate Suite Additional Protocol - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41018V081	LN/CN LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41018V090	LN/CN Version 9.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41018V100	LN/CN Version 10.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41019V081	BN Version 8.1 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41020V081	BN Version 8.1 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41021V081	BN Version 8.1 Corporate Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41024V081	Corporate Suite (4M Flash) includes all Version 8.1 Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
41024V081	Corporate Suite (4M Flash) includes all Version 8.1 Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42020V081	LN/CN Corp Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42020V090	LN/CN Version 9.0 Corp Suite*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
42020V100	LN/CN Version 10.0 Corp Suite	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
42020V110	LN/CN Version 11.0 Corp Suite	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
42020V110	FN/ALN/LN/CN Version 11.3 Corporate Suite - Flash	PASS	11.3	N/A	N/A	
42020V120	FN/ALN/LN/CN Version 12.0 Corporate Suite - Flash	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/1998, to be Year2000 compliant.
42024V081	ASN Version 8.1 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42025V081	ASN Version 8.1 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SMDS	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42026V081	ASN Version 8.1 Corp Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42032V081	IP Access Suite (2M Flash) includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42032V081	IP Access Suite (2M Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42033V081	Remote Office Suite (2M Flash) includes IP Access plus DLSw for Ethernet and	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42033V081	Remote Office Suite (2M Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42034V081	IP Access Suite (4M Flash) includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42034V081	IP Access Suite (4M Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42035V081	Remote Office Suite (4M Flash) includes IP Access plus DLSw for Ethernet and	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
42035V081	Remote Office Suite (4M Flash)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4286-08	Single Port Multichannel E1 (MC-E1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4286-16	Single Port Multichannel E1 (MC-E1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4287-08	Dual Port Multichannel E1 (MC-E1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4287-16	Dual Port Multichannel E1 (MC-E1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4290	V.35 Adapter Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4291-16	Single Port Multichannel T1 (MC-T1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4291-8	Single Port Multichannel T1 (MC-T1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4292-16	Dual Port Multichannel T1 (MC-T1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4292-8	Dual Port Multichannel T1 (MC-T1) ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4295-16	Single Port High Speed Serial Interface (HSSI) ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4295-8	Single Port High Speed Serial Interface (HSSI) ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4380-16	Quad Port Synchronous ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4380-8	Quad Port Synchronous ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4415-16	Ethernet/Single Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4415-8	Ethernet/Single Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4425-16	Ethernet/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4425-8	Ethernet/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4435-16	Dual Ethernet/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4435-8	Dual Ethernet/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4590	Dual Ethernet/DSDE High Speed Filters Expansion Option	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4605-16	Dual Port Ethernet ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
4605-8	Dual Port Ethernet ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4606-16	Dual Port Ethernet ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4606-8	Dual Port Ethernet ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4630-16	Dual Ethernet/Dual Port Sync ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4630-8	Dual Ethernet/Dual Port Sync ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4635-16	Quad Port Ethernet ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4635-8	Quad Port Ethernet ILI - High Perf/Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4655-16	Quad Port Ethernet ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4655-8	Quad Port Ethernet ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4806-08	Quad Port Token Ring ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4806-16	Quad Port Token Ring ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4810-16	Dual Port Token Ring ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4810-8	Dual Port Token Ring ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4820-16	Token Ring/Single Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4820-8	Token Ring/Single Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4840-16	Token Ring/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4840-8	Token Ring/Dual Port Sync ILI - High Perf	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4930-16	Multimode FDDI ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4930-8	Multimode FDDI ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4935-16	Multimode FDDI ILI - Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4935-8	Multimode FDDI ILI - Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4940-16	Single Mode FDDI ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4940-8	Single Mode FDDI ILI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4942-16	Hybrid Single Mode/Multimode FDDI ILI (Single Mode on PHY A/Multimode PHY B)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4942-8	Hybrid Single Mode/Multimode FDDI ILI (Single Mode on PHY A/Multimode PHY B)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4943-16	Hybrid Multimode/Single Mode FDDI ILI (Single Mode on PHY B/Multimode PHY A)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4943-8	Hybrid Multimode/Single Mode FDDI ILI (Single Mode on PHY B/Multimode PHY A)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4945-16	Single Mode FDDI ILI - Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4945-8	Single Mode FDDI ILI - Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4947-16	Hybrid Single Mode/Multimode FDDI ILI - Filters (Single Mode on PHY A/Multimode PHY B)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4947-8	Hybrid Single Mode/Multimode FDDI ILI - Filters (Single Mode on PHY A/Multimode PHY B)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4948-16	Hybrid Multimode/Single Mode FDDI ILI - Filters (Single Mode on PHY B/Multimode PHY A)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
4948-8	Hybrid Multimode/Single Mode FDDI ILI - Filters (Single Mode on PHY B/Multimode PHY A)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
500*/NR75E/600*	Marathon/NetRunner/STADIA Rel. 1.0 thru 4.*	PASS	1.0-4.*	N/A	N/A	Upgrade to Rel. 5.3 available at cost of software, but not required.
500*/NR75E/600*	Marathon/NetRunner/STADIA Rel. 5.*	PASS	5.*	N/A	N/A	Upgrade to Rel. 5.1F or 5.2B available at cost of service, but not required.
500*/NR75E/600*	Marathon/NetRunner/STADIA Rel. 5.1F, 5.2B or 5.3	PASS	5.1F, 5.2B, 5.3	N/A	N/A	Upgrade available
5000	System Controller Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50000V081	AFN Flash Card Spare w/ Corp Suite (8.1)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50000V081	AFN Flash Card Spare w/ Corp Suite (8.1)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
50007	Model 50007 AN 1M to 2M Flash SIMM Spare	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50007	1M to 2M Flash SIMM Spare/Upgrade	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50009	Flash/Floppy FN Base Unit 110V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5000F	Model 5000F Ethernet/Token Ring/FDDI Chassis (14 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5000N	Model 5000N Ethernet Chassis (14 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5000NT	Model 5000NT Ethernet/Token Ring Chassis (14 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
50010	Flash/Floppy FN Base Unit 220V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50011V081	FN/ALN/LN/CN Flash Memory Card Spare - 4MB (8.1)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50011V081	FN/ALN/LN/CN Flash Memory Card Spare - 4MB (8.1)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5002	System Controller ROM Upgrade	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50021	Quad Port Token Ring Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
50023	ASN ISDN BRI Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
50029V081	ASN Version 8.1 Flash Card Spare w/ System Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50035	AFN Diag/BOOT PROM Upgrade Kit (From V7.x to V8.1x)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50035	AFN Diag/BOOT PROM Upgrade Kit (From V7.x to V8.1x)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
50038	Dual 100BASE-T Link Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5004	Flash/Floppy LN Base Unit - 110V/220V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5005	Flash/Floppy CN Base Unit - 220V - Single Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5005F	Model 5005F Ethernet/Token Ring/FDDI chassis (8 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5005N	Model 5005N Ethernet Chassis (8 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5005NT	Model 5005NT Ethernet/Token Ring Chassis (8 slots).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5006	Flash/Floppy CN Base Unit - 220V - Dual Power Supplies	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5008	Octal Port Synchronous Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5010	System I/O Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5014	1/4 Inch Floppy Disk Drive	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5016	3-1/2 Inch Floppy Disk Drive	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5019	5-1/4 Inch to 3-1/2 Inch Floppy Drive Upgrade Kit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5020	FN Base Unit - 110V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5022	FN Base Unit - 220V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5024	FN Power Supply - 110V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5025	FN Power Supply - 220V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
502A	Shielded Twisted Pair (STP) Transceiver.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5031	New LN Chassis with 620 Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5031	LN Chassis with 620 watt Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5033	LN Base Unit - 110V/220V (620 watt)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5048	New CN Chassis with 1500W Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5048	CN Chassis with Single Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5049	CN Base Unit - 220V - Single Power Supply	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
504A	10BASE-FL Transceiver.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
505	Unshielded Twisted Pair (UTP) Transceiver.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5050	CN Base Unit - 220V - Dual Power Supplies	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5051	CN Power Supply - 220V	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5051L	Model 5051L AC Power Supply (Minimum one supply required per 5005 chassis).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5052	CN Redundant Power Supply Kit - Field Installable	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5053	New CN Chassis with Dual1500W Power Supplies	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5053	CN Chassis with Dual Power Supplies	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
508B	Model 508B 10BASE-T Transceiver.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
51001	ATM Link Module - SONET/SDH STS-3c MMF Spare	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
51002	ATM Link Module - SONET/SDH STS-3c SMF Spare	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5121	8M ACE 030	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5121-RB	8M ACE 030 Migration Program	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5122	4M to 8M Field Upgrade Kit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5124	16M ACE 030	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
518	10BASE-T Transceiver with AAUI Port for Apple Ethernet.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5200	Dual Port T1 Framer/Multiplexer Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5201	Dual Port T1 Framer/Multiplexer Link Module - DACS 56K	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5250	Dual Port E1 Framer/Multiplexer Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5280	Quad Port Synchronous Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5295	Single Port High Speed Serial Interface (HSSI) Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5304P	Model 5304P 10-Port 10BASE-F Per-Port Configuration Switching Ethernet Host Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5307P	Model 5307P 24-Port 10BASE-T Per-Port Configuration Switching Ethernet Host Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5308A	Model 5308A 24-Port 10BASE-T Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5308-AF	Model 5308-AF 16-Port 10BASE-T Ethernet Host Module with AUI and 10BASE-F Fiber Interconnect Ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5308P	Model 5308P 24-Port 10BASE-T Per-Port Configuration Switching Ethernet Host Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5310-06	Model 5310 Option 06 Ethernet Network Management Module with on-board Data Collection Engine (DCE) and sockets for two additional 5311 DCEs.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5310A	Model 5310A Ethernet Network Management Module with pre-installed Management Communications Engine (MCE) and sockets for two additional Model 5311A DCEs.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5310SA	Model 5310SA Ethernet Network Management Module with pre-installed Data Collection Engine (DCE) and sockets for two additional Model 5311A DCEs.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5311A	Model 5311A Ethernet Data Collection Engine (DCE) for Model 5310 Ethernet Network Management Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5378-F	Model 5378-F Quad Cluster Ethernet Host Module with 4 10BASE-F Fiber Ports and 16 10BASE-T Ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5390-FE	Model 5390-FE Communications Server base unit with 2Mb Flash memory. TCP/IP dial up routing and terminal server software version 9.0. 24 Asynchronous, 115.2 Kbps, RS-232 Ports. PPP and SLIP link layer protocol support. Includes Tech. Pubs on CD-ROM.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5405	Dual Port Ethernet Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5410	Ethernet/Single Port Sync Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5420	Ethernet/Dual Port Sync Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5430	Dual Ethernet/Dual Port Sync Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5450	Quad Port Ethernet Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
5505	Dual Ethernet - High Speed Filters Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5505P	Model 5505P 20-Port Active Retiming STP/UTP Token Ring Host Module with Per-Port Configuration Switching.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5510-06	Model 5510-06 Token Ring Network Management Module with on-board Data Collection Engine (DCE) and socket for one additional 5511 DCE.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5530	Dual Ethernet/Dual Sync - High Speed Filters Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5531	Dual Ethernet/Dual Sync - Std.Filters Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5532	Dual Ethernet/Dual Sync - Max. Filters Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5575-C	Model 5575-C Intelligent Dual Repeater Cluster Token Ring Host Module with 2 STP/UTP RI/RO trunks and 6 Active Retiming STP/UTP Ports plus Monitor Port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5575-F	Model 5575-F Intelligent Dual Repeater Cluster Token Ring Host Module with 2 Fiber RI/RO trunks and 6 Active Retiming STP/UTP Ports plus Monitor Port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5710	Dual Port Token Ring Link Module**	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5720	Token Ring & Single Port Sync Link Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5740	Token Ring & Dual Port Sync Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5904-2SM	Model 5904-2SM FDDI Fiber Host Module with 4 Multimode Fiber and 2 Single Mode Fiber Ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5910S	Model 5910S FDDI Network Management Module with A/B Multimode Fiber Ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5910S-SM	Model 5910S-SM FDDI Network Management Module with A/B Single Mode Fiber Ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5920	Optical Bypass Switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5930	Multimode FDDI Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5940	Single Mode FDDI Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5942	Hybrid Single Mode/Multimode FDDI Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5943	Hybrid Multimode/Single Mode FDDI Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5944	Single Port Multichannel T1 (MC-T1) Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5945	Dual Port Multichannel T1 (MC-T1) Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5946	Multimode FDDI - High Speed Filters (HSF) Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5947	Single Mode FDDI - High Speed Filters (HSF) Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5948	Hybrid Single Mode/Multimode FDDI - HSF Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5950	Quad Ethernet - High Speed Filters Link Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5DN002	Mode 5DN002 Distributed 5000 Multi-segment configuration switch hub with slots for two Distributed 5000 Ethernet host modules. Includes cascade cable for expansion within a Distributed 5000 stack.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5DN003	Model 5DN003 Distributed 5000 Multi-segment configuration switch hub with slots for three Distributed 5000 Ethernet host modules and one NMM. Includes cascade cable for expansion within a Distributed 5000 stack.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5DN304P	Model 5DN304P Distributed 5000 3 port 10BASE-FL Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5DN307P	Model 5DN307P Distributed 5000 12 port 10BASE-T Telco Host Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5DN308P	Model 5DN308P Distributed 5000 12 port 10BASE-T Host Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
5DN310	Distributed 5000 Network Management Module with sockets for three Data Collection Modules (DCMs)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
5DN378P-F	Model 5DN378P-F Distributed 5000 Mixed Media Host Module with 10BASE-FL	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
60000	System Suite V579 Includes 802.1 Transparent/Source Route Bridge, TCP/IP SNMP Agent	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
60001	LAN Suite V5.79 System Suite plus DECnet, XNS, IPX and AppleTalk	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
60002	WAN Suite V5.79 System Suite plus X.25, Frame Relay, SMDS, Security	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
60003	Corporate Suite V5.79 Includes all Version 5.79 Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
620	Model 620 Optivity Version 1.0 for NMS. Includes Novell NetWare Management System Platform. Requires DOS/Windows 3.1 Station and NetWare 3.11 Server.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
620-1	Optivity Campus 6.1 for Novell ManageWise (Requires Novell ManageWise v2.1) Requires DOS/Windows 3.1 Station, Windows 95 and NetWare Server v3.11 or later.	FAIL	6.1	N/A	N/A	Upgrade to Campus 7.0.
620-1	Optivity Campus 6.1 for HP OpenView Windows (Includes HP OpenView Windows 7.2) Requires Windows 95, DOS/Windows 3.1 Station, or Windows NT Workstation 4.0.	FAIL	6.1	N/A	N/A	Upgrade to Campus 7.0.
620-1	Optivity Campus 6.2 for HP OpenView Windows (Includes HP OpenView Windows 7.2) Requires Windows 95, DOS/Windows 3.1 Station, or Windows NT Workstation 4.0.	FAIL	6.2	N/A	N/A	Upgrade to Campus 7.0.
620-2	Optivity 5.3 for NMS (Includes Novell NMS v2.0)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-1	Optivity LAN 7.1 for HP OpenView Network Node Manager. Requires HP OV Network Node Manager 3.3, 4.0, or 4.1	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
625-1	Optivity LAN 7.2 for HP OpenView Network Node Manager. Requires HP OV Network Node Manager 3.3, 4.0, or 4.1	FAIL	7.2	N/A	N/A	Upgrade to NMS 8.1.
625-2	Model 625 Option 2 Optivity 4.1 for HP OpenView Network Node Manager with HP OpenView Network Node Manager 3.3 for SunOS.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-3	Model 625 Option 3 Optivity 4.1 for HP OpenView Network Node Manager with HP OpenView Network Node Manager 3.3 for HP-UX.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-4	HP OpenView Network Node Manager 4.1 for SunOS, Solaris, or HP-UX. (Must be purchased in conjunction with Optivity)					Hewlett-Packard Product
625-5	Optivity Plus 5.1 for HP OpenView Network Node Manager. Includes Optivity 5.1 for HP OpenView NNM, LattisWare 5.1 for Unix, and HP OpenView NNM 3.3 for HP-UX, SunOS.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-6	Optivity Enterprise 7.1 for HP OpenView NNM. Includes Optivity LAN 7.1, Optivity Internetwork 7.1, Optivity Analysis 7.1, and Optivity Planning 7.0. Requires HP OpenView NNM 4.0 or 3.3 for HP-UX 9.05 or 10.01, SunOS, or Solaris 2.4.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
625-6	Optivity Enterprise 7.2 for HP OpenView NNM. Includes Optivity LAN 7.2, Optivity Internetwork 7.1, Optivity Analysis 7.2, and Optivity Planning 7.0. Requires HP OpenView NNM 4.0 or 3.3 for HP-UX 9.05 or 10.01, SunOS, or Solaris 2.4.	FAIL	7.2	N/A	N/A	Upgrade to NMS 8.1.
625-6	Optivity Enterprise 6.5 for HP OpenView Network Node Manager.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-7	HP OpenView Network Node Manager 3.3 for HP-UX	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
625-8	HP OpenView Network Node Manager 3.3 for SunOS and Solaris	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
626-1	Optivity LAN 7.1 for IBM NetView for AIX. Requires IBM NV6000 v3.1 or v4.1 for AIX v3.25 or NV6000 v4.1 for AIX v4.1.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
626-1	Optivity LAN 7.2 for IBM NetView for AIX. Requires IBM NV6000 v3.1 or v4.1 for AIX v3.25 or NV6000 v4.1 for AIX v4.1.	FAIL	7.2	N/A	N/A	Upgrade to NMS 8.1.
626-2	Model 626 Option 2 Optivity 4.1 for IBM NetView/6000 with IBM NetView/6000 2.1	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
626-4	IBM NetView/6000 for AIX 4.1. (Must be purchased in conjunction with Optivity)					IBM Product
626-5	Optivity Plus 5.1 for IBM NetView/6000. Includes Optivity 5.1 for IBM NetView/6000, LattisWare 5.1 for Unix, and IBM NetView/6000 3.1.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
626-6	Optivity Enterprise 7.2 for IBM NetView for AIX. Includes Optivity LAN 7.2, Optivity Internetwork 7.1, Optivity Analysis 7.2, and Optivity Planning 7.0. Requires IBM NV6000 3.1 or 4.1 for AIX 3.25 or NV6000 4.1 for AIX 4.1.	FAIL	7.2	N/A	N/A	Upgrade to NMS 8.1.
626-6	Optivity Enterprise 6.5 for IBM NetView for AIX.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
627-1	LattisWare 5.1 for Unix. Includes RouterMan 3.0, PathMan 2.1, TrendMan 2.1 and DesignMan 2.0 for SunNet Manager, HP OpenView NNM and IBM NetView/6000.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
628-1	Optivity Internetwork 6.1.1 for SunNet Manager, HP OpenView Network Node Manager and NetView for AIX., includes integrated Xylogics Annex Manager application. If Annex Manager manuals (documentation) is required, please order #CM0015008.	FAIL	6.1.1	N/A	N/A	Upgrade to NMS 8.1.
628-1	Optivity Internetwork 7.1 for SunNet Manager, HP OpenView Network Node Manager and NetView for AIX., includes integrated Xylogics Annex Manager application. If Annex Manager manuals (documentation) is required, please order #CM0015008.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
629-1	Optivity Design and Analysis 6.0 for SunNet Manager, HP OpenView NNM, and NetView for AIX.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
629-2	Optivity Analysis 7.1 stand-alone or for SunNet Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity LAN 7.1 and Optivity Internetwork 7.1	FAIL	7.1	N/A	N/A	Upgrade to 8.0.
629-2	Optivity Analysis 7.2 stand-alone or for SunNet Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity LAN 7.1 and Optivity Internetwork 7.1	FAIL	7.2	N/A	N/A	Upgrade to 8.0.
629-2	Optivity Analysis 8.0 stand-alone or for SunNet Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity NMS 8.0.	PASS	8.x	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
629-2	Analysis 8.1 stand-alone or for Solstice Domain Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity NMS 8.1 and Optivity Planning 8.1.	PASS	8.1	N/A	N/A	
629-3	Optivity Planning 7.0 stand-alone or for SunNet Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity LAN 7.0 and Optivity Internetwork 6.1	FAIL	7	N/A	N/A	Upgrade to 8.0
629-3	Optivity Planning 8.0 stand-alone or for SunNet Manager, HP OpenView Network Node Manager, and NetView for AIX. Operates with Optivity NMS 8.0.	PASS	8.x	N/A	N/A	
629-3	Optivity Planning 8.0.1 Plus Web Reporting Capabilities Stand-Alone or for Solstice Domain Manager, HP OV NNM, and NetView for AIX. Operates with Optivity Analysis and Optivity NMS 8.0.	PASS	8.0.1	N/A	N/A	
636-03	Optivity Campus 6.1 for HP OpenView Windows (Includes HP OpenView Windows 7.2) Requires Windows 95, DOS/Windows 3.1 Station, or Windows NT Workstation 4.0.	FAIL	6.1	N/A	N/A	Upgrade to Campus 7.0
636-03	Optivity Campus 7.0 for HP OpenView Windows (Includes HP OpenView Windows 7.2) Requires Windows '95 or NT Workstation 4.0.	PASS	7.0	N/A	N/A	
637-1	Optivity LAN 7.1 for SunNet Manager. Requires SunNet Manager 2.2.3 or 2.3 or Solstice Domain Manager 2.3 for SunOS or Solaris 2.4 or 2.5.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
637-1	Optivity LAN 7.2 for SunNet Manager. Requires SunNet Manager 2.2.3 or 2.3 or Solstice Domain Manager 2.3 for SunOS or Solaris 2.4 or 2.5.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1.
637-2	Model 637 Option 2 Optivity 4.1 for SunNet Manager with SunNet Manager 2.0 for SunOS.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
637-4	SunNet Manager 2.2 for Solaris 1.x/SunOS 4.1.x. (Must be purchased in conjunction with Optivity)					Sun
637-4	SunNet Manager 2.2 for Solaris 1.x/SunOS 4.1.x	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
637-5	Optivity Plus 5.1 for SunNet Manager. Includes Optivity 5.1 for SunNet Manager, LattisWare 5.1 for Unix, and SunNet Manager 2.2 for SunOS.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
637-6	Optivity Enterprise 7.1 for SunNet Manager. Includes Optivity LAN 7.1, Optivity Internetwork 7.1, Optivity Analysis 7.1, and Optivity Planning 7.0. Requires SunNet Manager v2.2.3 or v2.2.2 for SunOS or Solaris 2.5 or 2.4.	FAIL	7.1	N/A	N/A	Upgrade to NMS 8.1. Upgrade to Analysis 8.0 and Planning 8.0.
637-6	Optivity Enterprise 7.2 for SunNet Manager. Includes Optivity LAN 7.2, Optivity Internetwork 7.1, Optivity Analysis 7.2, and Optivity Planning 7.0. Requires SunNet Manager v2.2.3 or v2.2.2 for SunOS or Solaris 2.5 or 2.4.	FAIL	7.2	N/A	N/A	Upgrade to NMS 8.1. Upgrade to Analysis 8.0 and Planning 8.0.
637-6	Optivity Enterprise 6.5 for SunNet Manager.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
637-8	SunNet Manager 2.2 for Solaris 2.x.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
651-01	Model 651-01 NETMAP Version 3.0 for IBM OS/2. Requires IBM NetView/PC and TCP/IP Software (See Product Data Sheet for Version Compatibility).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
660	Model 660 LattisViews Version 1.0 - OSF/Motif-based Advanced Ethernet and Token Ring Network Management Software for IBM, DEC, and HP Enterprise Management Systems.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
674-01	Release 1.0 Vision DeskTop for Sun (SunNet Manager required), Single User License.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
675	Release 1.1 AssetManager for Sun, HP, and IBM.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
675-01	Model 675-01 Release 1.0 AssetManager for Sun (SunNet Manager and Optivity 4.0 required). Includes one administrator license and two analyst licenses.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
6910AF	Corporate Suite V5.81 Includes all Version 5.81 Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
692-1	Model 692-1 Ethernet BridgeMan Version 1.0 for DOS. Requires Model 636-03 or stand-alone with Windows 3.x and Model 691.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
693-2	Model 693-2 Ethernet BridgeMan Release 2.0 for UNIX (SunNet Manager). Model 637 Optivity for UNIX required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
702-01	Model 3356 Remote Bridge SNMP Firmware Version 2.0 (Note: All 3356-00 units shipped after 10/15/92 include SNMP Firmware).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
7140	SPEX Terminators (qty 2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
725-04	Version 9.1.x Local Load EPROM Option Kit for the Ethernet Local Router.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
725-05	Version 9.1.x Local/Remote Ethernet Router Software Kit for 338x Routers. Includes Sparc and MS-DOS formats on 3.5" Media.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
726-04	Version 9.1.x Local Load EPROM Kit for the Remote Ethernet Router with X.25/Frame Relay Option.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
726-05	Version 9.1.x Remote Ethernet Router Software Kit with X.25/Frame Relay Option for 3386 Routers. Includes Sparc and MS-DOS formats on 3.5" Media.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
727-04	Router Documentation Set for Version 9.x software for (3800 and 3800A).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
727-06	Model 727-06 Router Software Configuration Guide for Version 10.0 software (equivalent to V10.0 Router Configuration and Reference Manuals from Cisco Systems).	PASS	10.x	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
730-02	Router DCE RS449 Adapter Cable for Model 3806 - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
730-03	Router DCE RS232 Adapter Cable for Model 3806 - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
730-04	Router DCE X.21 Adapter Cable for Model 3806 - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
730-05	Router DCE X.21 Adapter Cable for Model 3806 (NET.1 Compatible) - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
730-06	Router DTE X.21 Adapter Cable for Model 3806 (NET.1 Compatible) - 10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
730-07	Router DTE RS232 Adapter Cable for Model 3806 (NET.2 Compatible) -10 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74000-08	Quad Port Synchronous FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74000-16	Quad Port Synchronous FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74000-32	Quad Port Synchronous FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74001-08	Single Port High Speed Serial Interface (HSSI) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74001-16	Single Port High Speed Serial Interface (HSSI) FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74001-32	Single Port High Speed Serial Interface (HSSI) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74002-08	Dual Port Token Ring FRE2-040 8MB ILI**	PASS	11.03	N/A	N/A	
74002-16	Dual Port Token Ring FRE2-040 16MB ILI **	PASS	11.03	N/A	N/A	
74002-32	Dual Port Token Ring FRE2-040 32MB ILI **	PASS	11.03	N/A	N/A	
74003-08	Token Ring and Dual Port Sync FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74003-16	Token Ring and Dual Port Sync FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74003-32	Token Ring and Dual Port Sync FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74004-08	Ethernet/Single Port Sync	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74004-16	Ethernet/Single Port Sync	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74004-32	Ethernet/Single Port Sync	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74005-08	Quad Port Ethernet FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74005-16	Quad Port Ethernet FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74005-32	Quad Port Ethernet FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74006-08	Quad Port Ethernet - High Speed Filters FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74006-16	Quad Port Ethernet - High Speed Filters FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74006-32	Quad Port Ethernet - High Speed Filters FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74007-08	Dual Port Ethernet - High Speed Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74007-16	Dual Port Ethernet - High Speed Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74007-32	Dual Port Ethernet - High Speed Filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74008-08	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74008-16	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74008-32	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74009-08	Dual Ethernet/Dual Sync (ESAF) - Std filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74009-16	Dual Ethernet/Dual Sync (ESAF) - Std filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74009-32	Dual Ethernet/Dual Sync (ESAF) - Std filters	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74010-08	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74010-16	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74010-32	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74011-08	Multimode FDDI FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74011-16	Multimode FDDI FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74011-32	Multimode FDDI FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74012-08	Multimode FDDI - High Speed Filters FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74012-16	Multimode FDDI - High Speed Filters FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74012-32	Multimode FDDI - High Speed Filters FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74013-08	Singlemode FDDI FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74013-16	Singlemode FDDI FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74013-32	Singlemode FDDI FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74014-08	Hybrid Single Mode/Multimode FDDI (Single Mode on PHYA/Multimode PHY B) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74014-16	Hybrid Single Mode/Multimode FDDI (Single Mode on PHYA/Multimode PHY B) FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74014-32	Hybrid Single Mode/Multimode FDDI (Single Mode on PHYA/Multimode PHY B) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74015-08	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode PHYB) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74015-16	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode PHYB) FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74015-32	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode PHYB) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74016-08	Single Mode FDDI ILI - High Speed Filters FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74016-16	Single Mode FDDI ILI - High Speed Filters FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74016-32	Single Mode FDDI ILI - High Speed Filters FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
74017-08	Hybrid Single Mode/Multimode FDDI ILI-High Speed Filters (Single Mode on PHYA/Multimode on PHYB) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74017-16	Hybrid Single Mode/Multimode FDDI ILI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74017-32	Hybrid Single Mode/Multimode FDDI ILI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74018-08	Hybrid Multimode/Single Mode FDDI-High Speed Filters (Single Mode on PHYA/Multimode on PHYB) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74018-16	Hybrid Multimode/Single Mode FDDI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74018-32	Hybrid Multimode/Single Mode FDDI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74019-08	Single Port Multichannel T1 (MC-T1) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74019-32	Single Port Multichannel T1 (MC-T1) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74020-08	Dual Port Multichannel T1 (MC-T1) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74020-32	Dual Port Multichannel T1 (MC-T1) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74021-08	Quad Port Token Ring FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74021-16	Quad Port Token Ring FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74021-32	Quad Port Token Ring FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74023-08	ATM ILI - SONET/SDH STS-3c MMF (8MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74023-16	ATM ILI - SONET/SDH STS-3c MMF (16MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74023-32	ATM ILI - SONET/SDH STS-3c MMF (32MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74024-08	ATM ILI - SONET/SDH STS-3c SMF (8MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74024-16	ATM ILI - SONET/SDH STS-3c SMF (16MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74024-32	ATM ILI - SONET/SDH STS-3c SMF (32MB FRE2)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74025-08	Single Port Multichannel E1 (MC-E1) ILI - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74025-32	Single Port Multichannel E1 (MC-E1) ILI - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74026-08	Dual Port Multichannel E1(MC-E1) ILI - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74026-32	Dual Port Multichannel E1 (MC-E1) ILI - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74027-16	FRE2-060 Spare 16MB **	PASS	N/A	N/A	N/A	
74027-32	FRE2-060 Spare 32MB **	PASS	N/A	N/A	N/A	
74029-16	ATM ILI-SONET/SDH STS-3c MMF (16M)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74029-32	ATM ILI-SONET/SDH STS-3c MMF (32M)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74030-16	ATM ILI-SONET/SDH STS-3c SMF (16M)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74030-32	ATM ILI-SONET/SDH STS-3c SMF (32M)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74031-32	Single Port Multichannel T1 (MC-T1) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74032-32	Dual Port Multichannel T1 (MC-T1) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74033-32	Single Port MC E1 ILI (32M) - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74034-32	Dual Port MC E1 ILI (32M) - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
74035-16	Single Port High Speed Serial Interface (HSSI) FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74035-32	Single Port High Speed Serial Interface (HSSI) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74036-16	Multimode FDDI FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74036-32	Multimode FDDI FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74037-16	Multimode FDDI - High Speed Filters FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74037-32	Multimode FDDI - High Speed Filters FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74038-16	Singlemode FDDI FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74038-32	Singlemode FDDI FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74039-16	Singlemode FDDI- High Speed Filters FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74039-32	Singlemode FDDI- High Speed Filters FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74040-16	Hybrid Single Mode/Multimode FDDI(Single Mode on PHYA/Multimode on PHYB) FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74040-32	Hybrid Single Mode/Multimode FDDI(Single Mode on PHYA/Multimode on PHYB) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74041-16	Hybrid Single Mode/Multimode FDDI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74041-32	Hybrid Single Mode/Multimode FDDI-High Speed Filters(Single Mode on PHYA/Multimode on PHYB) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74042-16	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode PHYA) FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74042-32	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode PHYA) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
74043-16	Hybrid Multimode/Single Mode FDDI- High Speed Filters(Single Mode on PHYB/Multimode on PHYA) FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
74043-32	Hybrid Multimode/Single Mode FDDI- High Speed Filters(Single Mode on PHYB/Multimode on PHYA) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
74044-08	Dual 100BASE-T FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74044-16	Dual 100BASE-T FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74044-32	Dual 100BASE-T FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
74045-08	Octal Port Synchronous FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
74045-16	Octal Port Synchronous FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
74045-32	Octal Port Synchronous FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
75006V081	BN Version 8.1 Flash Card Spare w/ System Suite (8.1)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
76009V021	Site Manager Version 2.1 PC-DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
76009V021	Site Manager Version 2.1 PC-DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
76014V021	Site Manager Version 2.1 CD-ROM (includes UNIX and PC versions)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
76014V021	Site Manager Version 2.1 CD-ROM (includes UNIX and PC versions)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
770-04	Model 770-04 Version 5.3 Terminal Server Software Kit in VMS TK50 Format. Includes Documentation. (Model 773 Multi Megabyte memory required).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
770-05	Model 770-05 Version 5.3 Terminal Server Software Kit. Includes 3.5" DSHD DOS and 3.5" SS1 Formats. Includes Documentation. (Model 773 Multi Megabyte memory required).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
77007	Dual Port Multichannel E1 (MC-E1) Link Module - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
77009	Single Port Multichannel E1 (MC-E1) Link Module - for 75 ohm or 120 ohm leased line	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
772-01	Version 5.2 Flash EPROM Option Kit for 3395A Terminal Servers with 1Mb Memory (ships standard with 3395A).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
775-01	Model 775-01 Version 5.3 Flash EPROM Option Kit for 3395A Terminal Servers using Model 773 (2Mb SIMM Memory Option). Documentation Set not included.* (Model 773 Multi Megabyte memory required).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
775-152	Supplementary, firmware only, upgrade kit for the 281x Network Management Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
80010	4M to 8M ACE 030 Return to Factory (maintenance contract)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
80011	4M to 8M ACE 030 Return to Factory (no maintenance contract)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
80012	4M to 8M ACE 030 Advance Replacement maintenance contract)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
80013	4M to 8M ACE 030 Advance Replacement (no maintenance contract)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
800-A	Model 800-A 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI Port. (No power cord included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
800-B	Model 800-B 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI Port. Includes European "Schuko" power cord common in Austria, Benelux, Finland, France, Germany, Norway, and Sweden.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
800-C	Model 800-C 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI Port. (Includes power cord commonly used in the United Kingdom and Ireland).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
800-D	Model 800-D 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI Port. (Includes power cord commonly used in Japan).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
800-F	Model 800-F 10Base-T Workgroup Concentrator. Incorporates eight 10Base-T Ports and one AUI port. (Includes power cord commonly used in Australia, New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
8090	Advance Replacement Option - AFN Flash Memory Card Upgrade	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
8090	Advance Replacement Option - AFN Flash Memory Card Upgrade (Flash Card not included)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
810M	Model 810M Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports, one AUI Port, and IP/IPX Network Management Agent. (Includes North American power cord).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
810M-A	Model 810M-A Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports, one AUI Port, and IP/IPX Network Management Agent. (No power cord included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
810M-B	Model 810M-B Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports, one AUI Port, and IP/IPX Network Management Agent. Includes European "Schuko" power cord common in Austria, Benelux, Finland, France, Germany, Norway, and Sweden.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
810M-C	Model 810M-C Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports, one AUI Port, and IP/IPX Network Management Agent. (Includes power cord commonly used in the United Kingdom and Ireland).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
810M-D	Model 810M-D Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports, one AUI Port, and IP/IPX Network Management Agent. (Includes power cord commonly used in Japan).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
810M-F	Model 810M-F Managed 10BASE-T Workgroup Concentrator. Incorporates eight 10BASE-T Ports and one AUI port, and IP/IPX Network Management Agent. (Includes power cord commonly used in Australia, New Zealand and the People's Republic of China).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
850	UTP Cable Continuity Tester.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90000V081	Version 8.1 Router Install Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90001V081	Version 8.1 Router Management Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90002V081	Version 8.1 System Suite Protocol Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90026V081	Version 8.1 LAN Suite Protocol Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90031V081	Version 8.1 WAN Suite Protocol Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90032V081	Version 8.1 Complete Documentation Set	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90033V081	Version 8.1 Upgrade Documents	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
90039V081	Version 8.1 Release Notes	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
901A-8	Shielded Twisted Pair (STP) Concentrator Patch Cable for Ethernet and FDDI - 8 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
902B-16	Shielded Twisted Pair (STP) Wall Outlet Patch Cable for Ethernet - 16 ft. (Male DB-9 connector with thumbscrews to 4-position "IBM style" data connector).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
902B-8	Shielded Twisted Pair (STP) Wall Outlet Patch Cable for Ethernet and FDDI - 8 ft. (Male DB-9 connector with thumbscrews to 4-position "IBM style" data connector).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
906A-8	Shielded Twisted Pair (STP) Distribution Cable - 8 ft. (Male DB-9 connector with lockscrews to female DB-9 connector with lockscrews).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
910-14	Unshielded Twisted Pair (UTP) Patch Cable - 14 ft. (RJ-45 to RJ-45).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
910-7	Unshielded Twisted Pair (UTP) Patch Cable - 7 ft. (RJ-45 to RJ-45).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
922-8	FDDI MIC to MIC Fiber Duplex Patch Cable - 8 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
928A	10BASE-T Transceiver	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
931-6	8 RJ-45 to Male 50-Pin Telco Cable for Model 3395 Terminal Server - 6 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
932-6	8 RJ-45 to Female 50-Pin Telco Cable for Model 3395 Terminal Server - 6 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
961-25	T1 Straight-Thru Cable for Model 3356 Remote Bridge - 25 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
962-25	V.35 Straight-Thru Cable for Model 3356 Remote Bridge - 25 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
963-25	RS449 Straight-Thru Cable for Model 3356 Remote Bridge - 25 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
964-25	RS232 Modem Cable - 25 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-057	Firmware Upgrade Kit for SNMP Agent Version 3.0 for 3323 and 3324-ST.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-071	4Mb Memory Option Kit for Model 3383, 3384-ST, and 3386-01.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-122	High Watt Power Supply Upgrade Kit for Model 3030 Chassis. Includes Ethernet/Token Ring Backplane and High Watt Power Supply and Fan Unit (980-347 and 980-348).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-169	Model 975-169 Basic IP/IPX Boot PROM Upgrade Kit to add IPX management capabilities to existing Model 2715-03 Concentrators.	PASS	N/A	N/A	N/A	
975-170	Firmware and Doc. Upgrade Kit for the 281x-03 Network Management Module.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-192	SONET/SDH Multimode Fiber 155Mb/s ATM SBus Adapter Card.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-206	Model 975-206 5005 Side Mount Flanges.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
975-212	SONET/SDH Unshielded Twisted Pair (UTP)155Mb/s ATM SBus Adapter Card.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
975-248	CMS/MCS Network Service SONET/SDH 155 Mbps Multi Mode Fiber SBus Card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
976-6	16 RJ-11 to 50-Pin RJ-21 Octopus Cable - 6 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
977-6	4-Pack of RJ-45 to RJ-11 UTP Cable - 6 ft.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
980-108	Fan Tray Module for Model 3000 Premises Concentrator (this metal Fan Tray Module fits Model 3000 Concentrators without the plastic trim).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
980-347	Ethernet/Token Ring Backplane for Model 3030-HW Department Concentrator.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
980-458	Model 980-458 5000 Ethernet/Token Ring Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-459	Model 980-459 5000 Supply Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-460	Model 980-460 5000 FDDI Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-544	Model 980-544 5000 Fan Filter.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-545	Model 980-545 5000 Token Ring Configuration Board.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-546	Model 980-546 5000/5005 Clock Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-547	Model 980-547 5000 Fan Unit.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-577	Model 980-577 5000 Status Board.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-615	Model 980-615 5000 Ethernet Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-620	Model 980-620 5005 Fan Filter.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-621	Model 980-621 5005 Fan Unit.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-623	Model 980-623 5005 Ethernet Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-624	Model 980-624 5005 Ethernet/Token Ring Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-625	Model 980-625 5005 Supply Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-647	Model 980-647 19" Rack-mount kit for Model 800 and Model 810M.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-658	Model 980-658 Spare Power Supply for Model 800 and Model 810M.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-702	Model 980-702 Cable Guide hardware accessory for the Model 27XXB Token Ring Workgroup Concentrators.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
980-706	Model 980-706 5005F FDDI Backplane.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
993-073	332xS Ethernet High Speed Local Bridge Documentation.*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
993-100	Model 993-100 3522 Token Ring Local Bridge Documentation.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
993-148	Model 993-148 Documentation set for the 5390 Communication Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AA0000008	Cable Guide for Accelar 1200/1250, 2 pack	PASS	N/A	N/A	N/A	
AA0002001	HRPSU Base Unit	PASS	N/A	N/A	N/A	
AA0004001	ASN 2 Fast Packet Cache - Factory Installed	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AA0004011	AN/12-port ANH DSU/CSU 56/64 Kbps Adapter Module (North America Only)	PASS	N/A	N/A	N/A	
AA0005003	HRPSU Power Module AC 200 W	PASS	N/A	N/A	N/A	
AA0005006	BayStack UPS45 120 Volt, 450VA Uninterruptable Power Supply for Bay Networks by APC™.	PASS	N/A	N/A	N/A	
AA0005007	BayStack UPS45 230 Volt, 450VA Uninterruptable Power Supply for Bay Networks by APC™. Provides an uninterruptable power supply for up to four stackable units.	PASS	N/A	N/A	N/A	
AA0005A05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (No power cord included).	PASS	N/A	N/A	N/A	
AA0005B05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (Includes European Schuko power cord).	PASS	N/A	N/A	N/A	
AA0005C05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (Includes power cord used in UK and Ireland).	PASS	N/A	N/A	N/A	
AA0005D05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (Includes power cord used in Japan).	PASS	N/A	N/A	N/A	
AA0005E05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (Includes power cord used in North America).	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AA0005F05	RPSU Redundant Power Supply Unit for Bay Networks low watt stackable products. Provides redundant power for up to four stackable units. (Includes Australian power cord, also used in New Zealand and the PRC).	PASS	N/A	N/A	N/A	
AA0008001	BaySecure Firewall - 1 Management Software and Enterprise License. Requires Version 11.02 software**	FAIL	11.02	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008001	BaySecure Firewall - 1, 3.0a Management Software and Enterprise License. Requires Version 11.0X, 12.01, 12.10.	PASS	3.0a	N/A	N/A	
AA0008002	BaySecure Firewall - 1 Management Software and Medium License. Requires Version 11.02 software**	FAIL	11.02	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008002	BaySecure Firewall - 1, 3.0a Management Software and Medium License. Requires Version 11.0X, 12.01, 12.10.	PASS	3.0a	N/A	N/A	
AA0008003	BaySecure Firewall - 1 Management Software and Light License. Requires Version 11.02 software**	FAIL	11.02	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008003	BaySecure Firewall - 1, 3.0a Management Software and Light License. Requires Version 11.0X, 12.01, 12.10.	PASS	3.0a	N/A	N/A	
AA0008004	DES - 56 WAN Encryption Option (Router Software 11.01/Site Manager 5.01)*	FAIL	11.01	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008005	DES - 40 WAN Encryption Option (Router Software 11.01/Site Manager 5.01)	FAIL	11.01	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008006	DES - 40 WAN Encryption Option (Router Software 11.02/Site Manager 5.02)	FAIL	11.02	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008007	DES - 56 WAN Encryption Option (Router Software 11.02/Site Manager 5.02)*	FAIL	11.02	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AA0008010	DES - 40 WAN Encryption Option for V12.0	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0008011	DES - 56 WAN Encryption Option for V12.0*	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0008012	BaySecure Firewall - 1 Management Software and Enterprise License. Requires Version 12.0 or higher software**	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0008012	BaySecure Firewall - 1, 3.0b Management Software and Enterprise License. Requires Version 12.02 or 12.20.	PASS	3.0b	N/A	N/A	
AA0008013	BaySecure Firewall - 1 Management Software and Medium License. Requires Version 12.0 or higher software**	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0008013	BaySecure Firewall - 1, 3.0b Management Software and Medium License. Requires Version 12.02 or 12.20.	PASS	3.0b	N/A	N/A	
AA0008014	BaySecure Firewall - 1 Management Software and Light License. Requires Version 12.0 or higher software**	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0008014	BaySecure Firewall - 1, 3.0b Management Software and Light License. Requires Version 12.02 or 12.20.	PASS	3.0b	N/A	N/A	
AA0008016	BaySecure VPN Secure Manager V2.06 Software International	PASS	v2.06	N/A	N/A	VPNET Technologies Inc.
AA0008017	BaySecure VPN Secure Manager V2.06 Software Domestic*	PASS	v2.06	N/A	N/A	VPNET Technologies Inc.
AA0008018	BaySecure VPN Secure Client V2.1 Software International	PASS	v2.1	N/A	N/A	VPNET Technologies Inc.
AA0008019	BaySecure VPN Secure Client V2.1 Software Domestic*	PASS	v2.1	N/A	N/A	VPNET Technologies Inc.
AA0008020	DES - 40 WAN Encryption Option for V12.10	PASS	v12.10	N/A	N/A	
AA0008020	DES - 40 WAN Encryption Option for V12.20	PASS	v12.20	N/A	N/A	
AA0008021	DES - 56 WAN Encryption Option for V12.10	PASS	v12.10	N/A	N/A	
AA0008021	DES - 56 WAN Encryption Option for V12.20	PASS	v12.20	N/A	N/A	
AA0008022	Hi/fn LZS Compression Option-CD-ROM					
AA0008023	BaySecure FireWall-1 Management Software and Enterprise License. Requires 12.10 or higher software	PASS	v12.10	N/A	N/A	
AA0008024	BaySecure FireWall-1 Management Software and Medium License. Requires 12.10 or higher software	PASS	v12.10	N/A	N/A	
AA0008025	BaySecure FireWall-1 Management Software and Light License. Requires 12.10 or higher software	PASS	v12.10	N/A	N/A	
AA0008026	DES - 40 WAN Encryption Option For V12.01	PASS	v12.01	N/A	N/A	
AA0008027	DES - 56 WAN Encryption Option V12.01	PASS	v12.01	N/A	N/A	
AA0008028	DES - 40 WAN Encryption Option for V11.03	PASS	v11.03	N/A	N/A	
AA0008029	DES - 56 WAN Encryption Option for V11.03	PASS	v11.03	N/A	N/A	
AA0008036	DES - 40 WAN Encryption Option for V13.0	PASS	v13.0	N/A	N/A	
AA0008037	DES - 56 WAN Encryption Option for V13.0	PASS	v13.0	N/A	N/A	
AA0008038	Hi/fn LZS Compression Option-CD-ROM For BayRs 13.0 and Site Manager 7.0.	PASS	v13.0	N/A	N/A	
AA0008039	DES - 40 WAN Encryption Option for V13.10	PASS	v13.10	N/A	N/A	
AA0008040	DES - 56 WAN Encryption Option for V13.10	PASS	v13.10	N/A	N/A	
AA0008042	DES - 40 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AA0008042	DES - 40 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008042	DES - 40 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008042	DES - 40 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008042	DES - 40 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008043	DES - 56 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008043	DES - 56 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008043	DES - 56 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008043	DES - 56 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008043	DES - 56 WAN Encryption Option for V12.00-12.04, 12.10, 12.20, 13.01-13.02, 13.10, & 13.20.	PASS	N/A	N/A	N/A	
AA0008044	Hi/In LZS Compression Option (CD-ROM) for V12.10, 12.20, 13.01-13.02, 13.10, 13.20.	PASS	N/A	N/A	N/A	
AA0008044	Hi/In LZS Compression Option (CD-ROM) for V12.10, 12.20, 13.01-13.02, 13.10, 13.20.	PASS	N/A	N/A	N/A	
AA0008044	Hi/In LZS Compression Option (CD-ROM) for V12.10, 12.20, 13.01-13.02, 13.10, 13.20.	PASS	N/A	N/A	N/A	
AA0008044	Hi/In LZS Compression Option (CD-ROM) for V12.10, 12.20, 13.01-13.02, 13.10, 13.20.	PASS	N/A	N/A	N/A	
AA0008044	Hi/In LZS Compression Option (CD-ROM) for V12.10, 12.20, 13.01-13.02, 13.10, 13.20.	PASS	N/A	N/A	N/A	
AA0011004	ASN Fast Packet Cache - Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AA0011004	Dual Port Memory Module, 256KB Fast Packet Cache, For CPU Module- Optic	PASS	N/A	N/A	N/A	
AA0011006	BaySecure Firewall - 1 Management Software License Upgrade/Light to Enterprise	FAIL	v12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0011007	BaySecure Firewall - 1 Management Software License Upgrade/Medium to Enterprise	FAIL	v12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AA0011017	32MB 1297SF Memory Upgrade Kit	PASS	N/A	N/A	N/A	
AA0011018	32M Flash Card Spare - Formatted	PASS	N/A	N/A	N/A	
AA0011018	32M Flash Card Spare - Formatted	PASS	N/A	N/A	N/A	
AA0015006	Version 9.0 Complete Documentation set	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AA0015007	Version 9.0 On-Line Documentation - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AA0015010	Version 9.0 Release Notes with Upgrade Manual	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AA0015013	Version 10.0 Release Notes with Upgrade Manual	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AA0015033	Version 13.20 On-Line Documentation - CD-ROM.	PASS	N/A	N/A	N/A	
AA0015033	Version 13.20 On-Line Documentation - CD-ROM.	PASS	N/A	N/A	N/A	
AA0015033	Version 13.20 On-Line Documentation - CD-ROM.	PASS	N/A	N/A	N/A	
AA0015033	Version 13.20 On-Line Documentation - CD-ROM.	PASS	N/A	N/A	N/A	
AA0018011	CBL ASSY 15-Pin to RS-530.	PASS	N/A	N/A	N/A	
AA0018012	CBL ASSY 44-Pin to RS-530.	PASS	N/A	N/A	N/A	
AA0018016	HRPSU Output Cable (24 -pin)	PASS	N/A	N/A	N/A	
AA1001701	BaySecure VPN 550n (Ethernet) International with European, UK, or NA Power Cord*	PASS	N/A	N/A	N/A	VPNET Technologies Inc.
AA1001E02	BaySecure VPN 550n (Ethernet) Domestic w/ N.A. Power Cord*	PASS	N/A	N/A	N/A	VPNET Technologies Inc.
AA1100A01	Token Ring FO Extender	PASS	N/A	N/A	N/A	
AA2101701	BaySecure VPN 500n (WAN) International with European, UK, or NA Power Cord*	PASS	N/A	N/A	N/A	VPNET Technologies Inc.
AA2101E02	BaySecure VPN 500n (WAN) Domestic w/ N.A. Power Cord*	PASS	N/A	N/A	N/A	VPNET Technologies Inc.
AB1007001	LattisHub Model 2813SA-4M Managed Workgroup Concentrator with AUI interconnection Port. Includes Advanced Analyzer Network Management Agent.	PASS	2.0.0	N/A	N/A	
AB1007002	LattisHub Model 2814SA-4M Managed Workgroup Concentrator with Fiber interconnection Port. Includes Advanced Analyzer Network Management Agent.	PASS	2.0.0	N/A	N/A	
AB1011005	Agent 2.0 Upgrade Kit for System 2000 SA Network Management Modules. Upgrades Models 2813SA and 2814SA.	PASS	2.0.0	N/A	N/A	
AB1107001	Model 2715SA-4M Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect and STP RI/RO. Includes License for Advanced Analyzer Network Management Agent with version 2.0 agent.	PASS	v2.0	N/A	N/A	
AB1107002	Model 2715SA-F-4M Managed Token Ring 16-Port Active Retiming STP/UTP Workgroup Concentrator with Speed Detect and Fibre Optic RI/RO. Includes License for Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AB1111001	Boot Prom Upgrade Kit for 2715SA Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AB1111002	Supplementary, firmware only, upgrade kit for 2715SA Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AB1111003	SIMM Memory Module Upgrade Kit for Models 2715SA-08 and 2715SA-F-08. Includes a 4Mbyte that upgrades Models 2715SA-08 and 2715SA-F-08 to Models 2715SA-08-4M and 2715SA-F-08-4M, as needed to support Agent 2.0.	PASS	v2.0	N/A	N/A	
AC1007001	Model 3313SA-4M Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes AUI interconnection Port and Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	
AC1007002	Model 3314SA-4M Ethernet Network Management Module with connections to Channels A and B of System 3000 Multi-segment Ethernet backplanes. Includes 10BASE-FL interconnection Port and Advanced Analyzer Network Management Agent.	PASS	N/A	N/A	N/A	
AC1107001	Model 3517SA-4M Token Ring Network Management Module with Shielded Twisted Pair (STP) and Fiber Optic Repeater. Included License for Advanced Analyzer Network Management Agent with version 2.0 agent.	PASS	v2.0	N/A	N/A	
AC1111003	SIMM Memory Module Upgrade Kit for Model 3517SA-08. Includes a 4Mbyte that upgrades Model 3517SA-08 to Model 3517SA-08-4M, as needed to support Agent 2.0.	PASS	v2.0	N/A	N/A	
AC2202002	Model 3000CT Premises Concentrator with Multi-Segment Ethernet/Token Ring/Fast Ethernet Backplane and Model 3002 460W Power Supply.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AC2204001	Model 3405 Fast Ethernet Host Module with 12 100BASE-TX ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AC2204002	Model 3475-FX Fast Ethernet Host Module with 11 100BASE-TX ports and 1 100BASE-FX port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AC2207001	Model 3410 Fast Ethernet Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
ACCESS STACK NODE SYSTEMS		PASS	N/A	N/A	N/A	
AD0005001	Model 5052 DC Power Supply (Minimum one supply required per 5005 chassis).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD0005002	Model 5002 DC Power Supply (Minimum one supply required per 5000 chassis)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD0005003	Model 5051H 900W AC Power Supply for System 5005 (Minimum one Model 5051L or Model 5051H required per 5005 Chassis).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD0005F04	Model 5001 950W AC Power Supply (minimum one supply required per 5000 chassis). Includes Australian power cord, also used in New Zealand and the PRC.	PASS	N/A	N/A	N/A	
AD0008001	System 5000 Router System Suite 10.0 (4M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008002	System 5000 Router LAN Suite 10.0 (4M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008003	System 5000 Router WAN Suite 10.0 (4M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008004	System 5000 Router Corporate Suite 10.0 (8M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008009	System 5000 Router System Suite 11.0 (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008009	System 5000 Router System Suite 11.03	PASS	11.03	N/A	N/A	
AD0008010	System 5000 Router LAN Suite 11.0 (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008010	System 5000 Router LAN Suite 11.03	PASS	11.03	N/A	N/A	
AD0008011	System 5000 Router WAN Suite 11.0 (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008011	System 5000 Router WAN Suite 11.03	PASS	11.03	N/A	N/A	
AD0008012	System 5000 Router Corporate Suite 11.0 (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008012	System 5000 Router Corporate Suite 11.03	PASS	11.03	N/A	N/A	
AD0008013	System 5000 Router Corp Suite Additional Protocol for v11.0 - CD-ROM	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD0008014	System 5000 Router System Suite 11.0 (4M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AD0008014	System 5000 Router System Suite 11.03 (4M PCMCIA) includes Data Compression, TCP/IP, 802.1, Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw. *	PASS	11.03	N/A	N/A	
AD0008015	System 5000 Router V12.0 System Suite	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008016	System 5000 Router V12.0 System Suite 8M	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008017	System 5000 Router V12.0 LAN Suite 8M	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008018	System 5000 Router V12.0 WAN Suite 8M	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008019	System 5000 Router V12.0 Corporate Suite 8M	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008020	System 5000 Router Corp Suite Additional Protocol for v12.0 - CD ROM	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD0008021	System 5000 Router V12.10 System Suite 8M	PASS	v12.10	N/A	N/A	
AD0008021	System 5000 Router V12.20 System Suite 8M	PASS	v12.20	N/A	N/A	
AD0008022	System 5000 Router V12.10 LAN Suite 8M	PASS	v12.10	N/A	N/A	
AD0008022	System 5000 Router V12.20 LAN Suite 8M	PASS	v12.20	N/A	N/A	
AD0008023	System 5000 Router V12.10 WAN Suite 8M	PASS	v12.10	N/A	N/A	
AD0008023	System 5000 Router V12.20 WAN Suite 8M	PASS	v12.20	N/A	N/A	
AD0008024	System 5000 Router V12.10 Corporate Suite 8M	PASS	v12.10	N/A	N/A	
AD0008024	System 5000 Router V12.20 Corporate Suite 8M	PASS	v12.20	N/A	N/A	
AD0008025	System 5000 Router Version 12.10 Corp Suite - Additional Protocols - CD-ROM	PASS	v12.10	N/A	N/A	
AD0008025	System 5000 Router Version 12.20 Corp Suite - Additional Protocols - CD-ROM.	PASS	v12.20	N/A	N/A	
AD0008026	BaySecure Firewall - 1 Agent License for for 5380 or 5580. Requires Version 12.10 or higher.	PASS	v12.10	N/A	N/A	
AD0008027	System 5000 Router V13.0 System Suite 8M	PASS	v13.0	N/A	N/A	
AD0008028	System 5000 Router V13.0 LAN Suite 8M	PASS	v13.0	N/A	N/A	
AD0008029	System 5000 Router V13.0 WAN Suite 8M	PASS	v13.0	N/A	N/A	
AD0008030	System 5000 Router V13.0 Corporate Suite 8M	PASS	v13.0	N/A	N/A	
AD0008031	System 5000 Router Version 13.0 Corp Suite - Additional Protocols - CD-ROM.	PASS	v13.0	N/A	N/A	
AD0008032	System 5000 Router V13.10 System Suite 8M.	PASS	v13.10	N/A	N/A	
AD0008033	System 5000 Router V13.10 LAN Suite 8M.	PASS	v13.10	N/A	N/A	
AD0008034	System 5000 Router V13.10 WAN Suite 8M.	PASS	v13.10	N/A	N/A	
AD0008035	System 5000 Router V13.10 Corporate Suite 8M.	PASS	v13.10	N/A	N/A	
AD0008036	System 5000 Router Version 13.10 Corp Suite - Additional Protocols - CD-ROM.	PASS	v13.10	N/A	N/A	
AD0008037	DES - 56 IPSEC Option for System 5000 Router Software Version 13.10.	PASS	v13.10	N/A	N/A	
AD0008038	System 5000 Router V13.20 System Suite 8M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008039	System 5000 Router V13.20 LAN Suite 8M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008040	System 5000 Router V13.20 WAN Suite 8M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008043	System 5000 Router V13.20 System Suite 16M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008044	System 5000 Router V13.20 LAN Suite 16M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008045	System 5000 Router V13.20 WAN Suite 16M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008046	System 5000 Router V13.20 Corporate Suite 16M. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008047	System 5000 Router Version 13.20 Corp Suite - Additional Protocols - CD-ROM.	PASS	N/A	N/A	N/A	
AD0008048	3DES - IPSEC Option for System 5000 Router Software Version 13.20.	PASS	N/A	N/A	N/A	
AD0008049	System 5000 Router Version 11.03 Upgrade Kit - CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
AD0008050	DES - 56 IPSEC Option for System 5000 Router Software Version 13.20, 13.10.	PASS	N/A	N/A	N/A	
AD0011009	Airflow Module (Required for all empty slots in the 5000 chassis when using Router Modules)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD0011012	Models 5110/5115 Supervisory Modules Firmware REV 2.0 Upgrade Kit. Enables Proxy Mgmt for the 5000BH System and Telnet into the 5110 and 5115 Supervisory Modules. Includes firmware and installation instructions.	PASS	N/A	v2.0	N/A	
AD0011013	5 Pack Single Slot Filler Panels	PASS	N/A	N/A	N/A	
AD0011014	5 Pack Two Slot Filler Panels	PASS	N/A	N/A	N/A	
AD0011015	5 Pack Four Slot Filler Panels	PASS	N/A	N/A	N/A	
AD1004001	Model 5300PS per-port config. switching Ethernet Host with MDAs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1004002	Model 5307PS-HD 36 port 10BASE-T Ethernet Telco Host Module with per-port config switching and security.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1004003	Model 5380 Ethernet Router Module (must order memory separately)*	PASS	11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AD1004004	Model 5308PS 24-Port 10BASE-T Configuration Switching Ethernet Host Module with Port Security	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1004005	Model 5307S 24-Port 10BASE-T Telco with Security	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1004006	Model 5307PS 24-Port 10BASE-T Configuration Switching Ethernet Host Module with Port Security and Telco D-Connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1004007	Model 5308S 24-Port 10BASE-T with Security	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1007001	Model 5310A-8M Ethernet Network Management Module with pre-installed Management Communications Engine (MCE) and sockets for two additional Model 5311A DCEs.	PASS	N/A	N/A	N/A	
AD1007002	Model 5310SA-8M Ethernet Network Management Module with pre-installed Data Collection Engine (DCE) and sockets for two additional Model 5311A DCE's	PASS	N/A	N/A	N/A	
AD1011009	Agent 2.0 Upgrade Kit for System 5000 Network Management Modules. Upgrades Models 5310A, 5310SA and 5510-06.	PASS	N/A	N/A	N/A	
AD1011010	Models 5307/5307P/5308/5308P Ethernet Host Modules Firmware REV E Upgrade Kit. Enables autopartition protection from 100BASE-TX connections into 10BaseT shared media segments. Includes firmware, release notes and installation instructions.	PASS	N/A	N/A	N/A	
AD1011011	Models 5307S/5307PS/5308S/5308PS Ethernet Host Modules Firmware REV B Upgrade Kit. Enables autopartition protection from 100BASE-TX connections into 10BaseT shared media segments. Includes firmware, release notes and installation instructions.	PASS	N/A	N/A	N/A	
AD1033001	Multi-mode Fiber MDA for 5300PS Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033002	AUI MDA for 5300PS Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033003	10BASE-2 Host MDA for 5300PS Ethernet Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033004	10BASE-T host MDA for 5300PS module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033005	Single Mode Fiber MDA for 5300PS host module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033006	Male AUI MDA for 5300PS host module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1033007	Router Dual Ethernet Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104001	Model 5580 Token Ring Router Module (must order memory separately)*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104002	Model 5505S 24-Port Active Retiming STP/UTP Token Ring Host Module with embedded intelligence. Includes model 559 EMT.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104003	Model 5505PS 20-Port Active Retiming STP/UTP Token Ring Host Module with Per-Port Configuration Switching and embedded intelligence. Includes model 559 EMT.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104004	Model 5575A-F dual repeater cluster Token Ring Host Module with 2 fiber RI/RO trunks nd 6 active retiming STP/UTP Ports plus monitor port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104005	Model 5575A-C dual repeater cluster Token Ring Host Module with 2 fiber RI/RO trunks nd 6 active retiming STP/UTP Ports plus monitor port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1104008	Model 5575A-FJ Dual Repeater Cluster Module with 2 fiber ports, 6 active retimed UTP/STP ports, 1 monitor port, and embedded intelligence. 802.5j compliant.	PASS	N/A	N/A	N/A	
AD1107002	Model 5510-06-8M Token Ring Network Management Module with on-board Data Collection Engine (DCE) and socket for one additional 5511 DCE.	PASS	N/A	N/A	N/A	
AD1111002	Kit to upgrade 5505 with embedded intelligence. Includes 559 embedded management tool.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1111003	Kit to upgrade 5505P module with embedded intelligence. Includes model 559 embedded management tool.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1111004	Kit to upgrade 5505 with embedded intelligence. For use in upgrading existing 5505 modules already utilizing the model 559 EMT.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1111005	Kit to upgrade 5505P with embedded intelligence. For use in upgrading existing 5505P modules already utilizing the model 559 EMT.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1111006	Kit to upgrade 5575-F module with embedded intelligence.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1111007	Kit to upgrade 5575-C module with embedded intelligence.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1133002	Router Dual Token Ring Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1233002	Router Multimode FDDI Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1302001	Model 5000AH ATM/Ethernet/Token Ring Chassis (14 slots).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1304001	Model 5740 Switch Control Module with preloaded CMS, MCS, and switch management processes.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1304002	Model 5720 ATM Switch Fabric Module	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AD1304003	Model 5714 ATM Host Module with 8 ports of connectivity	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1304004	Model 5700 ATM Host Module houses up to 4 Media Dependent Adapter (MDA) cards	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1304006	Model 5780 ATM Router Module 16M DRAM /3M SRAM* (compatible only with Model 5000AH ATM/Ethernet/Token Ring Chassis)	PASS	N/A	N/A	N/A	
AD1304007	Model 5780 ATM Router Module 32M DRAM /6M SRAM* (compatible only with Model 5000AH ATM/Ethernet/Token Ring Chassis)	PASS	N/A	N/A	N/A	
AD1308001	ATM Router VNR Software (8M PCMCIA) (for Model 5780)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD1308002	ATM Router VNR Software 11.0 (16M PCMCIA) Flash (for Model 5780)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AD1308003	ATM Router VNR Software 12.0 (16M PCMCIA)	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AD1308004	System 5000 ATM VNR V12.20 Suite 16M PCMICA (for Model 5782).	PASS	v12.20	N/A	N/A	
AD1308005	System 5000 ATM VNR V13.0 Suite 16M PCMICA (for Model 5782).	PASS	v13.0	N/A	N/A	
AD1308006	System 5000 ATM VNR V13.10 Suite 16M PCMICA (for Model 5782).	PASS	v13.10	N/A	N/A	
AD1308007	System 5000 ATM VNR V13.20 Suite 32M PCMICA (for Model 5782). (See Note 1)	PASS	N/A	N/A	N/A	
AD1308008	System 5000 ATM VNR V13.0 Suite 32M PCMICA (for Model 5782).	PASS	N/A	N/A	N/A	
AD1311004	Model 5000AH ATM backplane upgrade kit - post 12/94	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1311005	Model 5000AH ATM upgrade kit - pre 12/94	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1311006	Model 5000AH ATM and FDDI upgrade kit - pre 12/94	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1333001	Model 5700-14 Two 155 Mbps Multimode Fiber Ports on a Media Dependent Adapter (MDA) card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1333002	Model 5700-15 Two 155 Mbps Unshielded Twisted Pair Ports on a Media Adapter (MDA) card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1333003	Model 5700-17 Two 155 Mbps Single Mode Fiber Ports on a Media Dependent Adapter (MDA) card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1333004	Model 5700-31 Two 45 Mbps DS3 Ports on a Media Dependent Adapter (MDA) card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1333005	Model 5700-41 Two 34 Mbps E3 Ports on a Media Dependent Adapter (MDA) card	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AD1402001	Model 5000BH ATM/PPX/Ethernet/Token Ring Chassis (14 slots)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1402002	Model 5000BHC ATM/PPX/Fast Ethernet/Ethernet/Token Ring Chassis (14 slots)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD1411001	Model 5000BH ATM/PPX backplane upgrade kit - available only for post 12/94 System 5000 chassis (manufacturing date code of 120194 or later)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2111004	Single HSSI Net Module Field Upgrade (requires v.12.0 Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133002	Router Dual Sync Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133004	Router Quad BRI Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133006	MCE1 Net Module for channelized E1 and ISDN PRI Field Upgrade	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133008	Dual MCT1 Field Upgrade (requires v.11.01 Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133010	Router Quad Sync Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133012	Router 32-Contexts Hardware Compression co-processor Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2133015	Router 128-Contexts Hardware Compression co-processor Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2201001	Model 5000C Fast Ethernet/Ethernet Chassis (14 slots)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2202001	Model 5005C Fast Ethernet/Ethernet Chassis (8 slots)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2204001	Model 5405 16 port 100BASE-TX Fast Ethernet Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2204002	Model 5475-FX 14 port 100BASE-TX and 2 port 100BASE-FX Fast Ethernet Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2204003	Model 5605P 24 port 10BASE-T/100BASE-TX autosense Ethernet/Fast-Ethernet Per-Port configuration Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2204004	Model 5675P-FX 20 port Autosense 10BASE-T/100BASE-TX Ethernet/Fast Ethernet and 2 port full duplex 100BASE-FX host module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2204005	Model 5620-FX 4-Port 100BASE-FX full duplex Segment Switching Module.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AD2207001	Model 5616SA Fast Ethernet and Ethernet Network Management Module; manages 12 Fast Ethernet and 12 Ethernet segments; comes pre-installed with one 5611-DCM that has two RMON1 and RMON2 interfaces. The 5616SA NMM has two additional sockets for 5611-DCMs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2207003	Model 5616A Fast Ethernet and Ethernet NMM; Manages 12 Fast Ethernet and 12 Ethernet segments simultaneous	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2211001	Model 5000C Fast Ethernet Backplane Upgrade Kit; available only for post 12/94 System 5000 Chassis (manufacturing date code of 120194 or later)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2233002	Router 100Base-T Net Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD2236001	Model 5611-DCM 10/100 Mbit/s RMON/RMON 2 Probe for Model 5616A Network Management Modules	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AD3102001	Model 5000S 14 slot frame switching chassis with three backplanes: 7.5Gbps frame switching backplane "S", 1.2 Gbps 12 segment Fast Ethernet backplane "C" and 12 segment Ethernet backplane "N".	PASS	N/A	N/A	N/A	
AD3102002	Model 5005S 8 slot frame switching chassis with three backplanes: 5Gbps frame switching backplane "S", 1.2 Gbps 12 segment Fast Ethernet backplane "C" and 12 segment Ethernet backplane "N".	PASS	N/A	N/A	N/A	
AD3104001	Model 5665 24 port 10BASE-T / 100BASE-TX Autosense desktop frame switching Host Module. Model 5665 connects to the frame switching backplane "S".	PASS	N/A	N/A	N/A	
AD3104002	Model 5660-FX 3 in 1 combo card. Frame switching NMM, shared media segment switch and 4 100Base-FX front panel uplink ports for frame switching and shared media modules.	PASS	N/A	N/A	N/A	
AD3111001	Frame switching backplane "S" upgrade kit for the 14 slot Model 5000S.	PASS	N/A	N/A	N/A	
AD3111002	Frame switching backplane "S" upgrade kit the 8 slot Model 5005S.	PASS	N/A	N/A	N/A	
AE0004003	AN/12-port ANH 2nd Ethernet Adapter Module **	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004004	AN Ethernet Data Collection Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004005	8-port ANH 3rd Synchronous Adapter Module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004006	8-port ANH ISDN BRI S/T (without NT1) Adapter Module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004007	8-port ANH 2nd Ethernet Adapter Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004008	8-port ANH Ethernet Data Collection Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0004012	8-port ANH DSU/CSU 56/64 kbps Adapter Module (North America Only)	PASS	N/A	N/A	N/A	
AE0004016	AN/12 Port ANH T1/FT1 Adapter Module	PASS	N/A	N/A	N/A	
AE0004017	8-Port ANH T1/FT1 Adapter Module	PASS	N/A	N/A	N/A	
AE0004018	AN/12-port ANH E1/FE1 Adapter Module (RJ)	PASS	N/A	N/A	N/A	
AE0004019	AN/12-port ANH E1/FE1 Adapter Module (BCN)	PASS	N/A	N/A	N/A	
AE0004020	8-port ANH E1/FE1 Adapter Module (RJ)	PASS	N/A	N/A	N/A	
AE0004021	8-port ANH E1/FE1 Adapter Module (BNC)	PASS	N/A	N/A	N/A	
AE0008003	IP Access Suite (4M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008004	Remote Office Suite (4M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008005	Corporate Suite (4M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008014	IP Access Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008015	Remote Office Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008016	Corporate Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008017	IP Access Suite (4M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008018	Remote Office Suite (4M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008019	Corporate Suite (4M PCMCIA) includes all Version 8.1 Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008020	IP Access Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008021	Remote Office Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008022	Corporate Suite (8M PCMCIA)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE0008023	IP Access Suite (4M PCMCIA) includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008024	Remote Office Suite (4M PCMCIA) includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AE0008025	Corp Suite (4M PCMCIA) includes all Version 10.0 software	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008027	Version 10.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008028	IP Access Suite (8M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008029	Remote Office Suite (8M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008030	Corporate Suite (8M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008032	IP Access Suite (4M PCMCIA) includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008032	IP Access Suite V11.03 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI.	PASS	N/A	N/A	N/A	
AE0008033	Remote Office Suite (4M PCMCIA) includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008033	Remote Office Suite V11.03 includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk.	PASS	v11.03	N/A	N/A	
AE0008034	Corporate Suite (4M PCMCIA) includes all Version 11.0 software	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008035	Version 11.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008035	Version 11.03 Corporate Suite Additional Protocols.**	PASS	v11.03	N/A	N/A	
AE0008036	IP Access Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008036	IP Access Suite V11.03 Software.	PASS	v11.03	N/A	N/A	
AE0008037	Remote Office Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008037	Remote Office Suite V11.03 Software.	PASS	v11.03	N/A	N/A	
AE0008038	Corporate Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AE0008038	Corporate Suite includes all Version 11.03 Software.	PASS	v11.03	N/A	N/A	
AE0008039	IP Access Suite (4M PCMCIA) V12.0 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008041	IP Access Suite (8M PCMCIA) V12.0	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008042	Remote Office Suite (8M PCMCIA) V12.0	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008043	Corporate Suite (8M PCMCIA) includes all V12.0 Software	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008044	Version 12.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008046	IP Access Suite (16M PCMCIA) V12.0	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008047	Remote Office Suite (16M PCMCIA) V12.0	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008048	Corporate Suite (16M PCMCIA) includes all V12.0 Software	FAIL	12.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AE0008049	IP Access Suite (8M PCMCIA) V12.10 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	PASS	v12.10	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AE0008049	IP Access Suite (8M PCMCIA) V12.20 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI.	PASS	N/A	N/A	N/A	
AE0008050	Remote Office Suite (8M PCMCIA) 12.10	PASS	v12.10	N/A	N/A	
AE0008050	Remote Office Suite (8M PCMCIA) 12.20.	PASS	N/A	N/A	N/A	
AE0008051	Corporate Suite (8M PCMCIA) includes all V12.10 Software	PASS	v12.10	N/A	N/A	
AE0008051	Corporate Suite (8M PCMCIA) includes all V12.20 Software.	PASS	v12.20	N/A	N/A	
AE0008052	IP Access Suite (16M PCMCIA) 12.10	PASS	v12.10	N/A	N/A	
AE0008052	IP Access Suite (16M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
AE0008053	Remote Office Suite (16M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
AE0008054	Corporate Suite (16M PCMCIA) includes all V12.10 Software	PASS	v12.10	N/A	N/A	
AE0008054	Corporate Suite (16M PCMCIA) includes all V12.20 Software.	PASS	v12.20	N/A	N/A	
AE0008055	Remote Office Suite (16M PCMCIA) 12.10	PASS	v12.10	N/A	N/A	
AE0008055	Version 12.10 Corporate Suite Additional Protocols - CD-ROM	PASS	v12.10	N/A	N/A	
AE0008055	Version 12.20 Corporate Suite Additional Protocols - CD-ROM.	PASS	v12.20	N/A	N/A	
AE0008059	IP Access Suite (8M PCMCIA) V13.0	PASS	v13.0	N/A	N/A	
AE0008060	Remote Office Suite (8M PCMCIA) V13.0	PASS	v13.0	N/A	N/A	
AE0008061	Corporate Suite (8M PCMCIA) includes all V13.0 Software	PASS	v13.0	N/A	N/A	
AE0008062	IP Access Suite (16M PCMCIA) V13.0	PASS	v13.0	N/A	N/A	
AE0008063	Remote Office Suite (16M PCMCIA) V13.0	PASS	v13.0	N/A	N/A	
AE0008064	Corporate Suite (16M PCMCIA) includes all V13.0 Software	PASS	v13.0	N/A	N/A	
AE0008065	Version 13.0 Corporate Suite Additional Protocols - CD-ROM.	PASS	v13.0	N/A	N/A	
AE0008066	IP Access Suite (8M PCMCIA) V13.10 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression (WCP/MSA), Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI.	PASS	v13.10	N/A	N/A	
AE0008067	Remote Office Suite (8M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
AE0008068	Corporate Suite (8M PCMCIA) includes all V13.10 Software.	PASS	v13.10	N/A	N/A	
AE0008069	IP Access Suite (16M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
AE0008070	Remote Office Suite (16M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
AE0008071	Corporate Suite (16M PCMCIA) includes all V13.10 Software.	PASS	v13.10	N/A	N/A	
AE0008072	Version 13.10 Corporate Suite Additional Protocols - CD-ROM.	PASS	v13.10	N/A	N/A	
AE0008073	DES - 56 IPSEC Option for BayStack AN-ANH System Software Version 13.10.	PASS	v13.10	N/A	N/A	
AE0008078	IP Access Suite (8M PCMCIA) V13.20 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression (WCP/MSA), Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008078	IP Access Suite (8M PCMCIA) V13.20 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression (WCP/MSA), Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008079	Remote Office Suite (8M PCMCIA) 13.20. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008079	Remote Office Suite (8M PCMCIA) 13.20. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008080	Corporate Suite (8M PCMCIA) includes all V13.20 Software. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008080	Corporate Suite (8M PCMCIA) includes all V13.20 Software. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008081	IP Access Suite (16M PCMCIA) V13.20 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression (WCP/MSA), Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008081	IP Access Suite (16M PCMCIA) V13.20 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression (WCP/MSA), Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008082	Remote Office Suite (16M PCMCIA) 13.20. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008082	Remote Office Suite (16M PCMCIA) 13.20. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008083	Corporate Suite (16M PCMCIA) includes all V13.20 Software. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008083	Corporate Suite (16M PCMCIA) includes all V13.20 Software. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008084	3DES IPSEC Option for BayStack AN-ANH System Software Version 13.20.	PASS	N/A	N/A	N/A	
AE0008085	Version 13.20 Corporate Suite Additional Protocols - CD-ROM. (See Note 3)	PASS	N/A	N/A	N/A	
AE0008086	AN-ANH Version 11.03 Upgrade Kit - CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
AE0008087	DES - 56 IPSEC Option for BayStack AN-ANH System Software Version V13.20, 13.10.	PASS	N/A	N/A	N/A	
AE0011010	AN/12-port ANH 2nd Ethernet Field Upgrade/Spare **	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011011	AN Ethernet Data Collection Module Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011012	8-port ANH 3rd Synchronous Field Upgrade/Spare ***	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011013	8-port ANH ISDN BRI S/T (without NT1) Field Upgrade/Spare ***	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AE0011014	8-port ANH 2nd Ethernet Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011015	8-port ANH Ethernet Data Collection Module Field Upgrade/Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011018	AN/12-port ANH 2nd Ethernet**	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011022	AN Ethernet Data Collection Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011023	8-port ANH Ethernet Data Collection Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AE0011026	8-port ANH DSU/CSU 56/64 kbps Field Upgrade/Spare (North America Only)	PASS	N/A	N/A	N/A	
AE0011029	AN/12-port ANH T1/FT1 Field Upgrade/Spare	PASS	N/A	N/A	N/A	
AE0011030	8-port ANH T1/FT1 Field Upgrade/Spare	PASS	N/A	N/A	N/A	
AE0011031	AN/12-port ANH E1/FE1 Field Upgrade/Spare (RJ)	PASS	N/A	N/A	N/A	
AE0011032	AN/12-port ANH E1/FE1 Field Upgrade/Spare (BNC)	PASS	N/A	N/A	N/A	
AE0011033	8-port ANH E1/FE1 Field Upgrade/Spare (RJ)	PASS	N/A	N/A	N/A	
AE0011034	8-port ANH E1/FE1 Field Upgrade/Spare (BNC)	PASS	N/A	N/A	N/A	
AE1001001	ANH8 4M DRAM with V.8.10 IP Access on 2M Flash, and North American Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001002	ANH8 4M DRAM with V8.10 Remote Office on 2M Flash, and North American Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001003	ANH8 8M DRAM with V8.10 IP Access on 2M Flash, and North American Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001004	ANH8 8M DRAM with V8.10 Remote Office on 2M Flash, and North American Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001005	1 Ethernet x 2 Sync Base System	PASS	N/A	N/A	N/A	
AE1001006	BayStack AN: 1 Ethernet x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1001007	BayStack AN: 1 Ethernet x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1001008	BayStack AN: 1 Ethernet x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1001009	8-port Ethernet hub x2 Sync Base System	PASS	N/A	N/A	N/A	
AE1001010	BayStack ANH: 8-port Ethernet Hub x2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1001011	BayStack ANH: 8-port Ethernet Hub x2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1001012	BayStack ANH: 8-port Ethernet Hub x2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1001013	12-port Ethernet hub x 2 Sync Base System	PASS	N/A	N/A	N/A	
AE1001014	BayStack ANH: 12-port Ethernet Hub x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1001015	BayStack ANH: 12-port Ethernet Hub x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1001016	BayStack ANH: 12-port Ethernet Hub x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1001018	8-port ANH with 4MDRAM, V9.0 IP Access on 4M Flash, and North American (10A/110-120V) Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001019	8-port ANH with 4MDRAM, V9.0 Remote Office on 4M Flash, and North American (10A/110-120V) Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001020	8-port ANH with 8MDRAM, V9.0 IP Access on 4M Flash, and North American (10A/110-120V) Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001021	8-port ANH with 8MDRAM, V9.0 Remote Office on 4M Flash, and North American (10A/110-120V) Power Cord	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AE1001037	DC AN: 1 Ethernet x 2 Sync (0M DRAM)	PASS	N/A	N/A	N/A	
AE1001038	BayStack DC AN: 1 Ethernet x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1001039	BayStack DC AN: 1 Ethernet x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1001040	BayStack DC AN: 1 Ethernet x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1001041	DC AN: 8 Port Ethernet Hub x 2 Sync (0M DRAM)	PASS	N/A	N/A	N/A	
AE1001042	BayStack DC AN: 8 Port Ethernet Hub x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1001043	BayStack DC AN: 8 Port Ethernet Hub x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1001044	BayStack DC AN: 8 Port Ethernet Hub x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1101001	1 Token Ring x 2 Sync Base System	PASS	N/A	N/A	N/A	
AE1101002	BayStack AN: 1 Token Ring x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1101003	BayStack AN: 1 Token Ring x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1101004	BayStack AN: 1 Token Ring x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AE1101005	1 Ethernet x 1 Token Ring x 2 Sync Base System	PASS	N/A	N/A	N/A	
AE1101006	BayStack AN: 1 Ethernet x 1 Token Ring x 2 Sync (4M DRAM)	PASS	N/A	N/A	N/A	
AE1101007	BayStack AN: 1 Ethernet x 1 Token Ring x 2 Sync (8M DRAM)	PASS	N/A	N/A	N/A	
AE1101008	BayStack AN: 1 Ethernet x 1 Token Ring x 2 Sync (16M DRAM)	PASS	N/A	N/A	N/A	
AF0002702	ASN2 Base Unit 0MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002703	ASN2 Base Unit 0MB AC Redundant	PASS	11.03	N/A	N/A	
AF0002708	ASN2 Base Unit 8MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002709	ASN2 Base Unit 16MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002710	ASN2 Base Unit 32MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002711	ASN Base Unit AC Redundant (8MB)	PASS	11.03	N/A	N/A	
AF0002712	ASN Base Unit AC Redundant (16MB)	PASS	11.03	N/A	N/A	
AF0002713	ASN Base Unit AC Redundant (32MB)	PASS	11.03	N/A	N/A	
AF0002008	ASN2 Base Unit 8MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002009	ASN2 Base Unit 16MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002010	ASN2 Base Unit 32MB Non-Redundant	PASS	11.03	N/A	N/A	
AF0002011	ASN2 Base Unit 8M AC Redundant Power	PASS	11.03	N/A	N/A	
AF0002012	ASN2 Base Unit 16M AC Redundant Power	PASS	11.03	N/A	N/A	
AF0002013	ASN2 Base Unit 32M AC Redundant Power	PASS	11.03	N/A	N/A	
AF0002A01	ASN 0M DRAM Base Unit	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AF0002A04	ASN2 Base Unit 0MB 48V Redundant	PASS	11.03	N/A	N/A	
AF0002A14	ASN2 Base Unit 8M 48V Redundant Power	PASS	11.03	N/A	N/A	
AF0002A15	ASN2 Base Unit 16M 48V Redundant Power	PASS	11.03	N/A	N/A	
AF0002A16	ASN2 Base Unit 32M 48V Redundant Power	PASS	11.03	N/A	N/A	
AF0008001	ASN Version 9.0 System Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008002	ASN Version 9.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008003	ASN Version 9.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS *	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008004	ASN Version 9.0 Corp Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008005	ASN Version 9.0 Corp Suite Additional Protocol - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008006	ASN Version 9.0 Corp Suite Additional Protocol - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0008007	ASN Version 10.0 System Suite 4M includes TCP/IP, 802.1, Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw *	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008008	ASN Version 10.0 LAN Suite 4M Includes System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI *	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008009	ASN Version 10.0 WAN Suite 4M Includes System Suite plus ATM DXI, Frame Relay, LapB, X.25, SMDS *	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008010	ASN Version 10.0 Corporate Suite (8M PCMCIA)	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008012	ASN Version 10.0 Corp Suite - Additional Protocols - CD-ROM	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008013	ASN Version 10.0 System Suite (8M PCMCIA)*	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008014	ASN Version 10.0 LAN Suite (8M PCMCIA)*	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008015	ASN Version 10.0 WAN Suite (8M PCMCIA)*	FAIL	10.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008017	ASN Version 11.0 System Suite (8M PCMCIA)*	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008017	ASN Version 11.03 System Suite**	PASS	v11.03	N/A	N/A	
AF0008018	ASN Version 11.0 LAN Suite (8M PCMCIA)*	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008018	ASN Version 11.03 LAN Suite**	Pass	v11.03	N/A	N/A	
AF0008019	ASN Version 11.0 WAN Suite (8M PCMCIA)*	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008019	ASN Version 11.03 WAN Suite**	PASS	v11.03	N/A	N/A	
AF0008020	ASN Version 11.0 Corporate Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008020	ASN Version 11.03 Corporate Suite	PASS	v11.03	N/A	N/A	
AF0008021	ASN Version 11.0 Corp Suite - Additional Protocols - CD-ROM	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008021	ASN Version 11.03 Corp Suite - Additional Protocols - CD-ROM.*	PASS	v11.03	N/A	N/A	
AF0008022	ASN Version 11.0 System Suite 4M includes TCP/IP, 802.1, Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw *	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AF0008022	ASN Version 11.03 System Suite includes Data Compression, TCP/IP, 802.1, Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw *	PASS	v11.03	N/A	N/A	
AF0008023	BaySecure Firewall - 1 Agent License for Access Stack Node Systems. Requires Version 11.02 or higher software	FAIL	11.x	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AF0008025	ASN Version 12.0 System Suite (8M PCMCIA)*	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AF0008026	ASN Version 12.0 LAN Suite (8M PCMCIA)*	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AF0008027	ASN Version 12.0 WAN Suite (8M PCMCIA)*	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AF0008028	ASN Version 12.0 Corporate Suite (8M PCMCIA)	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AF0008029	ASN Version 12.0 Corp Suite - Additional Protocols - CD-ROM	FAIL	v12.0	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AF0008030	ASN Version 12.10 System Suite (8M PCMCIA)	PASS	12.1	N/A	N/A	
AF0008030	ASN Version 12.20 System Suite (8M PCMCIA)*.	PASS	v12.20	N/A	N/A	
AF0008031	ASN Version 12.10 LAN Suite (8M PCMCIA)	PASS	12.1	N/A	N/A	
AF0008031	ASN Version 12.20 LAN Suite (8M PCMCIA)*.	PASS	v12.20	N/A	N/A	
AF0008032	ASN Version 12.10 WAN Suite (8M PCMCIA)	PASS	12.1	N/A	N/A	
AF0008032	ASN Version 12.20 WAN Suite (8M PCMCIA)*.	PASS	v12.20	N/A	N/A	
AF0008033	ASN Version 12.10 Corporate Suite (8M PCMCIA)	PASS	12.1	N/A	N/A	
AF0008033	ASN Version 12.20 Corporate Suite (8M PCMCIA).	PASS	v12.20	N/A	N/A	
AF0008034	ASN Version 12.10 Corp Suite - Additional Protocols - CD-ROM	PASS	12.1	N/A	N/A	
AF0008034	ASN Version 12.20 Corp Suite - Additional Protocols - CD-ROM	PASS	v12.20	N/A	N/A	
AF0008042	ASN Version 13.0 System Suite (8M PCMCIA)*	PASS	v13.0	N/A	N/A	
AF0008043	ASN Version 13.0 LAN Suite (8M PCMCIA)*	PASS	v13.0	N/A	N/A	
AF0008044	ASN Version 13.0 WAN Suite (8M PCMCIA)*	PASS	v13.0	N/A	N/A	
AF0008045	ASN Version 13.0 Corporate Suite (8M PCMCIA)	PASS	v13.0	N/A	N/A	
AF0008046	ASN Version 13.0 LAN Suite (16M PCMCIA)*	PASS	v13.0	N/A	N/A	
AF0008047	ASN Version 13.0 WAN Suite (16M PCMCIA)*	PASS	v13.0	N/A	N/A	
AF0008048	ASN Version 13.0 Corporate Suite 16M PCMCIA)	PASS	v13.0	N/A	N/A	
AF0008049	ASN Version 13.0 Corp Suite - Additional Protocols - CD-ROM.	PASS	v13.0	N/A	N/A	
AF0008050	ASN Version 13.10 System Suite (8M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008051	ASN Version 13.10 LAN Suite (8M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008052	ASN Version 13.10 WAN Suite (8M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008053	ASN Version 13.10 Corporate Suite (8M PCMCIA).	PASS	v13.10	N/A	N/A	
AF0008054	ASN Version 13.10 Corp Suite - Additional Protocols - CD-ROM.	PASS	v13.10	N/A	N/A	
AF0008055	DES - 56 IPSEC Option for ASN System Software Version 13.10.	PASS	v13.10	N/A	N/A	
AF0008056	ASN Version 13.10 System Suite (16M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008057	ASN Version 13.10 LAN Suite (16M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008058	ASN Version 13.10 WAN Suite (16M PCMCIA)*.	PASS	v13.10	N/A	N/A	
AF0008059	ASN Version 13.10 Corporate Suite (16M PCMCIA).	PASS	v13.10	N/A	N/A	
AF0008063	ASN Version 13.20 System Suite (8M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008063	ASN Version 13.20 System Suite (8M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008064	ASN Version 13.20 LAN Suite (8M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008064	ASN Version 13.20 LAN Suite (8M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AF0008065	ASN Version 13.20 WAN Suite (8M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AF0008065	ASN Version 13.20 WAN Suite (8M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AF0008067	ASN Version 13.20 System Suite (16M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008067	ASN Version 13.20 System Suite (16M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008068	ASN Version 13.20 LAN Suite (16M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008068	ASN Version 13.20 LAN Suite (16M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AF0008069	ASN Version 13.20 WAN Suite (16M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AF0008069	ASN Version 13.20 WAN Suite (16M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AF0008070	ASN Version 13.20 Corporate Suite (16M PCMCIA).	PASS	N/A	N/A	N/A	
AF0008070	ASN Version 13.20 Corporate Suite (16M PCMCIA).	PASS	N/A	N/A	N/A	
AF0008071	3DES - IPSEC Option for ASN System Software Version 13.20.	PASS	N/A	N/A	N/A	
AF0008072	ASN Version 13.20 Corp Suite - Additional Protocols - CD-ROM.	PASS	N/A	N/A	N/A	
AF0008073	ASN Version 11.03 Upgrade Kit - CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
AF0008074	DES - 56 IPSEC Option for ASN System Software Versions 13.20, 13.10.	PASS	N/A	N/A	N/A	
AF0011002	ASN Flash Card Spare w/ System Suite (9.0)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AF0011005	32MB DRAM SIMM kit, CPU Memory-Option.	PASS	12.1	N/A	N/A	
AF1204001	Multimode FDDI Net Module (previous ordernumber 34003)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1204002	Single Mode FDDI Net Module (previous ordernumber 34009)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1204003	Hybrid Single Mode/Multimode FDDI (Single Mode on PHY A/Multimode PHY B)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1204004	Hybrid Single Mode/Multimode FDDI (Single Mode on PHY B/Multimode PHY A)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1211001	Multimode FDDI Net Module Spare (previous ordernumber 34003-S)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1211002	Single Mode FDDI Net Module - Spare (previous ordernumber 34009S)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1211003	Hybrid Single Mode/Multimode FDDI (Single Mode on PHY A/Multimode PHY B)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF1211004	Hybrid Single Mode/Multimode FDDI (Single Mode on PHY B/Multimode PHY A)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104004	MCE1 Net Module for channelized E1 and ISDN PRI	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104006	Quad Sync Net Module (Factory Installed)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AF2104007	32-Contexts Hardware Compression co-processor Net Module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104010	MCE1 Net Module for channelized E1 and ISDN PRI Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104012	128-Contexts Hardware Compression co-processor Net Module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104013	128-Contexts Hardware Compression co-processor Net Module - Spare*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104015	32-Contexts Hardware Compression co-processor Net Module - Spare*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104016	Dual MCT1 Factory Installed (requires v 11.01 Software)*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2104020	Single HSSI Factory Installed (requires v 12.00 Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2111001	Dual MCT1 Field Upgrade (requires v 11.01 Software)*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2111005	Quad Sync Net Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AF2111006	Single HSSI Upgrade (requires v 12.00 Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG0002001	BCN Redundant Line Cord AC Base Unit - includes SRM-L, SRM-F and 4 Power Supplies**	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG0002003	BCN Redundant Line Cord AC Base Unit - includes SRM-L, SRM-F and 4 Power Supplies***	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG0008001	BN Version 9.0 System Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008002	BN Version 9.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008003	BN Version 9.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SMDS	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008004	BN Version 9.0 Corporate Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008005	BN Version 9.0 Corp Suite Additional Protocols - DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008006	BN Version 9.0 Corp Suite Additional Protocols - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0008007	BN Version 10.0 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008008	BN Version 10.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI*	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008009	BN Version 10.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS*	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008010	BN Version 10.0 Corporate Suite Includes all Version 10.0 software	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008012	BN Version 10.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008013	BN Version 10.0 8M WAN Suite*	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008014	BN Version 10.0 8M LAN Suite*	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008017	BN Version 11.0 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008017	BN Version 11.03 System Suite data Compression, TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw**	PASS	v11.03	N/A	N/A	
AG0008018	BN Version 11.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (8M PCMCIA)	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008018	BN Version 11.03 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI**	PASS	v11.03	N/A	N/A	
AG0008019	BN Version 11.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (8M PCMCIA)	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008019	BN Version 11.03 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS**	PASS	v11.03	N/A	N/A	
AG0008020	BN Version 11.0 Corporate Suite Includes all Version 10.0 software (8M PCMCIA)	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008020	BN Version 11.03 Corporate Suite Includes all Version 11.0 software	PASS	v11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG0008021	BN Version 11.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG0008021	BN Version 11.03 Corporate Suite Additional Protocols.*	PASS	v11.03	N/A	N/A	
AG0008022	BaySecure Firewall - 1 Agent License for Backbone Node Systems. Requires Version 11.02 or higher.	FAIL	v11.02	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008024	BN Version 12.0 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008025	BN Version 12.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (8M PCMCIA)	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008026	BN Version 12.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (8M PCMCIA)	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008027	BN Version 12.0 Corporate Suite Includes all Version 10.0 software (8M PCMCIA)	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008028	BN Version 12.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG0008029	BN Version 12.10 System Suite TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw	PASS	12.2	N/A	N/A	
AG0008030	BN Version 12.10 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (8M PCMCIA)	PASS	12.2	N/A	N/A	
AG0008031	BN Version 12.10 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (8M PCMCIA)	PASS	12.2	N/A	N/A	
AG0008032	BN Version 12.10 Corporate Suite Includes all Version 10.0 software (8M PCMCIA)	PASS	12.2	N/A	N/A	
AG0008033	BN Version 12.10 Corporate Suite Additional Protocols - CD-ROM	PASS	12.2	N/A	N/A	
AG0008034	BN Version 12.10 Corporate Suite Includes all Version 12.10 software (16M PCMCIA)	PASS	12.2	N/A	N/A	
AG0008035	BN Version 12.0 Corporate Suite Includes all Version 12.0 software (16M PCMCIA)	PASS	12.01	N/A	N/A	
AG0008042	BN Version 13.0 System Suite Data Compression (WCP/MSA), TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*	PASS	v13.0	N/A	N/A	
AG0008043	BN Version 13.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (8M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008044	BN Version 13.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (8M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008045	BN Version 13.0 Corporate Suite Includes all Version 13.0 software (8M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008046	BN Version 13.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (16M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008047	BN Version 13.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (16M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008048	BN Version 13.0 Corporate Suite Includes all Version 13.0 software (16M PCMCIA)	PASS	v13.0	N/A	N/A	
AG0008049	BN Version 13.0 Corporate Suite Additional Protocols - CD-ROM.	PASS	v13.0	N/A	N/A	
AG0008050	BN Version 13.10 System Suite Data Compression (WCP/MSA), TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw*.	PASS	v13.10	N/A	N/A	
AG0008051	BN Version 13.10 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* (8M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008052	BN Version 13.10 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (8M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008053	BN Version 13.10 Corporate Suite Includes all Version 1310 software (8M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008054	BN Version 13.10 Corporate Suite Includes all Version 13.10 software (16M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008055	BN Version 13.10 Corporate Suite Additional Protocols - CD-ROM.	PASS	v13.10	N/A	N/A	
AG0008056	DES - 56 IPSEC Option for BN System Software Version 13.10	PASS	v13.10	N/A	N/A	
AG0008057	BN Version 13.10 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI* 16M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008058	BN Version 13.10 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (16M PCMCIA).	PASS	v13.10	N/A	N/A	
AG0008061	BN Version 13.0 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI (32M PCMCIA). See Note 1.	PASS	N/A	N/A	N/A	
AG0008062	BN Version 13.0 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS (32M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AG0008063	BN Version 13.0 Corporate Suite Includes all Version 13.0 software (32M PCMCIA)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG0008064	BN Version 13.20 System Suite Data Compression (WCP/MSA), TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw (16M PCMCIA). (See Note 1)	PASS	N/A	N/A	N/A	
AG0008065	BN Version 13.20 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI (16M PCMCIA). (See Note 1)	PASS	N/A	N/A	N/A	
AG0008066	BN Version 13.20 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS (See Note 1) (16M PCMCIA).	PASS	N/A	N/A	N/A	
AG0008067	BN Version 13.20 Corporate Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS* (16M PCMCIA).	PASS	N/A	N/A	N/A	
AG0008068	BN Version 13.20 LAN Suite System Suite plus DECnet Phase IV, AppleTalk, OSI, VINES, IPX, ATM DXI (32M PCMCIA). (See Note 1)	PASS	N/A	N/A	N/A	
AG0008069	BN Version 13.20 WAN Suite System Suite plus ATM DXI, Frame Relay, LapB, X.25, SDMS (See Note 1) (32M PCMCIA).	PASS	N/A	N/A	N/A	
AG0008070	BN Version 13.20 Corporate Suite Includes all Version 13.20 software (32M PCMCIA).	PASS	N/A	N/A	N/A	
AG0008071	3DES - IPSEC Option for BN System Software Version 13.20	PASS	N/A	N/A	N/A	
AG0008072	BN Version 13.20 Corporate Suite Additional Protocols - CD-ROM.	PASS	N/A	N/A	N/A	
AG0008073	BN Version 13.0 System Suite Data Compression (WCP/MSA), TCP/IP, 802.1 Transparent Bridge, Source Route Bridge, Translation Bridge, SNMP Agent, Wellfleet HDLC Encapsulation, PPP, OSPF, EGP, BGP, DLSw (16M PCMCIA) See Note 1.	PASS	N/A	N/A	N/A	
AG0008075	BN Version 11.03 Upgrade Kit - CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
AG0008076	DES - 56 IPSEC Option for BN System Software Version 13.20, 13.10	PASS	N/A	N/A	N/A	
AG0011001	BN Flash Card Spare w/ System Suite (9.0)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0011002	8 MB Flash memory card spare	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG0011003	FRE2-060 Spare 64MB ***	PASS	11.03	N/A	N/A	
AG0011021	16M FRE2-060E with Advanced Compression Co-Processor spare for 128M Context****	PASS	N/A	N/A	N/A	
AG0011022	32M FRE2-060E with Advanced Compression Co-Processor spare for 128M Context****	PASS	N/A	N/A	N/A	
AG0011023	64M FRE2-060E with Advanced Compression Co-Processor spare for 128M Context****	PASS	N/A	N/A	N/A	
AG0011025	16M FRE2-060E with Advanced Compression Co-Processor spare for 256M Context****	PASS	N/A	N/A	N/A	
AG0011026	32M FRE2-060E with Advanced Compression Co-Processor spare for 256M Context****	PASS	N/A	N/A	N/A	
AG0011027	64M FRE2-060E with Advanced Compression Co-Processor spare for 256M Context****	PASS	N/A	N/A	N/A	
AG0011038	FRE4-PPC Spare 32 MB	PASS	N/A	N/A	N/A	
AG0011039	FRE4-PPC Spare 64 MB	PASS	N/A	N/A	N/A	
AG0011040	FRE4-PPC Spare 128 MB	PASS	N/A	N/A	N/A	
AG0011041	1000BASE-SX Spare	PASS	N/A	N/A	N/A	
AG0011042	1000BASE-LX Spare	PASS	N/A	N/A	N/A	
AG0011043	4-PORT 10/100BASE-TX SPARE	PASS	N/A	N/A	N/A	
AG0011044	4-PORT 100BASE-FX SPARE	PASS	N/A	N/A	N/A	
AG1004001	Quad Port Ethernet FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1004002	Quad Port Ethernet- High Speed Filters FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1004003	Quad Port Ethernet FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1004004	Quad Port Ethernet - High Speed Filters FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1004005	Dual 100BASE-T FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1004006	Quad Port Ethernet FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1004007	Quad Port Ethernet - High Speed Filters FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1004008	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1004009	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1004010	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1004011	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1004012	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1004013	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1004015	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060E 32MB ILI with Advanced Compression Co-Processor for 128M Context.	PASS	N/A	N/A	N/A	
AG1004016	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060E 64MB ILI with Advanced Compression Co-Processor for 128M Context.	PASS	N/A	N/A	N/A	
AG1004019	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060E 32MB ILI with Advanced Compression Co-Processor for 128M Context.	PASS	N/A	N/A	N/A	
AG1004020	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060E 64MB ILI with Advanced Compression Co-Processor for 128M Context.	PASS	N/A	N/A	N/A	
AG1004030	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060E 32MB ILI with Advanced Compression Co-Processor for 256M Context.	PASS	N/A	N/A	N/A	
AG1004031	Dual Ethernet/Dual Sync (ESAF) - No Filters FRE2-060E 64MB ILI with Advanced Compression Co-Processor for 256M Context.	PASS	N/A	N/A	N/A	
AG1004032	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060E 32MB ILI with Advanced Compression Co-Processor for 256M Context.	PASS	N/A	N/A	N/A	
AG1004033	Dual Ethernet/Dual Sync (ESAF) - Max. Filters FRE2-060E 64MB ILI with Advanced Compression Co-Processor for 256M Context.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG1104003	Quad Port Token Ring FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1104004	Quad Port Token Ring FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1104005	Dual Port Token Ring FRE2-060 64MB ILI**	PASS	11.03	N/A	N/A	
AG1104006	Quad Port Token Ring FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1104007	Token Ring and Dual Port Synchronous FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1104008	Dual Port Token Ring FRE2-060 32MB ILI**	PASS	11.03	N/A	N/A	
AG1104009	Token Ring and Dual Port Synchronous FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG1104010	Dual Port Token Ring FRE2-060 16MB ILI**	PASS	11.03	N/A	N/A	
AG1104011	Token Ring and Dual Port Synchronous FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG1204001	Multimode FDDI FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204002	Multimode FDDI - High Speed Filters FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204003	Single Mode FDDI FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204004	Single Mode FDDI - High Speed Filters FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204005	Hybrid Single Mode/Multimode FDDI (Single Mode on PHYA/Multimode on PHYB) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204006	Hybrid Single Mode/Multimode FDDI- High Speed Filters (Single mode on PHYA/Multimode on PHYB) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204007	Hybrid Multimode/Single Mode FDDI (Single Mode on PHYB/Multimode on PHYA) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1204008	Hybrid Multimode/Single Mode FDDI - High Speed Filters (Single Mode on PHYB/Multimode on PHYA) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG1301001	ATM Starter Kit includes; 72000 BLN Base unit, 74005-08 Quad Port Ethernet 8M ILI, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301002	ATM Starter Kit includes; 72000 BLN Base unit, 74005-08 Quad Port Ethernet 8M ILI, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301003	ATM Starter Kit includes; 71000 BLN-2 Base unit-Dual Power Supplies, 74005-08 Quad Port Ethernet 8M ILI, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301004	ATM Starter Kit includes; 71000 BLN-2 Base unit- Dual Power Supplies, 74005-08 Quad Port Ethernet 8M ILI, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301005	ATM Starter Kit includes; 72000 BLN Base unit, 74021-08 Quad Port Token Ring ILI 8M, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301006	ATM Starter Kit includes; 72000 BLN Base unit, 74021-08 Quad Port Token Ring ILI 8M, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301007	ATM Starter Kit includes; 71000 BLN-2 Base unit-Dual Power Supplies , 74021-08 Quad Port Token Ring ILI 8M, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V-081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301008	ATM Starter Kit includes; 71000 BLN-2 Base unit- Dual Power Supply, 74021-08 Quad Port Token Ring ILI 8M, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301009	ATM Starter Kit includes; 72000 BLN Base unit, 74011-08 Multimode FDDI, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301010	ATM Starter Kit includes; 72000 BLN Base unit, 74011-08 Multimode FDDI, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301011	ATM Starter Kit includes; 71000 BLN-2 Base unit-Dual Power Supplies , 74011-08 Multimode FDDI, 74023-16 ATM ILI - Sonet/SDH STS-3c MMF 16M FRE2, 41019V-081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1301012	ATM Starter Kit includes; 71000 BLN-2 Base unit- Dual Power Supply, 74011-08 MULTIMODE FDDI, 74024-16 ATM ILI - Sonet/SDH STS-3c SMF 16M FRE2, 41019V081 BN LAN Suite System Suite Software	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1304001	8MB/1MB ARE with STS-3/STM-1 MMF Link Module	PASS	11.03	N/A	N/A	
AG1304002	16MB/3MB ARE with STS-3/STM-1 MMF Link Module	PASS	11.03	N/A	N/A	
AG1304003	32MB/6MB ARE with STS-3/STM-1 MMF Link Module	PASS	11.03	N/A	N/A	
AG1304004	8MB/1MB ARE with STS-3/STM-1 SMF Link Module	PASS	11.03	N/A	N/A	
AG1304005	16MB/3MB ARE with STS-3/STM-1 SMF Link Module	PASS	11.03	N/A	N/A	
AG1304006	32MB/6MB ARE with STS-3/STM-1 SMF Link Module	PASS	11.03	N/A	N/A	
AG1304007	8MB/1MB ARE with DS-3 Link Module	PASS	11.03	N/A	N/A	
AG1304008	16MB/3MB ARE with DS-3 Link Module	PASS	11.03	N/A	N/A	
AG1304009	32MB/6MB ARE with DS-3 Link Module	PASS	11.03	N/A	N/A	
AG1304010	8MB/1MB ARE with E3 Link Module	PASS	11.03	N/A	N/A	
AG1304011	16MB/3MB ARE with E3 Link Module	PASS	11.03	N/A	N/A	
AG1304012	32MB/6MB ARE with E3 Link Module	PASS	11.03	N/A	N/A	
AG1304014	ARE 64MB/6MB Stand Alone BGP Soloist	PASS	11.03	N/A	N/A	
AG1304015	64M/6M ARE with STS-3/STM-1 SMF Link Module	PASS	N/A	N/A	N/A	
AG1304016	64M/6MB ARE with DS-3 Link Module	PASS	N/A	N/A	N/A	
AG1304020	64M/6M ARE with STS-3/STM-1 MMF Link Module	PASS	N/A	N/A	N/A	
AG1304021	64M/6MB ARE with E3 Link Module	PASS	N/A	N/A	N/A	
AG1308001	BN Version 9.0 ARE ATM Suite	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG1308002	BN Version 9.0 ARE VNR plus Corporate Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AG1308003	BN Version 10.0 ARE ATM Suite - ATM PVC RFC 1483, plus BN LAN Suite	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG1308004	BN Version 10.0 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483, plus BN LAN Suite	FAIL	v10.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG1308005	BN Version 11.0 ARE ATM Suite - ATM PVC RFC 1483, plus BN LAN Suite	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG1308005	BN Version 11.03 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite.	PASS	v11.03	N/A	N/A	
AG1308006	BN Version 11.0 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483, plus BN LAN Suite	FAIL	v11.0	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
AG1308006	BN Version 11.03 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483.	PASS	v11.03	N/A	N/A	
AG1308007	BN Version 12.0 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG1308008	BN Version 12.0 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AG1308009	BN Version 12.10 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite	PASS	12.2	N/A	N/A	
AG1308009	BN Version 12.20 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite.	PASS	v12.20	N/A	N/A	
AG1308010	BN Version 12.10 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483	PASS	12.2	N/A	N/A	
AG1308010	BN Version 12.20 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483.	PASS	v12.20	N/A	N/A	
AG1308011	BN Version 13.0 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite.	PASS	v13.0	N/A	N/A	
AG1308012	BN Version 13.0 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483.	PASS	v13.0	N/A	N/A	
AG1308013	BN Version 13.10 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite.	PASS	v13.10	N/A	N/A	
AG1308014	BN Version 13.10 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483.	PASS	v13.10	N/A	N/A	
AG1308015	BN Version 13.0 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite. (32M PCMCIA)	PASS	N/A	N/A	N/A	
AG1308016	BN Version 13.0 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483. (32M PCMCIA)	PASS	N/A	N/A	N/A	
AG1308017	BN Version 13.20 ARE ATM plus LAN Suite - ATM PVC RFC 1483, plus BN Corp Suite. (32M PCMCIA)	PASS	N/A	N/A	N/A	
AG1308018	BN Version 13.20 ARE VNR plus Corp Suite - ATM LANE, ATM SVC Signaling, ATM PVC RFC 1483. (32M PCMCIA)	PASS	N/A	N/A	N/A	
AG1311009	ARE Spare - 8MB/1MB	PASS	N/A	N/A	N/A	
AG1311010	ARE Spare - 16MB/3MB	PASS	N/A	N/A	N/A	
AG1311011	ARE Spare - 32MB/6MB	PASS	N/A	N/A	N/A	
AG1311012	ARE Link Module Spare - STS-3/STM-1 MMF	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG1311013	ARE Link Module Spare - STS-3/STM-1 SMF	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG1311014	E3 ARE Link Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG1311015	DS-3 ARE Link Module Spare	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2104001	Quad Port Multichannel T1 (QMCT1) -DB15 version FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104002	Quad Port Multichannel T1 (QMCT1) -DB15 version FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104003	Quad Port Multichannel T1 (QMCT1) -DB15 version FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104004	Quad Port Multichannel T1 (QMCT1) -DB15 version FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104009	Octal Port Synchronous FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG2104010	Octal Port Synchronous FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104013	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104014	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104015	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104016	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104017	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104018	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104019	75 ohm Single Port Multichannel E1 (MCE1-II) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104020	75 ohm Single Port Multichannel E1 (MCE1-II) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104021	75 ohm Single Port Multichannel E1 (MCE1-II) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104022	120 ohm Single Port Multichannel E1 (MCE1-II) FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104023	120 ohm Single Port Multichannel E1 (MCE1-II) FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104024	120 ohm Single Port Multichannel E1 (MCE1-II) FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104025	Octal Sync w/32 Contexts Hardware Compression FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG2104026	Octal Sync w/32 Contexts Hardware Compression FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
AG2104027	Octal Sync w/32 Contexts Hardware Compression FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104028	Octal Sync w/32 Contexts Hardware Compression FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG2104029	Octal Sync w/32 Contexts Hardware Compression FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104030	Octal Sync w/128 Contexts Hardware Compression FRE2-040 8MB ILI	PASS	11.03	N/A	N/A	
AG2104031	Octal Sync w/128 Contexts Hardware Compression FRE2-040 16MB ILI	PASS	11.03	N/A	N/A	
AG2104032	Octal Sync w/128 Contexts Hardware Compression FRE2-040 32MB ILI	PASS	11.03	N/A	N/A	
AG2104033	Octal Sync w/128 Contexts Hardware Compression FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG2104034	Octal Sync w/128 Contexts Hardware Compression FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104035	Quad Port Synchronous FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG2104036	Quad Port Synchronous FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104037	Octal Sync w/32 Contexts Hardware Compression Link Module	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2104038	Octal Sync w/128 Contexts Hardware Compression Link Module	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2104039	Single Port High Speed Serial Interface (HSSI) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104040	Octal Port Synchronous FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104041	Octal Sync w/32 Contexts Hardware Compression FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104042	Octal Sync w/128 Contexts Hardware Compression FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104043	Quad Port Synchronous FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104044	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104045	120 ohm Single Port Multichannel E1 (MCE1-II) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104046	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104047	75 ohm Single Port Multichannel E1 (MCE1-II) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104048	Single Port Multichannel T1 (MC-T1) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104049	Dual Port Multichannel T1 (MC-T1) FRE2-060 64MB ILI	PASS	11.03	N/A	N/A	
AG2104052	Quad Port Multichannel T1 with DS0A (QMCT1 w/DS0A) Link Module DB15*	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2104054	Quad Port Multichannel T1 with DS0A (QMCT1 w/DS0A) DB15 FRE2-040 32MB ILI *	PASS	11.03	N/A	N/A	
AG2104055	Quad Port Multichannel T1 with DS0A (QMCT1 w/DS0A) DB15 FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2104056	Quad Port Multichannel T1 with DS0A (QMCT1 w/DS0A) DB15 FRE2-060 64MB ILI *	PASS	11.03	N/A	N/A	
AG2104077	Quad Port Synchronous FRE2-060E 16MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104078	Quad Port Synchronous FRE2-060E 16MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104079	Quad Port Synchronous FRE2-060E 32MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104080	Quad Port Synchronous FRE2-060E 32MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104081	Quad Port Synchronous FRE2-060E 64MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104082	Quad Port Synchronous FRE2-060E 64MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104089	Octal Port Synchronous FRE2-060E 16MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104090	Octal Port Synchronous FRE2-060E 16MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104091	Octal Port Synchronous FRE2-060E 32MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104092	Octal Port Synchronous FRE2-060E 32MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104093	Octal Port Synchronous FRE2-060E 64MB ILI with Advanced Co-Processor with 128 Context	PASS	N/A	N/A	N/A	
AG2104094	Octal Port Synchronous FRE2-060E 64MB ILI with Advanced Co-Processor with 256 Context	PASS	N/A	N/A	N/A	
AG2104129	Dual Port Multichannel T1 (MC-T1) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 128 Context.	PASS	N/A	N/A	N/A	
AG2104130	Dual Port Multichannel T1 (MC-T1) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 256 Context.	PASS	N/A	N/A	N/A	
AG2104133	Quad Port Multichannel T1 (QMCT1) -DB15 FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 128 Context.	PASS	N/A	N/A	N/A	
AG2104134	Quad Port Multichannel T1 (QMCT1) -DB15 FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 256 Context.	PASS	N/A	N/A	N/A	
AG2104135	Quad Port Multichannel T1 (QMCT1) -DB15 FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 128 Context.	PASS	N/A	N/A	N/A	
AG2104136	Quad Port Multichannel T1 (QMCT1) -DB15 FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 256 Context.	PASS	N/A	N/A	N/A	
AG2104151	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 128 Context	PASS	N/A	N/A	N/A	
AG2104152	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 256 Context	PASS	N/A	N/A	N/A	
AG2104153	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 128 Context	PASS	N/A	N/A	N/A	
AG2104154	120 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 256 Context	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AG2104169	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 128 Context.	PASS	N/A	N/A	N/A	
AG2104170	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 32MB ILI with Advanced Co-Processor Compression with 256 Context.	PASS	N/A	N/A	N/A	
AG2104171	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 128 Context.	PASS	N/A	N/A	N/A	
AG2104172	75 ohm Dual Port Multichannel E1 (MCE1-II) FRE2-060E 64MB ILI with Advanced Co-Processor Compression with 256 Context.	PASS	N/A	N/A	N/A	
AG2111001	120 ohm Dual Port Multichannel E1 (MCE1-II) Link Module for 120 ohm ISDN PRI & 120 ohm leased line	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111002	120 ohm Single Port Multichannel E1 (MCE1-II) Link Module for 120 ohm ISDN PRI & 120 ohm leased line	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111003	75 ohm Dual Port Multichannel E1 (MCE1-II) Link Module for 75 ohm leased line	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111004	75 ohm Single Port Multichannel E1 (MCE1-II) Link Module for 75 ohm leased line	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111005	32 Contexts Hardware Compression Daughterboard	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111006	128 Contexts Hardware Compression Daughterboard	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2111007	Quad Port Multichannel T1 (QMCT1) Link Module DB15 version	PASS	11.03	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AG2204001	Dual 100BASE-T FRE2-060 16MB ILI	PASS	11.03	N/A	N/A	
AG2204002	Dual 100BASE-T FRE2-060 32MB ILI	PASS	11.03	N/A	N/A	
AG2204015	4-POR 10/100BASE-TX with FRE4-PPC 32MB	PASS	N/A	N/A	N/A	
AG2204016	4-POR 10/100BASE-TX with FRE4-PPC 64MB	PASS	N/A	N/A	N/A	
AG2204017	4-POR 10/100BASE-TX with FRE4-PPC 128MB	PASS	N/A	N/A	N/A	
AG2204018	4-POR 100BASE-FX with FRE4-PPC 32MB	PASS	N/A	N/A	N/A	
AG2204019	4-POR 100BASE-FX with FRE4-PPC 64MB	PASS	N/A	N/A	N/A	
AG2204020	4-POR 100BASE-FX with FRE4-PPC 128MB	PASS	N/A	N/A	N/A	
AG2204021	1000BASE-SX with FRE4-PPC 32MB	PASS	N/A	N/A	N/A	
AG2204022	1000BASE-SX with FRE4-PPC 64MB	PASS	N/A	N/A	N/A	
AG2204023	1000BASE-SX with FRE4-PPC 128MB	PASS	N/A	N/A	N/A	
AG2204024	1000BASE-LX with FRE4-PPC 32MB	PASS	N/A	N/A	N/A	
AG2204025	1000BASE-LX with FRE4-PPC 64MB	PASS	N/A	N/A	N/A	
AG2204026	1000BASE-LX with FRE4-PPC 128MB	PASS	N/A	N/A	N/A	
AH3214001	Optivity NMS 8.0. Requires HPOV 4.0, 4.1 or 5.0, for HP/UX 10 or Solaris 2.5, Tivoli TME NetView 4.1 for AIX 4.1 or 4.2 or SunNet Manager v2.2.3 or v2.2.2 for Solaris 2.5.	FAIL	v8.0	N/A	N/A	Upgrade to NMS 8.1.
AH3214001	Optivity NMS 8.0. Update 1 Requires HPOV 4.0, 4.1 or 5.0, for HP/UX 10 or Solaris 2.5, Tivoli TME NetView 4.1 for AIX 4.1 or 4.2 or SunNet Manager v2.2.3 or v2.2.2 for Solaris 2.5.	FAIL	v8.0	N/A	N/A	Upgrade to NMS 8.1. Upgrade to Analysis 8.0 and Planning 8.0.
AH3214001	Optivity NMS 8.1.1 For Solstice Domain Manager, HP OV NNM and TME 10 NetView for AIX. Includes Optivity LAN, Internetworking, Site Manager, Annex Manager. Requires one of the SNMP platforms listed.	PASS	v8.1.1	N/A	N/A	
AH3214002	Optivity Enterprise 8.0. Includes Optivity NMS 8.0. Optivity Analysis 7.2, and Optivity Planning 7.0.	FAIL	v8.0	N/A	N/A	Upgrade to NMS 8.1. Upgrade to Analysis 8.0 and Planning 8.0.
AH3214002	Optivity Enterprise 8.0.1 (Update 1) Includes Optivity NMS 8.0 Update 1, Optivity Analysis 8.0, and Optivity Planning 8.0.	FAIL	v8.0.1	N/A	N/A	Upgrade to NMS 8.1. Upgrade to Analysis 8.0 and Planning 8.0.
AH3214002	Optivity Enterprise 8.1.2 for HP OpenView NNM, TME 10 NetView for AIX and Sun Solstice Domain Manager. Includes Optivity NMS 8.1.1, Optivity NCS 2.0, Optivity Analysis 8.1 and Optivity Planning 8.0 Update #1.	PASS	v8.1.2	N/A	N/A	
AH3214002	Optivity Enterprise 8.2 for HP OpenView NNM, TME 10 NetView for AIX and Sun Solstice Domain Manager. Includes Optivity NMS 8.1.1, Optivity NCS 2.0, Optivity Analysis 8.1 and Optivity Planning 8.0 Update #1.	PASS	N/A	N/A	N/A	
AH3214003	Optivity Call Reporter version 1.0 for Unix. Includes Informix DB single user license. Requires HP-UX, Sun Solaris, or IBM/AIX (for use with 5399 and 8000 platforms only)	PASS	v1.0	N/A	N/A	
AH3214003	Optivity Call Reporter V1.1 for Unix. Includes Informix database single-user license. Requires one of the following Unix platforms: Sun Solaris, and IBM/AIX. (For use with 5399 and 8000 Platforms only).	PASS	v1.1	N/A	N/A	
AH3214003	Optivity Call Reporter V1.2 for Unix. Informix database single-user license. Requires one of the following Unix platforms: Sun Solaris or IBM/AIX. (For use with 5399 and 8000 Platforms ONLY).	PASS	v1.2	N/A	N/A	
AH3214006	Optivity NCS 2.0 - Includes NETarchitect 2.0 for Solaris, HP-UX, and IBM AIX, and NETconfigurator 2.0 for Solaris, HP-UX, IBM AIX, Windows/NT.	PASS	v2.0	N/A	N/A	
AH3214006-2.1	Optivity NCS 2.1 - Includes NETarchitect 2.1 for Solaris, HP-UX, and IBM AIX, and NETconfigurator 2.1 for Solaris, HP-UX, IBM AIX, Windows/NT.	PASS	N/A	N/A	N/A	
AH3214006-2.1	Optivity NCS 2.1 - Includes NETarchitect 2.1 for Solaris, HP-UX, and IBM AIX, and NETconfigurator 2.1 for Solaris, HP-UX, IBM AIX, Windows/NT.	PASS	N/A	N/A	N/A	
AH3214008	Optivity Enterprise 8.1.1 for HP OpenView NNM, TME 10 NetView for AIX and Sun Solstice Domain Manager. Includes Optivity NMS 8.1.1, Optivity NCS 2.0, Optivity Analysis 8.1 and Optivity Planning 8.0 Update #1.	PASS	v8.1.1	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AH3214009	Optivity Service Accounting (OSA) V1.0-Bundle. Includes OSA Basic AH3214022 with distributed support for up to 6 Flow Data Collectors. Runs on Solaris 2.5.1.	PASS	N/A	N/A	N/A	
AH3214012	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 10 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214012	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 10 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214012	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 10 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214014	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 100 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214014	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 100 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214014	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 100 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214015	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 500 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214015	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 500 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214015	Provides centralized configuration management for Contivity Extranet Switch (CES) based VPN services. Licensed up to 500 CES. Requires Optivity Network Configuration System 2.0. Supported platforms: NT 4.0, Solaris 2.5.1, HP-UX 10.2, and AIX 4.2	PASS	N/A	N/A	N/A	
AH3214016-9.0	Optivity NMS 9.0 for Solaris. Includes support for HP Network Node Mgr (Solaris only), Solstice Domain Mgr, and Tivoli Netview (Solaris only). Also includes Optivity NMS 9.0 Client for Microsoft NT and Windows '95/98.	PASS	N/A	N/A	N/A	
AH3214022	Optivity Service Accounting (OSA) V1.0-Basic. Includes standalone support for single workstation install only. Includes 1 Flow Data Collector. Runs on Solaris 2.5.1.	PASS	N/A	N/A	N/A	
AH3214023	Optivity Service Accounting (OSA) V1.0- FDC Add-on. Includes support for adding 1 additional Flow Data Collector to an OSA Basic installation. Runs on Solaris 2.5.1. Requires AH3214022 (OSA Basic).	PASS	N/A	N/A	N/A	
AH3214024	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214012 - Optivity VPN Manager for Contivity 1.0 license for 10 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0 (See Note 2)	PASS	N/A	N/A	N/A	
AH3214024	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214012 - Optivity VPN Manager for Contivity 1.0 license for 10 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0 (See Note 2)	PASS	N/A	N/A	N/A	
AH3214024	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214012 - Optivity VPN Manager for Contivity 1.0 license for 10 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0 (See Note 2)	PASS	N/A	N/A	N/A	
AH3214025	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214014 - Optivity VPN Manager for Contivity 1.0 license for 100 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	
AH3214025	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214014 - Optivity VPN Manager for Contivity 1.0 license for 100 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	
AH3214025	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214014 - Optivity VPN Manager for Contivity 1.0 license for 100 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	
AH3214026	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214015 - Optivity VPN Manager for Contivity 1.0 license for 500 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AH3214026	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214015 - Optivity VPN Manager for Contivity 1.0 license for 500 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	
AH3214026	Optivity VPN Manager 1.0 for Contivity Extranet Switch with Optivity NCS 2.0 bundle. This package includes AH3214015 - Optivity VPN Manager for Contivity 1.0 license for 500 Contivity Extranet Switches and AH3214006 - Optivity NCS 2.0	PASS	N/A	N/A	N/A	
AH3313001	Optivity Analysis for Windows NT. RMON 2 traffic analysis software, works with Windows 95 or Windows NT	FAIL	v1.0	N/A	N/A	Upgrade to Analysis for Windows NT v1.1
AH3313002	Optivity Campus/Analysis bundle, requires Windows 95 or Windows NT	FAIL	v6.x	N/A	N/A	Upgrade to Campus 7.0 and Analysis for Windows NT v1.1.
AH3313002	Optivity Campus 7.0.1/Analysis 1.1 bundle, requires Windows/95 or Windows/NT	PASS	N/A	N/A	N/A	
AH3313004	Optivity Workgroup version 4.0. Includes EZ-Lan and EZ-Internetwork.	PASS	v4.0	N/A	N/A	
AH3313004	Optivity Workgroup version 4.0.1. Includes EZ-Lan and EZ-Internetwork.	PASS	N/A	N/A	N/A	
AH3313005	Optivity Service Level Help 1.0 Real time end-to-end application service level management help desk software. Manages up to 100 nodes (desktops).	PASS	v1.0	N/A	N/A	
AH3313006	Optivity Service Level Help 300 Node Upgrade Real time end-to-end application service level management help desk software. Manages up to 300 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313006-2.1	Optivity Service Level Help (SLH) 300 User License option allows deployment of up to 300 VitalAgents for Optivity. Optivity SLH server software is included with this user license option. For larger deployments, please contact your local sales representative. This product replaces Order #'s AH3313005 and AH3313006.	PASS	N/A	N/A	N/A	
AH3313007	Optivity Service Level Help 500 Node Upgrade Real time end-to-end application service level management help desk software. Manages up to 500 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313007-2.1	Optivity Service Level Help (SLH) 500 User License option allows deployment of up to 500 VitalAgents for Optivity. Optivity SLH server software is included with this user license option. This product replaces Order #'s AH3313005 and AH3313007.	PASS	N/A	N/A	N/A	
AH3313008	Optivity Service Level Help 1000 Node Upgrade Real time end-to-end application service level management help desk software. Manages up to 1000 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313008-2.1	Optivity Service Level Help (SLH) 1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLH server software is included with this user license option. This product replaces Order #AH3313005 and AH3313008.	PASS	N/A	N/A	N/A	
AH3313008-2.1.2	Optivity Service Level Help (SLH) 1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLH server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313010	Optivity Service Level Analysis 1.0. Historical end-to-end application service level management analysis software. Manages up to 100 nodes (desktops).	PASS	v1.0	N/A	N/A	
AH3313011	Optivity Service Level Analysis 300 Node Upgrade. Historical end-to-end application service level management analysis software. Manages up to 300 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313011-2.1	Optivity Service Level Analysis (SLA) 300 User License option allows deployment of up to 300 VitalAgents for Optivity. Optivity SLA server software is included with this user license option. This replaces Order #'s AH3313010 and AH3313011.	PASS	N/A	N/A	N/A	
AH3313011-2.1.2	Optivity Service Level Analysis (SLA) 300 User License option allows deployment of up to 300 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313012	Optivity Service Level Analysis 500 Node Upgrade. Historical end-to-end application service level management analysis software. Manages up to 500 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313012-2.1	Optivity Service Level Analysis (SLA)500 User License option allows deployment of up to 500 VitalAgents for Optivity. Optivity SLA server software is included with this user license option. This Product replaces Order #'s AH3313010 and AH3313012-1.0.	PASS	N/A	N/A	N/A	
AH3313012-2.1.2	Optivity Service Level Analysis (SLA)500 User License option allows deployment of up to 500 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313013	Optivity Service Level Analysis 1000 Node Upgrade. Historical end-to-end application service level management analysis software. Manages up to 1000 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313013-2.1	Optivity Service Level Analysis (SLA) 1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLA server software is included with this user license option. This product replaces Order #'s AH3313010 and AH3313013-1.0.	PASS	N/A	N/A	N/A	
AH3313013-2.1.2	Optivity Service Level Analysis (SLA) 1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AH3313015	Optivity Service Level Management 1.0. This is a bundle of Optivity SL Help and SL Analysis. Enables end-to-end application service level management analysis and help desk software. Manages up to 100 nodes(desktops).	PASS	v1.0	N/A	N/A	
AH3313016	Optivity Service Level Management 300 Node Upgrade. This is a bundle of Optivity SL Help and SL Analysis. Enables end-to-end application service level management historical analysis and help desk software. Manages up to 300 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313016-2.1	Optivity Service Level Management (SLM) 300 User License option allows deployment of up to 300 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option. This product replaces Order #s AH3313015-1.0 and AH3313016.	PASS	N/A	N/A	N/A	
AH3313016-2.1.2	Optivity Service Level Management(SLM) 300 User License option allows deployment of up to 300 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313017	Optivity Service Level Management 500 Node Upgrade. This is a bundle of Optivity SL Help and SL Analysis. Enables end-to-end application service level management historical analysis and help desk software. Manages up to 500 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313017-2.1	Optivity Service Level Management (SLM) 500 User License option allows deployment of up to 500 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option. This product replaces Order #s AH3313015-1.0 and AH3313017-1.0.	PASS	N/A	N/A	N/A	
AH3313017-2.1.2	Optivity Service Level Management (SLM) 500 User License option allows deployment of up to 500 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313018	Optivity Service Level Management 1000 Node Upgrade. This is a bundle of Optivity SL Help and SL Analysis. Enables end-to-end application service level management historical analysis and help desk software. Manages up to 1000 nodes (desktops).	PASS	N/A	N/A	N/A	
AH3313018-2.1	Optivity Service Level Management(SLM)1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option. This product replaces Order #s AH3313015-1.0 and AH3313018-1.0.	PASS	N/A	N/A	N/A	
AH3313018-2.1.2	Optivity Service Level Management(SLM)1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313018-2.1.2	Optivity Service Level Management(SLM)1000 User License option allows deployment of up to 1000 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313023-2.1	Optivity Service Level Management (SLM) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server s/w are incl. with this user license option. (See Note 1)	PASS	N/A	N/A	N/A	
AH3313023-2.1.2	Optivity Service Level Management (SLM) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313024-2.1	Optivity Service Level Analysis (SLA) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity SLA server software is included with this user license option. (See Note 2)	PASS	N/A	N/A	N/A	
AH3313024-2.1.2	Optivity Service Level Analysis (SLA) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313025-2.1	Optivity Service Level Help (SLH) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity SLH server software is included with this user license option. (See Note 3)	PASS	N/A	N/A	N/A	
AH3313025-2.1.2	Optivity Service Level Help (SLH) 5000 User License option allows deployment of up to 5000 VitalAgents for Optivity. Optivity SLH server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313027-2.1	Optivity Service Level Management (SLM) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313027-2.1.2	Optivity Service Level Management (SLM) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	
AH3313028-2.1	Optivity Service Level Management (SLM) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity Service Level Help (SLH) and Service Level Analysis (SLA) server software are included with this user license option. For larger deployments, please contact your local sales representative.	PASS	N/A	N/A	N/A	
AH3313028-2.1.2	Optivity Service Level Management (SLM) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity SLH and SLA server s/w are included with this user license option.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AH3313029-2.1	Optivity Service Level Help (SLH) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity SLH server software is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313029-2.1.2	Optivity Service Level Help (SLH) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity SLH server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313030-2.1	Optivity Service Level Analysis (SLA) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity SLA server software is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313030-2.1.2	Optivity Service Level Analysis (SLA) 2000 User License option allows deployment of up to 2000 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313031-2.1	Optivity Service Level Help (SLH) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity SLH server software is included with this user license option. For larger deployments, please contact your local sales representative.	PASS	N/A	N/A	N/A	
AH3313031-2.1.2	Optivity Service Level Help (SLH) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity SLH server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313032-2.1	Optivity Service Level Analysis (SLA) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity SLA server software is included with this user license option. For larger deployments, please contact your local sales representative.	PASS	N/A	N/A	N/A	
AH3313032-2.1.2	Optivity Service Level Analysis (SLA) 3000 User License option allows deployment of up to 3000 VitalAgents for Optivity. Optivity SLA server s/w is included with this user license option.	PASS	N/A	N/A	N/A	
AH3313033-9.0	Optivity NMS 9.0 for Microsoft Windows NT. Includes support for HP Network Node Manager (NT version) and Tivoli TME 10 Netview (NT Version). Also includes Optivity NMS 9.0 Windows '95/98 Client software.	PASS	N/A	N/A	N/A	
AH3313034-9.0	Upgrade from Optivity Campus to Optivity NMS 9.0 for NT. Requires previous purchase of Optivity Campus.	PASS	N/A	N/A	N/A	
AH3313039-1.0	Optivity Policy Services (OPS) S/W V1.0, to manage up to 2500 IP addresses & 100 interfaces on NT or Solaris. Allows multiple DNS, DHCP, Policy, application servers and administrators; extend by adding address or device licenses.(See Note 1).	PASS	N/A	N/A	N/A	
AH3313042-1.0	Optivity Policy Services (OPS) V 1.0 , Printed Document Set.	PASS	N/A	N/A	N/A	
AH3313043-1.0	License only, Optivity Policy Services (OPS) V1.0 2500 IP address license upgrade.	PASS	N/A	N/A	N/A	
AH3313044-1.0	License only, Optivity Policy Services (OPS) V1.0 5000 IP address license upgrade.	PASS	N/A	N/A	N/A	
AH3313045-1.0	License only, Optivity Policy Services (OPS) V1.0 25000 IP address license upgrade.	PASS	N/A	N/A	N/A	
AH3313046-1.0	Software, license only, Optivity Policy Services (OPS) V1.0 250 policy device interface license upgrade.	PASS	N/A	N/A	N/A	
AH3313047-1.0	Software, license only, Optivity Policy Services (OPS) V1.0 500 policy device interface license upgrade.	PASS	N/A	N/A	N/A	
AH3313048-1.0	Software, license only, Optivity Policy Services (OPS) V1.0 2500 policy device interface license upgrade.	PASS	N/A	N/A	N/A	
AH3313049-1.0	Software, license for each additional concurrent user for Optivity Policy Services (OPS) V1.0 runtime database for Windows NT.	PASS	N/A	N/A	N/A	
AH3313050-1.0	Software, Optivity Policy Services (OPS) V1.0 Runtime Database for Solaris (Workgroup). Oracle 8 Workgroup Server for Solaris licensed for 5 concurrent users.	PASS	N/A	N/A	N/A	
AH3313051-1.0	Software, license for each additional concurrent user for Optivity Policy Services (OPS) V1.0 runtime database for Solaris Workgroup.	PASS	N/A	N/A	N/A	
AH3313052-1.0	Software, Optivity Policy Services (OPS) V1.0 Runtime Database for Solaris (Enterprise). Oracle 8 Enterprise Server for Solaris licensed for 5 concurrent users.	PASS	N/A	N/A	N/A	
AH3313053-1.0	Software, license for each additional concurrent user for Optivity Policy Services (OPS) V1.0 runtime database for Solaris Enterprise.	PASS	N/A	N/A	N/A	
AH3313054-3.0	Optivity Service Level Management (SLM) Base: incl. server s/w for Service Level Help and Service Level Analysis. Optivity SLM Base must be purchased in conjunction with a User License Option.	PASS	N/A	N/A	N/A	
AH3313055-3.0	Optivity Service Level Management 100 User License Option allows deployment of up to 100 agents. Server s/w is NOT incl. Upgrades are available in the listed User License Option increments only.	PASS	N/A	N/A	N/A	
AH3313056-3.0	Optivity Service Level Management 250 User License Option allows deployment of up to 250 agents. Server s/w is NOT included. (Upgrades are available in the listed User License Option increments only).	PASS	N/A	N/A	N/A	
AH3313057-3.0	Optivity Service Level Management 500 User License Option allows deployment of up to 500 agents. Server s/w is NOT included. (Upgrades are available in the listed User License Option increments only).	PASS	N/A	N/A	N/A	
AH3313060-3.0	Optivity Service Level Management 1000 User License Option allows deployment of up to 1000 agents. Server s/w is NOT included. (Upgrades are available in the listed User License Option increments only).	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AH3313061-3.0	Optivity Service Level Management 2500 User License Option allows deployment of up to 2500 agents. Server s/w is NOT included. (Upgrades are available in the listed User License Option increments only).	PASS	N/A	N/A	N/A	
AH3313062-3.0	Optivity Service Level Management 5000 User License Option allows deployment of up to 5000 agents. Server s/w is NOT included. (Upgrades are available in the listed User License Option increments only).	PASS	N/A	N/A	N/A	
AH3334001	Quick2Config Version 1.2 Windows graphical router configuration utility for AN, ANH, and ASN Routers. Requires Windows 95	FAIL	1.2	N/A	N/A	Upgrade to Quick2Config 1.3a release available by 1/1/98, to be Year2000 compliant.
AH3334001	Quick2Config Version 1.3 Windows graphical router configuration utility for AN, ANH, and ASN Routers. Requires Windows 95	FAIL	1.3	N/A	N/A	Upgrade to Quick2Config 1.3.2.
AK3401001	Model 10625 Multimedia Switch. Base unit contains 8 x 25Mb/s ATM ports, 2 x 155Mb/s ATM ports, 1 x Ethernet port, 1 x console port and SNMP agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3401002	4 port 25Mb/s ATM MDA for the Multimedia Switch. Expands the number of 25Mb/s ATM ports on a Model 10625 Multimedia switch.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3401003	Model 10626 Multimedia Switch. Base unit containing 20x 25Mb/s ATM ports, 2x155Mb/s ATM ports, 1x Ethernet port, 1x console port, SNMP agent and Rate Pacing Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3401004	Model 10626 Multimedia Switch. Base unit containing 16x 25Mb/s ATM ports, 2x155Mb/s ATM ports, 2x Token Ring port, 1x console port, SNMP agent.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3401005	2 Port V.35 Module For 10625 Switch	PASS	N/A	N/A	N/A	
AK3401006	2-ports 155 Mb/s ATM Module, with two fiber connectios: one Single-mode [SM] and one Multi-mode [MM]	PASS	N/A	N/A	N/A	
AK3401016	2U Switch, with a single High Speed Serial Module(V.35 Mod) and a single 4x25Mb/s module	PASS	N/A	N/A	N/A	
AK3401017	VSM-3 V-Ether Switching Module for the Multi-Media workgroup switch. Includes (6) RJ45 10BaseT ports.	PASS	N/A	N/A	N/A	
AK3401018	VSM-11 SM/MM OC-3 Telco Module for the Multimedia Switch.	PASS	N/A	N/A	N/A	
AK3401019	VSM-8 V-Ether Switching Module for the Multi-Media workgroup switch. Includes (6) RJ45 10BaseT ports.	PASS	N/A	N/A	N/A	
AK3401020	Model 10625 Multimedia Ethernet Switch. Base unit contains 12 x 10BaseT Ethernet ports, 1 x Ethernet port, 1 x console port, diagnostics cable, SNMP agent.	PASS	N/A	N/A	N/A	
AK3401021	Model 10625 Multimedia Switch. Base unit contains 12 x 25Mb/s ATM ports, 2 x 155Mb/s ATM ports, 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401022	Model 10626 Multimedia Switch. Base unit containing 30 x 25Mb/s ATM ports, 2x155Mb/s ATM ports, 1x Ethernet port, 1x console port, diagnostics cable, and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401023	VSW-2002SM Model 10626 Multimedia Switch. Base unit containing 8 x 25Mb/s ATM ports, 2 x 155Mb/s Single Mode ATM ports, 1x Ethernet port, 1x console port, diagnostics cable, and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401024	Workgroup Video Switch. Includes (4) 25 Mbps ATM ports, (2) High speed serial ports, (1) Ethernet port, 1 x console port, diagnostics cable and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401024	Workgroup Video Switch. Includes (6) 25 Mbps ATM ports, (2) High speed serial ports, (1) Ethernet port, 1 x console port, diagnostics cable and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401025	VSM-9 (6) port 25Mb/s ATM MDA for the Multimedia Switch. Expands the number of 25Mb/s ATM ports on a Model 10625 Multimedia switch.	PASS	N/A	N/A	N/A	
AK3401026	Model 10625 Multimedia Switch. Base unit includes 4 x T1 IMA ports, 4 x 25 Mbps ATM Ports, 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP agent.	PASS	N/A	N/A	N/A	
AK3401027	Access Switch Includes 1 x DS-3, 2 x 155Mb/s ATM ports, 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP agent and IPR-1000 routing software.	PASS	N/A	N/A	N/A	
AK3401028	Access Switch Includes 4 x T1 IMA ports, 6 x 25 Mbps ATM ports, 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP agent and IPR-1000 routing software.	PASS	N/A	N/A	N/A	
AK3401029	VSM-4 (2) Port 155Mb/s ATM Module with two Single-mode [SM] ports.	PASS	N/A	N/A	N/A	
AK3401030	VSM-12 (2) port 155Mb/s ATM WAN Fiber MM Module.	PASS	N/A	N/A	N/A	
AK3401031	VSM-15 (1) port DS-3 MDA.	PASS	N/A	N/A	N/A	
AK3401032	VSM-16 (1) port E-3 MDA.	PASS	N/A	N/A	N/A	
AK3401033	VSM-17 (1) port Digital PBX MDA.	PASS	N/A	N/A	N/A	
AK3401034	VSM-18 (4) port Analog phone access Module.	PASS	N/A	N/A	N/A	
AK3401035	VSM-19 (1) port Analog PBX Attachment MDA.	PASS	N/A	N/A	N/A	
AK3401036	VSM-21 (4) port T-1 IMA MDA with integrated CSU.	PASS	N/A	N/A	N/A	
AK3401037	VSM-22 (1) port ATM DXI Module.	PASS	N/A	N/A	N/A	
AK3401038	Model 10625 Multimedia Switch. Includes 4 x 25 Mbps ATM ports, 2 x High Speed Serial (T1), 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP.	PASS	N/A	N/A	N/A	
AK3401039	Model 10625 Multimedia Switch. Includes 4 x 25 Mbps ATM ports, 1 x DS-3, 1 x Ethernet port, 1 x console port, diagnostics cable and SNMP agent.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AK3402001	VSW-2999 2U Switch chassis (empty). Can be populated with up to 3 modules from the Switch Add-in Modules section. Includes rack mounting brackets and SNMP license.	PASS	N/A	N/A	N/A	
AK3402002	VSW-1999 1U Switch chassis (empty). Can be populated with up to 3 modules from the Switch Add-in Modules section.	PASS	N/A	N/A	N/A	
AK3409001	MultiMedia/ATM Demo System: Includes: 8 port MultiMedia Switch, 2 user MOS, 1 hr MPEG Media Storage Server, 2 25Mbps ATM adapters, MPEG Decodes, 100Mhz Pentium PC, PictureTel PS50s w/ SpeakerPhone & VAFC Graphics Card.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409002	VCH-0300 ATM-attached Video Cache (3 Hrs of MPEG1/5 Streams)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409004	VCH-5020 ATM-attached Video Cache 20 Hours (16GB Gross, 12GB in RAID-5 format)/25 Streams	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409005	VCH-5050 ATM-attached Video Cache 50 Hours (32GB Gross, 28GB in RAID-5)/25 Streams	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409006	VCH-5100 ATM-attached Video Cache 100 Hours (72GB Gross, 63GB in RAID-5)/50 Streams	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409007	VCA-1000 V-Caster MPEG-1 Video Broadcast Station (Requires V-TV or MOS 4.x)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409008	VGS-2000 Quad-BRI Gateway Complete System	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409009	VGS-3000 PRI/T1 Gateway Complete System	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409010	VGS-3010 PRI/E1 Gateway Complete System	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409011	VGS-5000 Gateway Base Chassis, MOS, and Gateway software	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409012	VGS-5001 25Mbps GW ATM Interface card with MVIP Connections for the VGS-5000 Gateway Base Chassis	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409013	VGS-5004 Quad-BRI Interface for the VGS-5000 Gateway Base Chassis	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409014	VGS-5005 PRI/T1 Interface for the VGS-5000 Gateway Base Chassis	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409015	VGS-5006 PRI/E1 Interface for the VGS-5000 Gateway Base Chassis	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3409023	VCA-4000 MPEG-2 Single Channel V-Caster (1/2 D1)	PASS	N/A	N/A	N/A	
AK3409024	Video Manager. Easy-to-use NT server-based software product that provides the interface and management for the V-Cache or V-Caster video streaming modules.	PASS	N/A	N/A	N/A	
AK3409025	VLS-1000 Video Locator Service (VLS). Graphical interface which allows videoconferencing users to place and manage calls easily.	PASS	N/A	N/A	N/A	
AK3409026	VGS-0323X H.323 - H.320 Gateway includes PRI and ATM interface and DSP processor.	PASS	N/A	N/A	N/A	
AK3409027	VGS-0323B H.323 - H.320 Gateway includes Quad BRI, ATM interface, and DSP processor.	PASS	N/A	N/A	N/A	
AK3409028	Complete I-Studio 100 with 10/100 Ethernet Interface and 6GB Hard Disk.	PASS	N/A	N/A	N/A	
AK3409029	Complete I-Studio 100 with Gigabit Ethernet Interface and 6GB Hard Disk.	PASS	N/A	N/A	N/A	
AK3409030	VCH-70200 ATM-attached Video Cache 200 Hours (144GB Gross, 126 GB in RAID-5)/70 Streams - Includes ATM-SCSI Controller and MOS 75 User License.	PASS	N/A	N/A	N/A	
AK3409031	VCH-70100 ATM-attached Video Cache 100 Hours (72GB Gross, 63GB in RAID 5)/70 Streams - Includes ATM-SCSI Controller and MOS 75 User License.	PASS	N/A	N/A	N/A	
AK3409032	VCH-7050 ATM-attached Video Cache 50 Hours (32GB Gross, 28GB in RAID 5)/70 Streams - Includes ATM-SCSI Controller and MOS 75 User License.	PASS	N/A	N/A	N/A	
AK3409033	VGS-4001-10 H.320 - H.321 Gateway with 1 x ATM25 and Quad-BRI.	PASS	N/A	N/A	N/A	
AK3409034	VGS-4100-10 H.320 - H.321 Gateway with 1 x ATM25 and PRI/T1.	PASS	N/A	N/A	N/A	
AK3409035	VGS-4010-10 H.320 - H.321 Gateway with 1 x ATM25 and PRI/E1.	PASS	N/A	N/A	N/A	
AK3416006-15.03	IP Routing Software	PASS	N/A	N/A	N/A	
AK3416007-1.0	ACSW-VPR Voice Software License (Required for each switch with voice modules)	PASS	N/A	N/A	N/A	
AK3418007	VSM-22 V.35 Adapter Cable.	PASS	N/A	N/A	N/A	
AK3419001	25Mbps ATM Adapter card for PCI BUS PC's. Supports LANE, MOS, ODI and NDIS. Supports client M OS software in Windows, Novell and Microsoft NT environments.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3419002	25Mbps ATM Adapter card for ISA BUS PC's. Supports LANE, MOS, ODI and NDIS. Supports client MOS software in Windows, Novell and Microsoft NT environments.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3419004	VAM-4000 ISA 25Mb/s ATM NIC with onboard MVIP and rate shaping, MOS-1, CODEC Software, and MVIP cable for PictureTel 50, 100, 200; Zyadacron On-Wan Z-240, Nortel Multimedia conferencing and VCON Armada Cruiser 100 & 150.	PASS	N/A	N/A	N/A	
AK3433001	VAM-1000 Add-on H/W and S/W for Direct Connection to PicTel PCS100	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AK3433002	VAM-1500 Add-on H/W and S/W for Direct Connection to PicTel PCS50	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3433003	VSA-5000 25Mbps ATM Adapter and Additional Add-on H/W and S/W for Direct Connection to PictureTel Venue 2000 Room System	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AK3433013	BVS-0003 Zydacron OnWan Enterprise bundle with Zydacron 240+ Codec & std camera. Also includes FVC ATM NIC, MVIP + Real Magic card, and MOS license.	PASS	N/A	N/A	N/A	
AK3433014	BVS-0004 Zydacron OnWan Enterprise bundle with Zydacron 240+ Codec & enhanced camera. Also includes FVC ATM NIC, MVIP + Real Magic card, and MOS license.	PASS	N/A	N/A	N/A	
AK3433015	VAN-8400-V25 H.310 ATM Encoder/Decoder Base unit with 25Mb/s ATM interface.	PASS	N/A	N/A	N/A	
AK3433016	VAN-8400-V155 H.310 ATM Encoder/Decoder Base unit with 155Mb/s ATM interface.	PASS	N/A	N/A	N/A	
AK3433017	VAN-8401-12S-V155 H.310 ATM Encoder/2 Decoder Base unit with 155Mb/s ATM interface.	PASS	N/A	N/A	N/A	
AK3433018	Zydacron OnWan Enterprise MPEG-2 Bundle with Zydacron 240+ Codec & enhanced camera. Also includes FVC ATM NIC and MVIP + Realmajic Netstream MPEG-2 Codec.	PASS	N/A	N/A	N/A	
AK3433019	VAN-8400-VCC25-U VaN Videoconferencing Complete Package with 25 Mbit/sec ATM Interface (110V, NTSC) and no Monitor. Includes Encoder/Decoder, Echo Cancellation System, software, cart, enhanced camera, scan converter, microphone and cabling.	PASS	N/A	N/A	N/A	
AK3433020	VAN-8401-22-V25 H.310 ATM 2 Encoder/2 Decoder Base unit with 25Mb/s ATM interface.	PASS	N/A	N/A	N/A	
AK3433021	VAN-8401-13-V155 VaN super base with 1 Encoder, 3 Decoders with 155Mb/s ATM interface.	PASS	N/A	N/A	N/A	
AK3433023	VAN-8401-22-V155 VaN super base unit (7 slot) with 2x Encoder, 2x Decoder, ATM 155 MMF	PASS	N/A	N/A	N/A	
AL1901001	BayStack Ethernet Workgroup Switch with six 10BASE-T switched ports	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AL1912A01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (No power cord included)	PASS	N/A	N/A	N/A	
AL1912B01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
AL1912C01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (Includes power cord commonly used in the United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
AL1912D01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (Includes power cord commonly used in Japan)	PASS	N/A	N/A	N/A	
AL1912E01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL1912F01	BayStack 310-24T Switch (24 10 BaseT ports plus 1 10/100BaseTX port and 2 MDA slots) (Includes Australian power cord, also commonly used in New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	
AL2001704	BayStack 303 Ethernet Switch with 24 switched 10BASE-T ports, 1 switched 100BASE-TX port, and 1 optional 100BASE-TX/FX MDA slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2001705	BayStack 304 Ethernet Switch with 12 switched 10BASE-T ports, 1 switched 100BASE-TX port, and 1 optional 100BASE-TX/FX MDA slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2001001	BayStack Ethernet Workgroup Switch with six 10BASE-T switched ports and one 100BASE-T switchport (requires Media Adapter).	PASS	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AL2001002	BayStack 302T Ethernet Switch with 8 switched 10BASE-T ports and 1 100BASE-TX port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2001003	BayStack 302F Ethernet Switch with 8 switched 10BASE-T ports and 1 100BASE-FX port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2001A06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001A07	BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001A09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001A12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001A13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001A14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (No power cord included)	PASS	N/A	N/A	N/A	
AL2001B06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AL2001B07	BayStack 70-16T (16 10/100BaseTX) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AL2001B09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AL2001B12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AL2001B13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AL2001B14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AL2001C06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001C07	BayStack 70-16T (16 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001C09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001C12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001C13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001C14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2001D06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001D07	BayStack 70-16T (16 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001D09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001D12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001D13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001D14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2001E06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001E07	BayStack 70-16T (16 10/100BaseTX) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001E09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001E12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001E13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001E14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2001F06	BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2001F07	BayStack 70-16T (16 10/100BaseTX) unmanaged Ethernet switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2001F09	BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2001F12	5-PAK of BayStack 70-8T 10/100 autosense (8 10/100BaseTX) unmanaged Ethernet switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2001F13	5-PAK of BayStack 70-16T 10/100 autosense (16 10/100BaseTX) unmanaged Ethernet switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2001F14	5-PAK of BayStack 70-24T (24 10/100 autosense rack mount) unmanaged Ethernet switch.	PASS	N/A	N/A	N/A	
AL2012?01	BayStack Model 350T 10/100 Autosense Switch; 10/100BaseTX on all 16 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2012?02	BayStack 350F 10/100 autosense (12 10/100BaseTX Plus 2 100BaseFX) Ethernet switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2012?08	BayStack 350F-HD 10/100 autosense (24 10/100BaseTX Plus 2 100BaseFX) Ethernet switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2012?10	BayStack 350T-HD Autosense (24 10/100BaseTX) Ethernet switch	PASS	N/A	N/A	N/A	
AL2012?14	BayStack 450-24T Switch (24 10/100BaseTX plus 1 MDA slot and 1 Cascade Slot).	PASS	N/A	N/A	N/A	
AL2012?15	BayStack 450-12T Switch (12 10/100BaseTX plus 1 MDA slot and 1 Cascade Slot).	PASS	N/A	N/A	N/A	
AL2012?17	BayStack 350-24T Switch (24 10/100BaseTX plus 1 MDA slot).	PASS	N/A	N/A	N/A	
AL2012?18	BayStack 350-12T Switch (12 10/100BaseTX plus 1 MDA slot).	PASS	N/A	N/A	N/A	
AL2012A19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (No power cord included)	PASS	N/A	N/A	N/A	
AL2012B19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AL2012C19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AL2012D19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AL2012E19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (Includes North American power cord)	PASS	N/A	N/A	N/A	
AL2012F17	BayStack 350-24T Switch (24 10/100BaseTX plus 1 MDA slot). Includes Australian power cord, also in New Zealand and the PRC	PASS	N/A	N/A	N/A	
AL2012F19	BayStack 450-12F Switch (12 100BaseFX plus 1 MDA slot and 1 Cascade Slot)(Uses Mini-MTRJ Connectors) (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AL2018001	BayStack 400-SRC Cascade Return Cable (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2018002	BayStack 400-SSC Spare Cascade Cable (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2018003	BayStack 350/450 Wall Mount Kit - Kit includes 2 wall mount brackets and two expansion brackets for stacking units up to two high.	PASS	N/A	N/A	N/A	
AL2018004	BayStack 400-SRC Cascade Return Cable (3 meter) (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2019001	100BASE-TX UTP Media Adapter for Workgroup Switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2019002	100BASE-FX Fiber Media Adapter for Workgroup Switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL2033002	BayStack 400-2FX 2-port 100BASE-FX MDA (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2033003	BayStack 400-4FX 4-port 100BASE-FX MDA (for BayStack 450 Switches)(Mini MT-RJ connectors)-	PASS	N/A	N/A	N/A	
AL2033004	BayStack 400-4TX 4-port 10BASE-T/100BASE-TX MDA (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2033005	BayStack 450-1SX 1-port 1000BASE-SX Single PHY MDA (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2033006	BayStack 450-1SR 1-port 1000BASE-SX Redundant PHY MDA (for BayStack 450 Switches).	PASS	N/A	N/A	N/A	
AL2033007	BayStack 450-1LX 1-port 1000BASE-LX Single PHY MDA (for BayStack 450 switches).	PASS	N/A	N/A	N/A	
AL2033008	BayStack 450-1LR 1-port 1000Base-LX Redundant PHY MDA (For BayStack 450 switches).	PASS	N/A	N/A	N/A	
AL2033010	BayStack 400-ST1 Cascade Module (for BayStack 450).	PASS	N/A	N/A	N/A	
AL3133001	MTX-1 100BASE-TX Media Dependent Adapter (MDA) for BayStack 303/304 Ethernet Switches	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AL3133002	MFx-1 100BASE-FX Media Dependent Adapter (MDA) for BayStack 303/304 Ethernet Switches	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AM0008001	System Software 5.0 for BN Systems (On Flash): provides Frame Relay Switching, and IP Access and Routing functionality. The SNMP Agt for Netw Mgmt and the Acc. SW creates files containing statistical traffic data that is needed for billing purposes.	FAIL	v5.0	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008002	System Software 5.0 for ASN Systems (On Flash): provides Frame Relay Switching, and IP Access and Routing functionality. The SNMP Agt for Netw Mgmt and the Acc. SW creates files containing statistical traffic data that is needed for billing purposes.	FAIL	v5.0	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008004	System Software 6.1 for BN Systems (On Flash): provides FR Switching, and IP Access and Routing, and ISDN functionality. The SNMP Agt for Netw Mgmt and the Acc. SW creates files containing statistical traffic data that is needed for billing purposes.	FAIL	v6.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008005	System Software 6.1 with ATM option for BN (On Flash): provides FR Switching, IP Access and Routing, ISDN access, ATM Trunking, and Frame Relay to ATM Internetworking. Includes SNMP Agent for Network Management and Accounting Software.	FAIL	v6.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008006	System Software 6.1 for ASN Systems (On Flash): provides FR Switching, and IP Access and Routing, and ISDN functionality. The SNMP Agt for Netw Mgmt and the Acc. SW creates files containing statistical traffic data that is needed for billing purposes.	FAIL	v6.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008007	BayStream software 7.1 for BN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	FAIL	7.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008007	BayStream software 7.2 for BN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.2	N/A	N/A	
AM0008007	BayStream software 7.3 for BN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.3	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AM0008008	BayStream software 7.1 for BN ATM Systems (On Flash): same as AM0008007 with additional support for ATM ARE interfaces including ATM Trunking and FR/ATM Network and Service Interworking.	FAIL	7.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008008	BayStream software 7.2 for BN ATM Systems (On Flash): same as AM0008007 with additional support for ATM ARE interfaces including ATM Trunking and FR/ATM Network and Service Interworking.	PASS	v7.2	N/A	N/A	
AM0008008	BayStream software 7.3 for BN ATM Systems (On Flash): same as AM0008007 with additional support for ATM ARE interfaces including ATM Trunking and FR/ATM Network and Service Interworking.	PASS	v7.3	N/A	N/A	
AM0008009	BayStream software 7.1 for ASN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	FAIL	7.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008009	BayStream software 7.2 for ASN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.2	N/A	N/A	
AM0008009	BayStream software 7.3 for ASN Systems (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.3	N/A	N/A	
AM0008010	BayStream software 7.1 for System 5000	FAIL	7.1	N/A	N/A	Upgrade to BayStream BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AM0008010	BayStream software 7.2 for System 5000 (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.2	N/A	N/A	
AM0008010	BayStream software 7.3 for System 5000 (On Flash): provides FR Switching, IP Access and Routing, SDLC/FR Interworking, ISDN, Dial VPN Services. Includes SNMP Agent for Network Management and Accounting Software.	PASS	v7.3	N/A	N/A	
AM0014001	HP Open View 3.31 SNMP	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AM0014002	HP Open View 3.31 NNM (Must be ordered in conjunction with BNX-SPS Software and License)					Hewlett-Packard Product
AP0000001	Site Manager Version 3.0 PC-DOS Diskette	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AP0000002	Site Manager Version 3.0 CD-ROM (includes UNIX and PC versions)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AP0000004	Site Manager Version 4.0 PC-DOS Diskette	FAIL	v4.0	N/A	N/A	Upgrade to Site Manager 6.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AP0000005	Site Manager Version 4.0 CD-ROM (includes UNIX and PC versions)	FAIL	v4.0	N/A	N/A	Upgrade to Site Manager 6.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AP0000010	Site Manager Version 5.0 CD-ROM (includes UNIX and PC versions)	FAIL	v5.0	N/A	N/A	Upgrade to Site Manager 6.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AP0000011	Site Manager Version 5.0 CD-ROM (includes UNIX and PC versions)	FAIL	v5.0	N/A	N/A	Upgrade to Site Manager 6.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AP0000012	Site Manager Version 6.0 CD-ROM	FAIL	v6.0	N/A	N/A	Upgrade to Site Manager 6.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
AP0000013	Site Manager Version 6.10 CD-ROM	PASS	v6.10	N/A	N/A	
AP0000013	Site Manager Version 6.20 CD-ROM.	PASS	v6.20	N/A	N/A	
AP0000014	Site Manager Version 7.0 CD-ROM	PASS	v7.0	N/A	N/A	
AP0000015	Site Manager Version 7.10 CD-ROM	PASS	v7.10	N/A	N/A	
AP0000017	Site Manager Version 7.20 CD-ROM.	PASS	N/A	N/A	N/A	
AP0008001	Version 9.0 Controlled Introduction Features - CD-ROM	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AP0014001	BNX Site Manager Software 5.0 on CD-ROM (Solaris, SUN OS, RS-6000, PC)	FAIL	v5.0	N/A	N/A	Upgrade to Site Manager BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AP0014003	BNX Site Manager Software 6.1 on CD-ROM (Solaris, SUN OS, RS-6000, PC)	FAIL	v6.1	N/A	N/A	Upgrade to Site Manager BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AP0014004	BayStream 7.1 Site Manager CD-ROM	FAIL	v7.1	N/A	N/A	Upgrade to Site Manager BNX 7.1 Rev3 available by 1/1/98, to be Year2000 compliant.
AP0014004	BayStream 7.2 Site Manager CD-ROM	PASS	v7.2	N/A	N/A	
AP0014004	BAYSTREAM V7.3 Site Manager CD-ROM	PASS	v7.3	N/A	N/A	
AQ1002001	Model 5DN003A with temperature sensor. Multisegment configuration switch hub with 3 slots for Host Module and NMM	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1004001	Model 5DN378P-A Distributed 5000 Mixed Media Host Module with AUI	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AQ1004002	Model 5DN301P Distributed 5000 4 port 10Base-2 ThinNet Host Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1004003	Model 5DN378P-SM Distributed 5000 7-Port Mixed Media Host Module with Single Mode Fiber and port config. switching.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1004004	Model 5DN308PS Distributed 5000 12-Port 10BASE-T Host Module with Port Security	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1004005	Model 5DN307PS Distributed 5000 12-Port 10BASE-T Telco Host Module with Port Security	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1007001	Model 5DN310SA Advanced Analyzer Network Management Module for Distributed 5000 with one pre-installed Data Collection Module (DCM) and sockets for two additional Model N11 DCMs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1007002	Model 5DN310-4M Distributed 5000 Network Management Module with telenet. Includes sockets for three data collection modules (DCMs).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1007003	Model 5DN310SA-4M Distributed 5000 Advanced Analyzer Network Management Module with telenet and RMON 2. Includes one pre-installed data collection module (DCM) and sockets for two additional DCM	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1007004	Model N11-8M Distributed 5000 Data Collection Module with RMON 2	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ1011004	Rev E Boot Firmware only kit for Distributed 5000 NMM	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012001	BayStack 28200 Modular Ethernet Switch chassis with 4 slots for optional plug in Media Dependent Adapter (MDA) cards for 10/100 switched Ethernet and FDDI, using Fiber or UTP Cabling.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012002	BayStack 28200-15 eight port 10BASE-T MDA card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012003	BayStack 28200-14 four port 10BASE-FL MDA card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012004	BayStack 28200-105 two port 100BASE-TX MDA card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012005	BayStack 28200-104 two port 100BASE-FX MDA card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012006	Model 28200-EXP 2 port expansion port card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012007	BayStack 28200-109 FDDI Multimode Fiber Dual-Attachment MDA Card,	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AQ2012010	28200-DCM 10Mb Ethernet RMON Probe, w/8mg DRAM. Steerable to any 10mb switch port, supports all (9) RMON groups. Requires v2.0 (or greater) switch software.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0002703	Centillion 50 chassis, including 1 (one) power supply and rack mount kit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0002001	Centillion 100 Chassis, including one Power Supply, RS232 and Rack Mount Kit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0002002	Centillion 100 Chassis, including two Power Supplies, RS232 and Rack	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0002F02	Centillion 100 Chassis, including two Power Supplies, RS232 and Rack Mount Kit. Includes Australian power cord, also used in New Zealand and the PRC	PASS	N/A	N/A	N/A	
AS0011003	Centillion 4 MB FLASH memory upgrade kit for Centillion Software version 3.2.2 or newer and C100 ATM Wiring Closet MCP (AS1304005) and ATM Network Center MCP (AS1304007) modules (both discontinued). (See Note 1)	PASS	N/A	N/A	N/A	
AS0011003	Centillion 4 MB FLASH memory upgrade kit for Centillion Software version 3.2.2 or newer and C100 ATM Wiring Closet MCP (AS1304005) and ATM Network Center MCP (AS1304007) modules (both discontinued). (See Note 1)	PASS	N/A	N/A	N/A	
AS0012001	Standard Switching Software License for Centillion, Version 3.0 Token Ring and Ethernet LANE/IISP for ATMSpeed and TokenSpeed MCP (CDROM, License, all documentation)	PASS	v3.0	N/A	N/A	
AS0012001	Standard Switching Software License for Centillion 50/100, Version 3.1 Token Ring and Ethernet LANE/IISP for ATMSpeed and TokenSpeed MCP (CDROM, License, all documentation).	PASS	v3.1	N/A	N/A	
AS0012001	Standard Switching Software for Centillion 50/100, Version 3.2 Token Ring and Ethernet LANE/IISP for ATMSpeed and TokenSpeed MCP (CDROM, License, all documentation).	PASS	v3.2	N/A	N/A	
AS0012001-4.0	Standard Switching Software for Centillion 50/100, Version 4.0 Token Ring/Ethernet LANE, IISP, and MLT for ATM/Token Ring MCPs (CDROM, License, All Documentation)	PASS	N/A	N/A	N/A	
AS0012002	Advanced Switching Software License for Centillion, Version 3.0 Token Ring and Ethernet LANE/IISP, PNNI, QoS, for ATMSpeed MCP (CDROM, License, all documentation)	PASS	v3.0	N/A	N/A	
AS0012002	Advanced Switching Software License for Centillion 50/100 Version 3.1 Token Ring and Ethernet LANE/IISP, PNNI, QoS, for ATMSpeed MCP (CDROM, License, all documentation).	PASS	v3.1	N/A	N/A	
AS0012002	Advanced Switching Software for Centillion 50/100, Version 3.2 Token Ring and Ethernet LANE/IISP, PNNI, QoS, for ATMSpeed MCP (CDROM, License, all documentation).	PASS	v3.2	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AS0012002-4.0	Advanced Switching Software for Centillion 50/100, Version 4.0 Token Ring/Ethernet LANE, PNNI, MPOA, and QoS for ATMSpeed MCP (CDROM, License, All Documentation)	PASS	N/A	N/A	N/A	
AS0012003	Advanced Switching Software Upgrade for Centillion 50/100, Converts Standard Software License to Advanced License (CDROM, License, All Documentation).	PASS	N/A	N/A	N/A	
AS0013001	SpeedView version 2.0 for Windows 3.1. Centillion100 Installation and Configuration is included in the Manual.	PASS	v3.1	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0013001	SpeedView SNMP for Windows NT/95, Version 3.2 (CDROM, License, all documentation).	PASS	v3.2	N/A	N/A	
AS0013001-4.0	SpeedView SNMP for Windows 95/NT, Version 4.0 Supports all Centillion 20/50/100 and 5000BH Platforms(CDROM, License, All Documentation)	PASS	N/A	N/A	N/A	
AS0014001	SpeedView version 2.0 for UNIX for HP OpenView and NV/6000 for AIX	PASS	v2.0	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS0015001	SpeedView for Windows 3.1 Manual. Centillion100 Installation and Configuration is included in the Manual.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AS0015002	SpeedView for UNIX Installation and Configuration Manual.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AS1104001	4 Port TokenSpeed Token Ring Switching Host Module for UTP & STP.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1104002	4 Port TokenSpeed Token Ring Switching Host Module Multimode Fiber.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1104003	4 Port TokenSpeed/MCP Token Ring Switching Host Module with Master Control Processor for UTP & STP.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1104004	4 Port TokenSpeed/MCP Token Ring Switching Host Module with MCP for Multimode Fiber.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AS1104005	4 Port Token Ring Expansion Module (UTP) for the Centillion10 Workgroup Switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1104006	2 Port Token Ring Expansion Fiber Module for the Centillion10 Workgroup Switch	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1111001	Upgrade existing 4 Port TokenSpeed MCP for UTP & STP and 2 Port ATMSpeed ATM Module to a 4 Port TokenSpeed Switching Host Module for UTP & STP and a 4 Port ATMSpeed/MCP module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1111002	Upgrade existing 4 Port TokenSpeed MCP for Fiber and 2 Port ATMSpeed ATM Module to a 4 Port TokenSpeed Switching Host Module for Fiber and a 4 Port ATMSpeed/MCP Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1111003	Upgrade existing 4 Port TokenSpeed MCP for UTP & STP to a 4 Port TokenSpeed Switching Host Module for UTP & STP and a 4 Port ATMSpeed/MCP module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1111004	Upgrade existing 4 Port TokenSpeed MCP for Fiber to a 4 Port TokenSpeed Switching Host Module for Fiber and a 4 Port ATMSpeed/MCP module*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304001	2 Port ATMSpeed ATM Switching Host Module for OC-3c SONET over Multimode Fiber.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304002	2 Port ATMSpeed ATM Switching Host Module for OC-3c SONET over Single-mode Fiber	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304003	4 port ATMSpeed ATM Switching Host Module for SONET OC-3c over Multimode Fiber	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304005	4 Port ATMSpeed/MCP ATM Switching Host Module with Master Control Processor for OC-3c SONET over Multimode Fiber (4MB packet buffer, 10MB processor memory).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304007	4 Port ATMSpeed Network Center MCP ATM Switching Host Module with Master Control Processor for SONET OC-3c over Multimode Fiber (4MB packet buffer 16MB processor memory)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304008	4 Port ATMSpeed MDA MCP, accepts two 2 port "CL" series MDAs (16k cells buffer, 16M processor memory)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304009	4 Port ATMSpeed MDA switch, accepts two 2 port "CL" series MDAs (16k cells buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1304010	1 Port ATMSpeed 622 MCP for SONET OC-12c over Multimode Fiber.	PASS	N/A	N/A	N/A	
AS1304011	1 Port ATMSpeed 622 MCP for SONET OC-12c over Singlemode Fiber.	PASS	N/A	N/A	N/A	
AS1304012	1 Port ATMSpeed 622 Switching Host Module for SONET OC-12c over Multimode Fiber.	PASS	N/A	N/A	N/A	
AS1312001	4 Port ATMSpeed MDA MCP, accepts Two 2 port "CL" series MDAs below (16K cell buffer, 32M DRAM, Installed Advanced Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1701701	Centillion 50T Token Ring Workgroup Switch with 16 Switch Token Ring Ports, 1 exp slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1701703	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 8 Port TokenSpeed	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1701704	C50 Chassis w/TokenSpeed 8 Port MCP	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1701705	Centillion 20 - Token Ring Workgroup Switch with 24 UTP/STP RJ-45 ports and 1 Expansion Slot.	PASS	N/A	N/A	N/A	
AS1701A11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (No power cord included)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AS1701B11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
AS1701C11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes power cord commonly used in the United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
AS1701D11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes power cord commonly used in Japan)	PASS	N/A	N/A	N/A	
AS1701E11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AS1701F11	C50 Chassis w/ATMSpeed MDA MCP and 16 port TokenSpeed Host Module (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes Australian power cord, also commonly used in New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	
AS1704001	8 Port TokenSpeed UTP/STP token ring switching host module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1704002	8 Port TokenSpeed UTP/STP token ring switching host module with master control processor	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1704004	16 port TokenSpeed HD UTP/STP Token Ring Switching Host Module.	PASS	N/A	N/A	N/A	
AS1711001	Upgrade existing 4 Port TokenSpeed MCP to an 8 Port TokenSpeed MCP	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1711002	Upgrade existing 4 Port TokenSpeed MCP to a ATM MDA MCP, ATM MMF MDA and 8 Port TokenSpeed Host	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1711003	Upgrade from 4 port TokenSpeed MCP to ATM MDA MCP (AS1304008) and 16 port TokenSpeed (AS1704004) and receive a credit of \$2000 upon return of the 4 port TokenSpeed MCP.	PASS	N/A	N/A	N/A	
AS1711004	Upgrade from 8 port TokenSpeed MCP (AS1704002) to ATM MDA MCP (AS1304008) and 16 port TokenSpeed (AS1704004) and receive a credit of \$3000 upon return of the 8 port TokenSpeed MCP.	PASS	N/A	N/A	N/A	
AS1712001	Centillion10 Token Ring Workgroup Switch (8 TR ports UTP) includes SW and tech pubs kit, rack mount kit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1733001	Two (2) port copper ATM Expansion Module for the Centillion 20 Token Ring Workgroup Switch.	PASS	N/A	N/A	N/A	
AS1733002	Two (2) port fiber ATM Expansion Module for the Centillion 20 Token Ring Workgroup Switch.	PASS	N/A	N/A	N/A	
AS1733003	Four (4) port (2 copper/2 fiber) ATM Expansion Module for the Centillion 20 Token Ring Workgroup Switch.	PASS	N/A	N/A	N/A	
AS1901701	Centillion 50N Ethernet/ATM Workgroup Switch with 2 ATM OC3-c and 16 10BASE-T ports, 1 exp slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1901703	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and EtherSpeed 24-Port 10Mbps w/Telco Connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1901704	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and EtherSpeed 16-Port 10Mbps, 1K CAM w/RJ45 Connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1901705	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and EtherSpeed 16-Port 100Mbps Segment Switch (Four 4 port 100BaseTX segments) w/RJ45 Connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1901A06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (No power cord included)	PASS	N/A	N/A	N/A	
AS1901B06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
AS1901C06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes power cord commonly used in the United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
AS1901D06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes power cord commonly used in Japan)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AS1901E06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AS1901F06	C50 Chassis w/ATMSpeed MDA MCP (16k cell buffer, 16M processor memory) and 4 port EtherSpeed 10/100Mbps Ethernet Switching Host (Requires separate purchase of ATMSpeed Flex MDA). Includes Standard Switching Software License for Centillion 50/100. (Includes Australian power cord, also commonly used in New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	
AS1904001	16 Port EtherSpeed Ethernet Switching Host Module for 10BASE-T (1.25 MB buffer memory, 1 k CAM)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1904002	16 Port EtherSpeed Ethernet Switching Host Module for 10BASE-T (1.25 MB buffer memory, 8 k CAM)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1904003	8 Port EtherSpeed/MCP Ethernet Switching Host Module with Master Control Processor for 10BASE-T	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
AS1904004	8 Port EtherSpeed/MCP Ethernet Switching Host Module with Master Control Processor for 10BASE-T (1.25 MB buffer memory, 8 k CAM, 4MB processor memory)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1904005	8 Port EtherSpeed Ethernet Switching Host Module for 10BASE-FL (1.25MB buffer memory)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS1904008	24 port C100 EtherSpeed Switching Host Module for 10BaseT, Half Duplex, w/2 ea. 50 pin Telco connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS2004001	14 Port EtherSpeed 10/100 Ethernet Switching Host Module with 12 10Base-T ports and 2 100Base-FX ports (4MB packet buffer 8k CAM)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS2004002	10 Port EtherSpeed 10/100 Ethernet Switching Host Module with 8 10Base-T ports and 2 100Base-TX ports (4MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS2004004	10 Port EtherSpeed 10/100 Ethernet Switch Host Module w/ 8 10Base-T ports and 2 100Base-TX Ports (4MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS3104001	4 port EtherSpeed 100Mbps Ethernet Switching Host 100BaseTX (4 MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AS3104003	16 Port EtherSpeed 100Mbps Ethernet segment switch (Four 4 port 100BASE-TX segments)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AT2201?01	BayStack Model 202 12 port 100BT Hub/NMM	FAIL	1.0.0	1.0.0	N/A	BS202 doesn't have a Real Time clock, so it uses the Management system clock to report the information to the Web management interface. The year 2000 is reported as year 3900, but the month and date are correctly reported.
AT2201?02	BayStack Model 203 12 port 100BT Hub/NMM with 100BASE-F uplink	FAIL	1.0.0	1.0.0	N/A	BS203 doesn't have a Real Time clock, so it uses the Management system clock to report the information to the Web management interface. The year 2000 is reported as year 3900, but the month and date are correctly reported.
AT2201?03	BayStack Model 204 24 port 100BT Hub	PASS	1.0.0	1.0.0	N/A	
AT2201?04	BayStack Model 205 12 port 100BT Hub	PASS	N/A	N/A	N/A	
AT2201?05	BayStack Model 250 10BASE-T/100BASE-TX Autosense Hub/NMM with 12 RJ-45 ports	PASS	3.0.0	1.0.0	N/A	BS250 doesn't have a Real Time Clock, so it uses management system clock to report the information to the Web Management
AT2201?06	BayStack Model 251 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201?07	BayStack Model 252 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201?08	BayStack Model 253 10BASE-T/100BASE-TX Autosense Hub/NMM with 24 RJ-45 ports and optional 100BASE-FX Link Extender.	PASS	N/A	N/A	N/A	
AT2201A09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201A10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	
AT2201B09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201B10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	
AT2201C09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201C10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	
AT2201D09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201D10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	
AT2201E09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201E10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AT2201F09	BayStack Model 254 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	
AT2201F10	BayStack Model 255 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 ports and optional 100BASE-FX Link Extender	PASS	N/A	N/A	N/A	
AT2202001	BayStack 100BASE-T Fast Ethernet Hub with 12 100BASE-TX ports, 1 expansion slot, and 1 100BASE-T media adapter slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AT2202E02	BayStack 100BASE-T Fast Ethernet Hub with 24 100BASE-TX ports, 1 expansion slot, and 1 100BASE-T media adapter slot	PASS	N/A	N/A	N/A	
AT2204001	BayStack 100BASE-TX Fast Ethernet Host Module with 12 100BASE-TX ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AT2204002	BayStack 25F Fiber Link-Extender Module for BayStack 253 Hub/MMM.	PASS	N/A	N/A	N/A	
AT2204003	BayStack 250-1FX 100Base-FX MDA for BayStack 253 & 255	PASS	N/A	N/A	N/A	
AT2207001	BayStack Network Management Module for 100BASE-T Hub	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AT2218001	BayStack 100BASE-T Cascade Cable for Models 202 through 205.	PASS	N/A	N/A	N/A	
AT2218002	BayStack 100BASE-T Cascade Cable for Models 250 through 252.	PASS	N/A	N/A	N/A	
AT2219001	BayStack 100BASE-FX Fiber Media Adapter for 100BASE-T Hub	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
AT3901A04	BayStack 60-8T Hub with 8 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901A05	BayStack 60-16T Hub with 16 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901A06	BayStack 60-12T Hub with 12 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901A07	BayStack 60-24T Hub with 24 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901A08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901A09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (No power cord included)	PASS	N/A	N/A	N/A	
AT3901B04	BayStack 60-8T Hub with 8 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901B05	BayStack 60-16T Hub with 16 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901B06	BayStack 60-12T Hub with 12 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901B07	BayStack 60-24T Hub with 24 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901B08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901B09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
AT3901C04	BayStack 60-8T Hub with 8 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901C05	BayStack 60-16T Hub with 16 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901C06	BayStack 60-12T Hub with 12 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901C07	BayStack 60-24T Hub with 24 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901C08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901C09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
AT3901D04	BayStack 60-8T Hub with 8 RJ-45 Ports (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901D05	BayStack 60-16T Hub with 16 RJ-45 Ports. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901D06	BayStack 60-12T Hub with 12 RJ-45 Ports. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901D07	BayStack 60-24T Hub with 24 RJ-45 Ports. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901D08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901D09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
AT3901E04	BayStack 60-8T Hub with 8 RJ-45 Ports. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901E05	BayStack 60-16T Hub with 16 RJ-45 Ports. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901E06	BayStack 60-12T Hub with 12 RJ-45 Ports. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901E07	BayStack 60-24T Hub with 24 RJ-45 Ports. (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901E08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901E09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (Includes North American power cord)	PASS	N/A	N/A	N/A	
AT3901F04	BayStack 60-8T Hub with 8 RJ-45 Ports. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
AT3901F05	BayStack 60-16T Hub with 16 RJ-45 Ports. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AT3901F06	BayStack 60-12T Hub with 12 RJ-45 Ports. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AT3901F07	BayStack 60-24T Hub with 24 RJ-45 Ports. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AT3901F08	5-PAK of BayStack 60-12T 10BASE-T/100BASE-TX Autosense Hub with 12 RJ-45 Ports (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
AT3901F09	5-PAK of BayStack 60-24T 10BASE-T/100BASE-TX Autosense Hub with 24 RJ-45 Ports (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
C NTJ7*	Passport 4400 Rel. 2.0 and later	PASS	2.0+	N/A	N/A	No action required.
CG1001?01	BayStack101 10BASE-T Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?02	BayStack102 10BASE-T Hub with 24 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?04	BayStack104 10BASE-T Hub with 24 port TELCO Connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?05	BayStack105 10BASE-FL Hub with 6 ST ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?08	BayStack 50 10BASE-T Hub with 4 RJ-45 and 1 10BASE-2 BNC Ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?09	BayStack 51 10BASE-T Hub with 8 RJ-45 and 1 10BASE-2 BNC or AUI Autoselected ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?10	BayStack 52 10BASE-T Hub with 16 RJ-45 ports, 1 10BASE-2 BNC port and 1 AUI port	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?11	BayStack 150 10BASE-T Hub/MM with 24 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?12	BayStack 151 10BASE-T Hub with 24 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?13	BayStack 152 10BASE-T Hub/MM with 24 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001?14	BayStack 153 10BASE-T Hub with 12 RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001A06	BayStack106 10BASE-T Hub with 12 port RJ-45 Connectors and -48 VDC Pow	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1001A07	BayStack107 10BASE-T Hub with 24 port RJ-45 Connectors and -48 VDC Pow	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1007001	BayStack Ethernet Standard SNMP Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1007002	BayStack Ethernet Advanced Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1007003	BayStack Ethernet SA Advanced Analyzer Network Management Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1007004	BayStack Ethernet SA Advanced Analyzer Network Managment Model with RMON 2	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1011001	BayStack 10Base-T Host Firmware Upgrade Kit and Documentation for the BayStack 10Base-T Hub. Orders > 1 may order supplementary F/W kit CG1011002 if no additional documentation is required.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1011002	Model CG1011002 Supplementary, firmware only, 10Base-T Host Firmware Upgrade Kit for the BayStack 10Base-T/FL hub. May be ordered separately or in conjunction with CG1011001 firmware upgrade kits which include documentation	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1011005	BayStack 10Base-T Boot Firmware Upgrade Kit with documentation for the BayStack 10Base-T Advanced NMM. Orders >1can request CG1011006 if no documentation is required.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1011006	BayStack 10Base-T Boot Firmware Upgrade Kit without documentation for the BayStack 10Base-T Advanced NMM. Order number CG1011005 should be requested if documentation is required.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019001	BayStack AUI Media Adapter for 10Mb Ethernet hubs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019002	BayStack 10BASE-2 Media Adapter for 10Mb Ethernet hubs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019003	BayStack 10BASE-FL Fiber Media Adapter for 10Mb Ethernet hubs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019004	BayStack 10BASE-FL RDN Redundant Fiber Media Adapter for 10Mb Ethernet hubs*	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019005	BayStack 10BASE-T MDI Media Adapter for 10Mb Ethernet hubs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CG1019007	BayStack Single Mode Fiber Media adapter for 10Mb Ethernet hubs	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CH2004001	Model 58000, 10/100 Ethernet Switching Module for the System 5000 with 16 10BASE-T ports and 1 100BASE-X MDA expansion port.	FAIL	v2.0	N/A	N/A	Upgrade to v2.1.1.1 or subsequent version, available as of April 1, 1998, to be Year 2000 compliant.
CH2011002	Model 58000 MDA Expansion Module which accepts four 100BASE-X MDAs, for a total of eight ports.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CH3133001	Model 58000-104 two-port 100BASE-FX Fiber MDA with SC connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CH3133002	Model 58000-105 two-port 100BASE-TX UTP MDA with RJ connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CH3133003	Model 58000-106 two-port 100BASE-X Combo MDA with one fiber SC connector and one UTP RJ connector	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CH3133004	Model 58000-109 dual-attachment FDDI Multimode Fiber MDA with MIC connectors	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL 1904003	Model 5324 Ethernet Switching Host Module w/12 10Bast-FL Ethernet Ports (1.25 MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL0012001	Standard Switching Software License for 5000BH, Version 3.0 Token Ring and Ethernet LANE/IISP for ATM and Token Ring MCPs (CDROM, License, all documentation)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL0012001	Standard Switching Software License for 5000BH, Version 3.1 Token Ring and Ethernet LANE/IISP for ATM and Token Ring MCPs (CDROM, License, all documentation).	PASS	v3.1	N/A	N/A	
CL0012001	Standard Switching Software for 5000BH, Version 3.2 Token Ring and Ethernet LANE/IISP for ATM and Token Ring MCPs (CDROM, License, all documentation).	PASS	v3.2	N/A	N/A	
CL0012001-4.0	Standard Switching Software for 5000BH, Version 4.0 Token Ring/Ethernet LANE, IISP and MLT for ATM/Token Ring MCPs (CDROM, License, all documentation).	PASS	N/A	N/A	N/A	
CL0012002	Advanced Switching Software License for 5000BH, Version 3.0 Token Ring and Ethernet LANE/IISP, PNNI, QoS for ATM MCPs (CDROM, License, all documentation)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL0012002	Advanced Switching Software License for 5000BH, Version 3.1 Token Ring and Ethernet LANE/IISP, PNNI, QoS for ATM MCPs (CDROM, License, all documentation).	PASS	v3.1	N/A	N/A	
CL0012002	Advanced Switching Software for 5000BH, Version 3.2 Token Ring and Ethernet LANE/IISP, PNNI, QoS for ATM MCPs (CDROM, License, all documentation).	PASS	v3.2	N/A	N/A	
CL0012002-4.0	Advanced Switching Software for Centillion 5000BH, Version 4.0 Token Ring/Ethernet LANE, PNNI, MPOA, and QoS for ATMSpeed MCP (CDROM, License, All Documentation).	PASS	N/A	N/A	N/A	
CL0012003	Advanced Switching Software Upgrade for 5000BH, Converts Standard Image License to Advanced License (CDROM, License, All Documentation)	PASS	N/A	N/A	N/A	
CL1304001	Model 5724 4 port ATM switching host module, SONET OC3c over multimode fiber	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304002	Model 5724M 4 port ATM Switching Host Module with Master Control Processor, SONET OC-3c over MMF	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304004	Model 5724-SM 4 port ATM switching host module, SONET OC-3c over single mode fiber	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304006	Model 5782 Centillion MultiProtocol Engine 32M	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304007	Model 5782 Centillion MultiProtocol Engine 64M	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304008	Model 5724M-SM 4 Port ATM switching host module with Master Control Processor, SONET OC-3c over single mode fiber	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304013	Model 5720 ATM MDA Host, accepts two 2 port MDAs (16k cell buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304014	Model 5720M ATM MDA MCP, accepts two 2 port MDAs (16m processor memory, 16k cell buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1304015	Model 57622M-SM Single Port ATM Switching Host Module with Master Control Processor, SONET OC-12c over SMF.	PASS	N/A	N/A	N/A	
CL1304016	Model 57622M-MM Single Port ATM Switching Host Module with Master Control Processor, SONET OC-12c over MMF.	PASS	N/A	N/A	N/A	
CL1304017	Model 57622-MM Single Port ATM Switching Host Module, SONET OC-12c over MMF.	PASS	N/A	N/A	N/A	
CL1312001	Model 5720M ATM MDA MCP, accepts Two 2 port MDAs (32M DRAM, 16K cell buffer, Installed Advanced Software)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1333001	2 Port SONET/SDH MMF ATM MDA for models 5720,5720M, ATMSpeed MDA and ATMSpeed MCP MDA baseboards	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1333002	2 Port SONET/SDH UTP ATM MDA for models 5720,5720M, ATMSpeed MDA and ATMSpeed MCP MDA baseboards	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1333003	2 Port SONET/SDH SMF ATM MDA for models 5720,5720M, ATMSpeed MDA and ATMSpeed MCP MDA baseboards	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1333004	2 port DS-3 ATM MDA for Models 5720, 5720M, ATMSpeed MDA and ATMSpeed MCP MDA base boards.	PASS	N/A	N/A	N/A	
CL1333005	2 port E-3 ATM MDA for Models 5720, 5720M, ATMSpeed MDA and ATMSpeed MCP MDA base boards.	PASS	N/A	N/A	N/A	
CL1704001	Model 5525 Token Ring Switching Host Module with (8) Shielded RJ-45UTP/STP Token Ring Switching Ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1704002	Model 5525M Token Ring Switching Host Module with Master Control Processor and (8) Shielded RJ-45UTP/STP Token Ring Switching Ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1704003	Model 5524 Token Ring Switching Host Module with (8) Fiber 802.5 ST Token Ring Switch ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1704004	Model 5525HD Token Ring Switching Host Module with (24) shielded RJ-45 UTP/STP Token Ring switch ports.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CL1711001	Upgrade from 5525M (CL1704002) to 5720M (CL1304014) and 5525HD (CL1704004) and receive a credit of \$4,000 upon return of the 5525M.	PASS	N/A	N/A	N/A	
CL1904001	Model 5328 Ethernet Switching Host Module with 16 10Base-T Ethernet ports (1.25 MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1904002	Model 5328M Ethernet Switching Host Module with Master Control Processor (MCP) and 8 10Base-T Ethernet ports (1.25 MB packet buffer)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL1904004	Model 5329 HD Ethernet Switching Host Module with 24 10Base-T RJ-45 ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL3104004	Model 5425 4 port 100Mbps Ethernet switching host module, 100BaseTX	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL3104006	Model 5455 16 Port 100Mbps Ethernet segment switch (Four 4 port 100BASE-TX segments).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CL3104007	Model 5625 Ethernet Switching Host Module with 24-ports 10/100BaseTX Autosense (RJ-45).	PASS	N/A	N/A	N/A	
CL3104008	Model 5424 Ethernet Switching Host Module with 24-ports 100BaseFX (MT-RJ Connectors)	PASS	N/A	N/A	N/A	
CM0001001	Floppies-3.1, Software with Console Cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001002	CT24 Cart tape 3.1 Software with Console Cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001003	CD ROM 3.1 Software with Console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001004	DEC-TK50 (Unix) 3.1 Software with Console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001005	HP-4mm DAT Cartridge tape 3.1 Software with Console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001006	8mm DAT Cartridge tape 3.1 Software with Console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0001007	DEC-TK50 (VMS) Cartridge tape 3.1 Software with Console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0008001	ELS-MT-100 9-TRACK, 1600 bpi 1/2" magnetic tape*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0008002	ELS-CT24-100 QIC-24 1/4" cartridge tape*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0008003	ELS-FD3-100 3 1/2" floppy diskettes*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0008004	ELS-TK50-100 DEC TK-50 cartridge tape*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0008005	ELS-HPDAT-100 H-P 4mm DAT cartridge tape*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0008006	ELS-8MM-100 8mm DAT cartridge tape*	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0010002	BaySecure Access with Backup V1.3 Windows NT version.	PASS	v1.3	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010002	BaySecure Access Control with Backup V2.1 Windows NT version.	PASS	N/A	N/A	N/A	
CM0010003	BaySecure Access with Backup V1.3 NetWare Version.	PASS	v1.3	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010003	BaySecure Access with Backup V1.5 NetWare Version.	PASS	v1.5	N/A	N/A	
CM0010004	BaySecure Access, V1.3, Windows NT Version.	PASS	v1.3	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010004	BaySecure Access, V2.1, Windows NT Version.	PASS	v2.1	N/A	N/A	
CM0010005	BaySecure Access, V1.3, NetWare Version.	PASS	v1.3	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010005	BaySecure Access, V1.5, NetWare Version.	PASS	v1.5	N/A	N/A	
CM0010006	BaySecure Access with Backup V2.0, Unix Version	PASS	v2.0	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010006	BaySecure Access with Backup V2.1, Unix Version.	PASS	v2.1	N/A	N/A	
CM0010006	BaySecure Access with Backup V2.11, Unix Version.	PASS	v2.11	N/A	N/A	
CM0010007	BaySecure Access, V2.0, Unix	PASS	v2.0	N/A	N/A	Vendor is Funk Software / Upgrades available on CD Only
CM0010007	BaySecure Access, V2.1, Unix.	PASS	v2.1	N/A	N/A	
CM0010007	BaySecure Access, V2.11, Unix Version.	PASS	v2.11	N/A	N/A	
CM0011012	AX3-UPG-SLC-116 16 port serial line card, roms (IP only)	FAIL	N/A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0011014	AX3-UPG-SLC-132 32 port serial line card, roms (IP only)	FAIL	N/A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0011018	MARLIN 3000 PRI 6 module CH, NET5 Card (Euro/UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0011019	MARLIN 3000 PRI module 8 CH, NET5 Card (Euro/UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0011020	MARLIN 3000 PRI module 15 CH, NET5 Card (Euro/UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0011021	MARLIN 3000 PRI module 20 CH, NET5 Card (Euro/UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0011023	MARLIN 3000 PRI module 25 CH, NET5 Card (Euro/UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM0011047	Self-Boot Upgrade Kit, RA4000, R4.2 (available for all current units with the 3 ethernet interfaces combined on board)		R5.4	N/A	N/A	
CM0011049	Remote Annex Software, CDNT(Windows)\Version 4.2	FAIL	4.2	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0011050	Remote Annex Software,CD,UNIX,Version 4.2	FAIL	4.2	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0011062	Remote Annex Software, CD,NT/UNIX,V5.1 (for all Platforms)	PASS	5.1	N/A	N/A	
CM0011071	Remote Annex Software, CD,NT/UNIX,V5.4, for all Platforms.	PASS	5.4	N/A	N/A	Order Number also represented v5.2 and 5.3/Upgrades available on CD Only
CM0011071	Remote Annex Software, CD,NT/UNIX,V5.2,w/x2 Support (for 5399 and 8000 Platforms ONLY)	PASS	5.2	N/A	N/A	
CM0011075	Remote Annex Software, CD,NT/UNIX,V6.0 (for 5399 and 8000 Platforms ONLY)	PASS	v6.0	N/A	N/A	
CM0011075	Remote Access Software, CD,NT/UNIX,V6.1 (for 5399 and 8000 Platforms only).	PASS	v6.1	N/A	N/A	
CM0011077	Versalar Dialout Client (for 5399 and 8000 Platforms ONLY)	PASS	N/A	N/A	N/A	
CM0011078	Remote Annex Software, CD,NT/UNIX,V5.4 (for 2000, 4000, 5393, 6100, and 6300 Platforms Only).	PASS	v5.4	N/A	N/A	
CM0011080	Remote Annex Software, CD,NT/UNIX,V7.0 (for 5399 and 8000 Platforms ONLY).	PASS	N/A	N/A	N/A	
CM0011081	Remote Annex Software, On-Line Documentation CD, NT/UNIX Version 7.0 (for 5399 and 8000 Platforms only).	PASS	N/A	N/A	N/A	
CM0013001	RAX-FD3-1-11.1 3 1/2" floppy diskettes*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0013002	AX-FDS-1-10.0 3 1/2" floppy diskettes*	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014001	RAX-CT24-1-11.1 QIC-24 1/4" cartridge tape*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0014002	RAX-CD-1-11.1 CD Rom*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0014003	RAX-TK50-1-11.1 DEC TK-50 cartridge tape* (no Annex Manager included)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0014004	RAX-HPDAT-11.1 H-P 4mm DAT cartridge tape*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0014005	RAX-8MM-1-11.1 8mm DAT cartridge tape*	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0014006	AX-CT24-1-10.0 QIC-24 1/4" cartridge tape*	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014007	AX-CD-1-10.0 CD Rom*	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014008	AX-8MM-1-10.0 8mm DAT cartridge tape*	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014009	AX-TK50-1-10.0 DEC TK-50 cartridge tape* (no Annex Manager included)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014010	AX-HPDAT-1-10.0 H-P 4mm DAT cartridge tape*	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM0014012	Remote Access RA2000/4000/6100 CD ROM (NT) 3.1 Software with console c	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0014013	RA6300 CD ROM (NT) 3.1 Software with console cable	FAIL	R3.1	N/A	N/A	Upgrade to R5.1 or later/ Upgrades available on CD only
CM0014014	MicroAnnex ELS Network Software V7.1B CD Rom*.	PASS	v7.1b	N/A	N/A	
CM0015001	RAX-DOC-11.1 Documentation Kit: Users Guide, Hardware Guides, Network Administrators Guides, Software Installation Notes & Release Notes, for Remote Annexes	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0016001	OPT-3270-2 TN3270 protocol License for one Micro Annex XL	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0016002	OPT-3270-4 TN3270 protocol License for one Annex Three	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0016004	OPT-ARA-2 AppleTalk Remote Access (ARA) protocol License for one Micro Annex XL	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0016005	OPT-ARA-4 AppleTalk Remote Access (ARA) protocol License for one Annex Three	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM0016006	ROPT-IPX-4 IPX software, documentation and license for a 4 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016007	ROPT-IPX-8 IPX software, documentation and license for an 8 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016008	ROPT-IPX-16 IPX software, documentation and license for a 16 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016009	ROPT-IPX-18 IPX software, documentation and license for a 18 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016010	ROPT-IPX-36 IPX software, documentation and license for a 36 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016011	ROPT-IPX-54 IPX software, documentation and license for a 54 port Remote Annex	PASS	10.1	N/A	N/A	
CM0016013	ROPT-IPX-72 IPX software, documentation and license for a 72 port Remote Annex	PASS	10.1	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM0016035	AX-LAT-48 LAT Protocol right-to-use License for one 48 Port Remote Annex	PASS	N/A	N/A	N/A	
CM0016036	AX-LAT-60 LAT Protocol right-to-use License for one 60 Port Remote Annex	PASS	N/A	N/A	N/A	
CM1001011	2001-PNA1 Async 8 port, network-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001012	2001-PNA2 Async 8 port, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001013	2001-PSA1 Async 8 port, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001014	2001-PNC1 Async 8 port, network-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001015	2001-PNC2 Async 8 port, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001016	2001-PSC2 Async 8 port, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001017	2001-PND1 Async 8 port, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001018	2001-PSD1 Async 8 port, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001019	2002-PNA1 Async 16 port, network-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001020	2002-PNA2 Async 16 port, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001021	2002-PSA1 Async 16 port, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001022	2002-PNC1 Async 16 port, network-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001023	2002-PNC2 Async 16 port, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001024	2002-PND1 Async 16 port, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001025	2002-PSD1 Async 16 port, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001026	2002-PSD2 Async 16 port, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001027	2003-PNA1 Async 4 port, network-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001028	2003-PNA2 Async 4 port, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001029	2003-PSA1 Async 4 port, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001030	2003-PSA2 Async 4 port, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001031	2003-PNC1 Async 4 port, network-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001032	2003-PNC2 Async 4 port, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001033	2003-PSC1 Async 4 port, self-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001034	2003-PSC2 Async 4 port, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001035	2003-PND1 Async 4 port, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001036	2003-PND2 Async 4 port, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001037	2003-PSD1 Async 4 port, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001038	2003-PSD2 Async 4 port, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001039	2001-ENA2 Async 8 port, EFS, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001040	2001-ESA1 Async 8 port, EFS, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001041	2001-ENC2 Async 8 port, EFS, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001042	2001-END1 Async 8 port, EFS, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001043	2001-ESD1 Async 8 port, EFS, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001044	2001-ESD2 Async 8 port, EFS, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001045	2002-ENA1 Async 16 port, EFS, network-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001046	2002-ENA2 Async 16 port, EFS, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001047	2002-ESA1 Async 16 port, EFS, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001048	2002-ENC1 Async 16 port, EFS, network-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001049	2002-ENC2 Async 16 port, EFS, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001050	2002-END1 Async 16 port, EFS, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001051	2002-ESD1 Async 16 port, EFS, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001052	2003-ENA1 Async 4 port, EFS, network-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001053	2003-ENA2 Async 4 port, EFS, network-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001054	2003-ESA1 Async 4 port, EFS, self-booting, thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001055	2003-ESA2 Async 4 port, EFS, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001056	2003-ENC1 Async 4 port, EFS, network-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001057	2003-ENC2 Async 4 port, EFS, network-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001058	2003-ESC1 Async 4 port, EFS, self-booting, thin & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001059	2003-ESC2 Async 4 port, EFS, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001060	2003-END1 Async 4 port, EFS, network-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM1001061	2003-END2 Async 4 port, EFS, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001062	2003-ESD1 Async 4 port, EFS, self-booting, twisted pair & thick Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001063	2003-ESD2 Async 4 port, EFS, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001064	4001-PN1 Async 18 port, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001065	4001-PN2 Async 18 port, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001066	4001-PS1 Async 18 port, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001067	4001-PS2 Async 18 port, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001068	4002-PN1 Async 36 port, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001069	4002-PN2 Async 36 port, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001070	4002-PS1 Async 36 port, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001071	4002-PS2 Async 36 port, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001072	4004-PN1 Async 54 port, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001073	4004-PN2 Async 54 port, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001074	4004-PS1 Async 54 port, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001075	4004-PS2 Async 54 port, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001076	4003-PN1 Async 72 port, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001077	4003-PN2 Async 72 port, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001078	4003-PS1 Async 72 port, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001079	4003-PS2 Async 72 port, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001080	4001-EN1 Async 18 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001081	4001-EN2 Async 18 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001082	4001-ES1 Async 18 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001083	4001-ES2 Async 18 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001084	4002-EN1 Async 36 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001085	4002-EN2 Async 36 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001086	4002-ES1 Async 36 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001087	4002-ES2 Async 36 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001088	4004-EN1 Async 54 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001089	4004-EN2 Async 54 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001090	4004-ES1 Async 54 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001091	4004-ES2 Async 54 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001092	4003-EN1 Async 72 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001093	4003-EN2 Async 72 port, EFS, network-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001094	4003-ES1 Async 72 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 110V	PASS	R.5.4	N/A	N/A	
CM1001095	4003-ES2 Async 72 port, EFS, self-booting, thick, thin & twisted pair Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001096	2001-INA2 Async 8 port IP/IPX network-booting, thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001097	2001-INC2 Async 8 port IP/IPX, network-booting,thin & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001098	2001-ISC2 Async 8 port IP/IPX,self-booting,thin & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001099	2001-ISD2 Async 8 port IP/IPX, self-booting twisted pair & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001100	2001-IND2 Async 8 port IP/IPX, network-booting twisted pair & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM1001101	2001-ISA2 Asynch 8 port IP/IPX, self-booting, thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001102	2003-1NA2 Asynch 4 port, IP/IPX, network-booting thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001103	2003-1SA2 Asynch 4 port, IP/IPX, self-booting thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001104	2003-1NC2 Asynch 4 port, IP/IPX, network-booting thick & thin Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001105	2003-1SC2 Asynch 4 port, IP/IPX, self-booting thick & thin Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001106	2003-1ND2 Asynch 4 port, IP/IPX, network-booting twisted pair & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001107	2003-1ND2 Asynch 4 port, IP/IPX, self-booting twisted pair & thick Ethernet 220V	PASS	R.5.4	N/A	N/A	
CM1001108	2001-PND2 Async 8 port, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001109	2001-PSA2 Async 8 port, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001110	2001-PSD2 Async 8 port, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001111	2002-PND2 Async 16 port, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001112	2002-PSA2 Async 16 port, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001113	2002-PSC2 Async 16 port, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001114	2001-END2 Async 8 port, EFS, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001115	2001-ESA2 Async 8 port, EFS, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001116	2002-END2 Async 16 port, EFS, network-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001117	2001-ESC2 Async 8 port, EFS, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001118	2002-ESA2 Async 16 port, EFS, self-booting, thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001119	2002-ESD2 Async 16 port, EFS, self-booting, twisted pair & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001120	2002-ESC2 Async 16 port, EFS, self-booting, thin & thick Ethernet, 220V	PASS	R.5.4	N/A	N/A	
CM1001130	MARLIN 3000 Router PRI module 6 CH	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001131	MARLIN 3000 Router PRI module 8 CH (Euro version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001132	MARLIN 3000 Router PRI module 15 CH (Euro version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001133	MARLIN 3000 Router PRI module 20 CH (Euro version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001135	MARLIN 3000 Router PRI module 25 CH (Euro version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001139	X21 TO G703 Interface (UK version only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1001141	Remote Access RA2000 BAY Enclosure 8Port Thick Net/Thin Net Ethernet 110	PASS	R.5.4	N/A	N/A	
CM1001142	Remote Access RA2000 BAY Enclosure 8Port Twisted Pair /Thick Net Etherne	PASS	R.5.4	N/A	N/A	
CM1001143	Remote Access RA2000 BAY Enclosure 8Port Thick Net/Thin Net Ethernet 220	PASS	R.5.4	N/A	N/A	
CM1001144	Remote Access RA2000 BAY Enclosure 8Port Twisted Pair /Thick Net Etherne	PASS	R.5.4	N/A	N/A	
CM1001145	Remote Access RA2000 BAY Enclosure 16Port Thick Net/Thin Net Ethernet 1	PASS	R.5.4	N/A	N/A	
CM1001146	Remote Access RA2000 BAY Enclosure 16Port Twisted Pair /Thick Net Etherne	PASS	R.5.4	N/A	N/A	
CM1001147	Remote Access RA2000 BAY Enclosure 16Port Thick Net/Thin Net Ethernet 22	PASS	R.5.4	N/A	N/A	
CM1001148	Remote Access RA2000 BAY Enclosure 16 Port Twisted Pair /Thick Net Etherne	PASS	R.5.4	N/A	N/A	
CM1001149	External NT1 (North America only)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CM1009?13	AXM-A-8-N-10x 8 port, network-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?14	AXM-C-8-N-10x 8 port, network-booting, thin & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?15	AXM-D-8-N-10x 8 port, network-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?16	AXM-A-8-S-10x 8 port, self-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?17	AXM-C-8-S-10x 8 port, self-booting, thin & thick Ethernet 2MB, IP	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?18	AXM-D-8-S-10x 8 port, self-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?19	AXV2-A-8-S-10x 8 port, self-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?21	AXM-A-P-N-10x 8+2 port, network-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?22	AXM-C-P-N-10x 8+2 port, network-booting, thin & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?23	AXM-D-P-N-10x 8+2 port, network-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?24	AXM-A-P-S-10x 8+2 port, self-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?25	AXM-C-P-S-10x 8+2 port, self-booting, thin & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?26	AXM-D-P-S-10x 8+2 port, self-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM1009?27	AXM-A-16-N-10x 16 port, network-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?28	AXM-C-16-N-10x 16 port, network-booting, thin & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?29	AXM-D-16-N-10x 16 port, network-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?30	AXM-A-16-S-10x 16 port, self-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?31	AXM-C-16-S-10x 16 port, self-booting, thin & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?32	AXM-D-16-S-10x 16 port, self-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?33	AXV2-A-16-N-10x 16 port, network-booting, thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?34	AXV2-D-16-N-10x 16 port, network-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?37	AXE-A-8-N-10x 8 port, network-booting, thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?41	AXE-D-8-N-10x 8 port, network-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?43	AXE-A-8-S-10x 8 port, self-booting, thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?47	AXE-D-8-S-10x 8 port, self-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?49	AXE-C-P-N-10x 8+2 port, network-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?51	AXE-C-P-S-10x 8+2 port, self-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?53	AXE-A-16-N-10x 16 port, network-booting, thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?54	AXE-C-16-N-10x 16 port, network-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?55	AXE-D-16-N-10x 16 port, network-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?56	AXE-A-16-S-10x 16 port, self-booting, thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009?58	AXE-D-16-S-10x 16 port, self-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009001	AX3-16/0-1N-100 16 port, network-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009002	AX3-16/0-2N-100 16 port, network-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009003	AX3-32/0-1N-100 32 port, network-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009004	AX3-32/0-2N-100 32 port, network-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009005	AX3-32/32-1N-100 64 port, network-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009006	AX3-32/32-2N-100 64 port, network-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009007	AX3-16/0-1S-100 16 port, self-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009008	AX3-16/0-2S-100 16 port, self-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009009	AX3-32/0-1S-100 32 port, self-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009010	AX3-32/0-2S-100 32 port, self-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009011	AX3-32/32-1S-100 64 port, self-booting, thick, thin & twisted pair Ethernet, IP, 110V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009012	AX3-32/32-2S-100 64 port, self-booting, thick, thin & twisted pair Ethernet, IP, 220V	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009020	AXV2-D-8-S-100 8 port, self-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009035	AXV2-A-16-S-101 16 port, self-booting, thick Ethernet (2MB, IP)	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009036	AXV2-D-16-S-100 16 port, self-booting, twisted pair & thick Ethernet (2MB, IP)	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009039	AXE-C-8-N-101 8 port, network-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009045	AXE-C-8-S-100 8 port, self-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009048	AXV-C-8-N-100 8 port, network-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009050	AXE-D-P-N-101 8+2 port, network-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009052	AXE-D-P-S-101 8+2 port, self-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CM1009057	AXE-C-16-S-101 16 port, self-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009059	AXV-A-16-N-100 16 port, network-booting, thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009060	AXV-C-16-N-100 16 port, network-booting, thin & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1009061	AXV-D-16-N-100 16 port, network-booting, twisted pair & thick Ethernet	FAIL	7.1B	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1011001	4000-P18 Async 18 port serial line expansion card	PASS	N/A	N/A	N/A	
CM1011002	4000-P36 Async 36 port serial line expansion card	PASS	N/A	N/A	N/A	
CM1011003	4000-E18 Async 18 port serial line expansion card, Enterprise Feature Set	PASS	N/A	N/A	N/A	
CM1011004	4000-E36 Async 36 port serial line expansion card, Enterprise Feature Set	PASS	N/A	N/A	N/A	
CM1019001	AX3-UPG-TN-100 Thin (10Base-2) Ethernet adapter card (for installed base of LAN specific units)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1019002	AX3-UPG-TP-100 Twisted-pair (10Base-T) Ethernet adapter card (for installed base of LAN specific units)	FAIL	10.0A	N/A	N/A	Requires 14.1 Host Tools. Upgrades available on CD Only
CM1019003	6101-PS1 8 V.34 modems, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CM1019004	6102-PS1 16 V.34 modems, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CM1019005	6103-PS1 24 V.34 modems, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CM1019006	6101-ES1 8 V.34 modems, EFS, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CM1019007	6102-ES1 16 V.34 modems, EFS, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CM1019008	6103-ES1 24 V.34 modems, EFS, self-booting, thin, thick & twisted pair Ethernet, 110V	PASS	5.4	N/A	N/A	
CMOO110001	Client Pak, FastLin2 Software V2.13	FAIL	v2.13	N/A	N/A	Upgrade to R5.1 or later/Upgrades available on CD Only
CONTIVITY EXTRANET SWITCH		PASS	N/A	N/A	N/A	
CP1101701	BayStack501 Token Ring Hub with 24 Active UTP/STP RJ-45 ports, 1 MDA Slot	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1101702	BayStack502 Token ring Hub with 24 Active UTP/STP RJ-45 Ports, 1 MDA Slot and 1 Expansion Slot. Includes Standard Network Management Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1101703	BayStack503 Token Ring Hub with 24 Active UTP/STP RJ-45 Ports, 1 MDA Slot and 1 Expansion Slot. Includes Advanced Network Management Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1101704	BayStack504 Token Ring Hub with 24 Active UTP/STP RJ-45 Ports, 1 MDA Slot and 1 Expansion Slot. Includes Advanced Analyzer Network Management Module and Data Collection Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1107001	BayStack Token Ring Standard Network Management Module Upgrade Kit	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1107002	BayStack Token Ring Standard Network Management Module to Advanced Analyzer Upgrade Kit. Includes Data Collection Module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1111001	BayStack Token Ring Multi-Ring Expansion Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1111002	BayStack Token Ring Model 502 boot firmware version B upgrade kit. When the model 502 product started shipping no vendor was mfg. 60ns SIMMs. This allows the use of those SIMM's now being sold by different vendors.	PASS	N/A	N/A	N/A	
CP1111003	BayStack Token Ring models 503 and 504 boot firmware version B upgrade kit. When the models 503 and 504 begin shipping no vendors were mfg. 60ns Simm's, this allows the use of those Simm's now being sold by different vendors.	PASS	N/A	N/A	N/A	
CP1133001	BayStack Token Ring Dual Port Fiber 802.5j RI/RO Media Dependant Adapter.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CP1133002	BayStack Token Ring Dual Port Copper RI/RO Media Dependant Adapter.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CQ0011001	IIWARRANTY-2NDYR Extended Warranty includes; 2 years of hot swap RMA replacements, Free 2 years II Software Upgrades (if purchased at time of registration, Priority Technical Support	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001001	50-user Single Ethernet connector with 28.8 internal modem (supports 10Base-T and 10Base2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001002	50-user Dual Ethernet connectors with 28.8 internal modem (supports 10Base-T and 10Base2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001003	50-user Single Token Ring and Ethernet connectors with 28.8 internal modem (supports both 10Base-T and 10Base-2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001004	50-user Single Ethernet connector with built-in ISDN connection (supports both 10Base-T and 10Base-2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001005	50-user Dual Ethernet connectors with built-in ISDN connection (supports 10Base-T and 10Base2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001006	50-user Single Token Ring and Ethernet connectors with built-in ISDN connection (supports both 10Base-T and 10Base-2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CQ1001007	50-user Single Ethernet connector with built-in ISDN connection (supports both 10Base-T and 10Base-2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001008	50-user Dual Ethernet connectors with built-in ISDN connection (supports 10Base-T and 10Base2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001009	50-user Single Token Ring and Ethernet connectors with built-in ISDN connection (supports both 10Base-T & 10Base-2).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001010	Dual Ethernet connection with no internal modem and no built-in ISDN connection (supports both 10Base-T and 10Base-2). Designed to be used with an external router.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001011	50-user Single Ethernet with 28.8mb Internal Modem - Australian version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001012	50-user Dual Ethernet with 28.8mb Internal Modem - Australian version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001013	50-user Single Token-Ring/Single Ethernet with 28.8mb Internal Modem - Australian version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001014	UUNET Bundle - Dual Ethernet with ISDN with NT	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001015	UUNET Bundle - Single Token-Ring/Single Ethernet with ISDN with NT	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001016	50-user Single Ethernet with 28.8mb Internal Modem - UK version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001017	50-user Dual Ethernet with 28.8mb Internal Modem - UK version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001018	50-user Single Token-Ring/Single Ethernet with 28.8mb Internal Modem - UK version	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001020	20-user single Ethernet connector w/28.8k internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001021	20-user dual Ethernet connector w/28.8k internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001022	20-user single TR & Ethernet connector w/28.8k internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001023	20-user single Ethernet connector w/ISDN, North America only (includes NT1)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001024	20-user dual Ethernet connector w/ISDN, North America only (includes NT1)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001025	20-user single TR & Ethernet connector w/ISDN, North America only (includes NT1)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001026	20-user single Ethernet connector w/ISDN, no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001027	20-user dual Ethernet connector w/ISDN, no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001028	20-user single TR & Ethernet w/ISDN, no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001029	20-user dual Ethernet w/no internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001030	10 user add-on pack	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001031	20-user dual Token Ring & Ethernet w/no internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001032	50-user dual Token Ring (16/16) & Ethernet w/no internal modem	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CQ1001033	Single Ethernet connector w/28.8k internal modem (version: Australia)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001034	Dual Ethernet connector w/28.8k internal modem (version: Australia)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001035	Single Token Ring/ Ethernet connector w/28.8k internal modem (version: Australia)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001060	Single Ethernet connector w/28.8k internal modem (version: - U.K.)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001061	Dual Ethernet connector w/28.8k internal modem (version: - U.K.)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001062	Single Token Ring / Ethernet connector w/28.8k internal modem (version: - U.K.)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001069	30-user add-on pack (Limited Edition)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001071	Education Bundle 30-user Dual Ethernet connector w/28.8k internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001072	Education Bundle 30-user dual Ethernet connector w/ISDN , North America only	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001073	Education Bundle 30-user dual Ethernet connector w/ISDN no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001074	Education Bundle 30-user dual Ethernet w/no internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001078	Dual Ethernet with T1 and integrated CSU/DSU	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001079	Token Ring & Ethernet with T1 and integrated CSU/DSU	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001080	Dual Ethernet with internal DDS	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001081	Token Ring & Ethernet w/Internal DDS	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001082	Dual Ethernet with V.35	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001083	Token Ring & Ethernet with V.35	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001084	Dual Ethernet without internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001085	Dual Token Ring (16/16) & Ethernet w/no internal modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001086	Single Ethernet connector w/internal analog modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001087	Dual Ethernet connector w/internal analog modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001088	Single Token Ring & Ethernet connector w/internal analog modem	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001089	Single Ethernet connector w/ISDN , North America only	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001090	Dual Ethernet connector w/ISDN , North America only	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001091	Single TR & Ethernet connector w/ISDN, North America only	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001092	Single Ethernet connector w/ISDN no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001093	Dual Ethernet connector w/ISDN no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001094	Single TR & Ethernet w/ISDN, no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001098	Dual Ethernet with X.21	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001099	Dual Token Ring and Ethernet w/X.21	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001100	50-user add-on pack	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001101	Single Ethernet connector w/ISDN North American only (includes NT1)	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001102	Single Ethernet connector w/ISDN, no NT1	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001103	Dual Ethernet w/no internal modem.	PASS	N/A	N/A	N/A	
CQ1001104	Single Ethernet connector w/33.6k	PASS	3.22	N/A	N/A	All w/ version 3.22 and above

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CQ1001109	Single Ethernet connector w/56k Flex technology	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001110	Single Ethernet connector w/56k x2 technology	PASS	3.22	N/A	N/A	All w/ version 3.22 and above
CQ1001111	50-user Single Ethernet connector w/ internal K56 Flex/V.90 modem.	PASS	N/A	N/A	N/A	
CQ1001112	Single Ethernet w/ internal V.90 modem.	PASS	N/A	N/A	N/A	
CR0013001	WAN Services for NT	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR0013002	Connections for Windows NT 4.0	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504001	Eicon Card S51 with NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504002	Eicon Card C21 without NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504003	ISDN NT1 Unit for Quadro	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504004	Eicon Diva ISA card with Win 95/3.x/NT, with NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504005	Eicon Diva ISA card with Win95/3.x/NT, without NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504006	Eicon Card S51 without NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504007	ISDN Server for Windows NT Quadro without NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504010	Eicon Diva PCMCIA card with Win 95/3.x/NT, with NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504011	Eicon Diva PCMCIA card with Win 95/3.x/NT, without NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504016	Eicon Card C21 with NT1	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504017	DIVA Pro 2.0 ISA (S/T Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504018	DIVA Pro 2.0 ISA (U Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504019	DIVA Pro 2.0 PCI (S/T Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504020	DIVA Pro 2.0 PCI (U Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504021	DIVA Pro 2.0 PCMCIA (S/T Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CR1504022	DIVA Pro 2.0 PCMCIA (U Interface)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CS0036004	Field Memory Upgrade Kit to 64MB (Use with StackProbes: FE2200, FE2400T and FE2400F H/W rev 3a and above).	PASS	N/A	N/A	rev 3a	
CS0036005	Field Memory Upgrade Kit to 128MB (Use with StackProbes: FE2200, FE2400T and FE2400F H/W rev 3a and above).	PASS	N/A	N/A	rev 3a	
CS0036006	Boot PROM version 6.0.0 upgrade kit for Series 2000 FDDI Optivity StackProbes.	PASS	N/A	N/A	N/A	
CS0036007	Boot PROM version 6.0.1 upgrade kit for Series 2000 Fast Ethernet Optivity StackProbes.	PASS	N/A	N/A	N/A	
CS0036008	Boot PROM version 6.0.1 upgrade kit for WEB PocketProbe model FE1100.	PASS	N/A	N/A	N/A	
CS1036001	E101 - 1 Port Ethernet Probe - 4MB	PASS	N/A	N/A	N/A	
CS1036002	E202 - 2 Port Ethernet Probe - 5MB	PASS	N/A	N/A	N/A	
CS1036003	E404 - 4 Port Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS1036004	E402 - 4 Port (inc. 2 PassThru) Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS1036005	E402 - 4 Port (incl. 2 PassThru) Ethernet StackProbe - 12MB	PASS	N/A	N/A	N/A	
CS1036006	E404 - 4 Port Ethernet Probe - 12MB	PASS	N/A	N/A	N/A	
CS1036007	E101 - 1 Port Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS1036008	E202 - 2 Port Ethernet Probe - 12MB	PASS	N/A	N/A	N/A	
CS1036009	E100 - 1 Port Pocket Ethernet Probe - 4 MB	PASS	N/A	N/A	N/A	
CS1036010	E100-1 Port Pocket Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS1036011	E100 - 1 Port Pocket Ethernet Probe - 16 MB	PASS	N/A	N/A	N/A	
CS1036012	ET1100 - 1 Port Ethernet 10Base-T RMON/RMON2 WEB PocketProbe - 16MB	PASS	N/A	N/A	N/A	
CS1136001	T101 - 1 Port Token Ring Probe - 6MB	PASS	N/A	N/A	N/A	
CS1136002	T202 - 2 Port Token Ring Probe - 8MB	PASS	N/A	N/A	N/A	
CS1136003	T101 - 1 Port Token Ring Probe - 12MB	PASS	N/A	N/A	N/A	
CS1136004	T202 - 2 Port Token Ring Probe - 12MB	PASS	N/A	N/A	N/A	
CS1236001	F100 - 1 Port SAS FDDI Probe - 12MB	PASS	N/A	N/A	N/A	
CS1236002	F200 - 1 Port DAS FDDI Probe - 12MB	PASS	N/A	N/A	N/A	
CS1236003	F100 - 1 Port SAS FDDI Probe - 28MB	PASS	N/A	N/A	N/A	
CS1236004	F200 - 1 Port DAS FDDI Probe - 28MB	PASS	N/A	N/A	N/A	
CS1236005	FD2100 - 1 Port SAS FDDI Probe - 16MB	PASS	N/A	N/A	N/A	
CS1236006	FD2200 - 1 Port SAS FDDI Probe - 16MB	PASS	N/A	N/A	N/A	
CS1336001	FE100 - 1 PassThru Port Fast-Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS1336002	FE200 - 2 PassThru Port Fast-Ethernet Probe - 12MB	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CS1336003	FE100 - 1 PassThru Port Fast-Ethernet Probe - 28MB	PASS	N/A	N/A	N/A	
CS1336004	FE200 - 2 PassThru Port Fast-Ethernet Probe - 28MB	PASS	N/A	N/A	N/A	
CS3235001	OnSite RMON tools, including support for all 9 RMON groups plus internetwork traffic monitoring	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CS3235002	NetReporter, RMON-based trending and reporting applications	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
CS3936001	FE2100 - 1 PassThru Port Fast-Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS3936002	FE2200 - 2 PassThru Ports Fast-Ethernet Probe - 8MB	PASS	N/A	N/A	N/A	
CS3936003	FE2400T - 4 PassThru Ports Fast-Ethernet Probe - 16MB	PASS	N/A	N/A	N/A	
CS3936004	FE2400F - 4 PassThru Ports Fast-Ethernet Probe - 16MB	PASS	N/A	N/A	N/A	
CS3936006	FE1100 - 1 PassThru Port Fast Ethernet 10/100Base-TX RMON/RMON2 WEB	PASS	N/A	N/A	N/A	
CS3936007	Network Analysis Starter Kit - Optivity Analysis for Windows NT and WEB PocketProbe FE1100 Bundle works with Windows/95 or Windows/NT.	PASS	N/A	N/A	N/A	
CS3936008	Network Analysis Starter Kit - Pack of 5 x WEB PocketProbes model FE1100	PASS	N/A	N/A	N/A	
CU1001001	RA6300, EFS, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001002	RA6300, EFS, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001003	RA6300, EFS, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001004	RA6300, EFS, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001005	RA6300, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001006	RA6300, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001007	RA6300, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001008	RA6300, Selfboot, thick, thin & twisted pair Ethernet, 0-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001009	RA6301, EFS, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001010	RA6301, EFS, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001011	RA6301, EFS, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001012	RA6301, EFS, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001013	RA6301, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001014	RA6301, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001015	RA6301, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001016	RA6301, Selfboot, thick, thin & twisted pair Ethernet, 8-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001017	RA6302, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001018	RA6302, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001019	RA6302, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001020	RA6302, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001021	RA6302, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001022	RA6302, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001023	RA6302, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001024	RA6302, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001025	RA6303, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001026	RA6303, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001027	RA6303, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001028	RA6303, EFS, Selfboot, thick, thin & twisted pair Ethernet, 16-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001029	RA6303, Selfboot, thick, thin & twisted pair Ethernet, 24-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001030	RA6303, Selfboot, thick, thin & twisted pair Ethernet, 24-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CU1001031	RA6303, Selfboot, thick, thin & twisted pair Ethernet, 24-Modems, 110V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001032	RA6303, Selfboot, thick, thin & twisted pair Ethernet, 24-Modems, 220V, ISDN/T1	PASS	5.4	N/A	N/A	
CU1001033	RA6304, EFS, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001034	RA6304, EFS, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001035	RA6304, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 110V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001036	RA6304, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 220V, EURO - ISDN/E1	PASS	5.4	N/A	N/A	
CU1001039	RA6000, Software on CD-ROM	PASS	5.4	N/A	N/A	
CU1001040	RA6304, EFS, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 220V, Australia	PASS	5.4	N/A	N/A	
CU1001041	RA6304, Selfboot, thick, thin & twisted pair Ethernet, 32-Modems, 220V, Australia	PASS	5.4	N/A	N/A	
CU1001056	RA6, WF, 220V, EFS, 32- Modems - Malaysia	PASS	5.4	N/A	N/A	
CU1001057	RA6304, Selfboot, thick, thin,& twisted pair Ethernet, 32-Modems, 220V, Singapore. ISDN.	PASS	5.4	N/A	N/A	
CU1004B09	8000,0-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B10	8000,31-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS		N/A	N/A	
CU1004B11	8000,62-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B19	8000,31-Port, with X2 support (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B20	8000,62-Port,with X2 support (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B23	8000,31-Port, with K56Flex support (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B24	8000,62-Port,with K56Flex support (2 PRI or Channelized E1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004B27	Adapteen 8000,0-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B28	Adapteen 8000,31-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B29	Adapteen 8000,62-Port, (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B33	Adapteen 8000,31-Port, with X2 support (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B34	Adapteen 8000,62-Port,with X2 support (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B37	Adapteen 8000,31-Port, with K56Flex support (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004B38	Adapteen 8000,62-Port,with K56Flex support (2 PRI or Channelized E1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E09	8000,0-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E10	8000,24-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E11	8000,48-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E21	8000,24-Port, with X2 support (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E22	8000,48-Port,with X2 support (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E25	8000,24-Port, with K56Flex support (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E26	8000,48-Port,with K56Flex support (2 PRI or Channelized T1) Remote Access Concentrator. Host software and documentation included.	PASS	6	N/A	N/A	
CU1004E30	Adapteen 8000,0-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E31	Adapteen 8000,24-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E32	Adapteen 8000,48-Port, (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CU1004E35	Adapteon 8000,24-Port, with X2 support (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E36	Adapteon 8000,48-Port,with X2 support (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E39	Adapteon 8000,24-Port, with K56Flex support (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CU1004E40	Adapteon 8000,48-Port,with K56Flex support (2 PRI or Channelized T1) Remote Access Concentrator. Includes Hardware Compression, Host Software and documentation.	PASS	6	N/A	N/A	
CV0004001	ARN Serial Adapter Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004002	ARN ISDN BRI S/T Adapter Module (without NT1)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004003	ARN ISDN BRI U Adapter Module (with NT1)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004004	ARN 56/64 DSU/CSU Adapter Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004005	ARN V.34 Modem Adapter Module (North America only)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004011	ARN Tri Serial Expansion Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004012	ARN Ethernet Expansion Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004013	ARN Token Ring Expansion Module *	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004014	ARN Ethernet and Tri-Serial Expansion Module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004015	ARN Token Ring and Tri-Serial Expansion Module *	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004020	ARN V.34 Modem Console Module (North America only)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004021	ARN Ethernet DCM	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CV0004022	ARN X.25 PAD	PASS	N/A	N/A	N/A	
CV0004023	ARN T1/FT1 DSU/CSU Adapter Module (North America only) **	PASS	N/A	N/A	N/A	
CV0004024	ARN E1/FE1 Adapter Module (RJ)	PASS	N/A	N/A	N/A	
CV0004025	ARN E1/FE1 Adapter Module (BNC)	PASS	N/A	N/A	N/A	
CV0004026	ARN Ethernet and 7-Serial Expansion Module	PASS	N/A	N/A	N/A	
CV0004027	ARN 7-Serial Expansion Module	PASS	N/A	N/A	N/A	
CV0004042	ARN Ethernet and 7-Serial Expansion Module	PASS	N/A	N/A	N/A	
CV0004043	ARN 7-Serial Expansion Module	PASS	N/A	N/A	N/A	
CV0008001	IP Access Suite (4M PCMCIA) includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008001	IP Access Suite includes V11.03 Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI.	PASS	v11.03	N/A	N/A	
CV0008002	Remote Office Suite (4M PCMCIA) includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008002	Remote Office Suite V11.03 includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk.	PASS	v11.03	N/A	N/A	
CV0008003	Corporate Suite (4M PCMCIA) includes all Version 11.0 Software	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008003	Corporate Suite includes all Version 11.03 Software	PASS	v11.03	N/A	N/A	
CV0008004	IP Access Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008004	IP Access Suite V11.03 Software	PASS	v11.03	N/A	N/A	
CV0008005	Remote Office Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008005	Remote Office Suite V11.03 Software.	PASS	v11.03	N/A	N/A	
CV0008006	Corporate Suite (8M PCMCIA)	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008006	Corporate Suite includes all V11.03 Software	PASS	v11.03	N/A	N/A	
CV0008007	Version 11.0 Corporate Suite Additional Protocols - CD-ROM	FAIL	11.x	N/A	N/A	Upgrade to BayRS v11.03 Rev5 or BayRS 12.0 Rev2, to be Year 2000 compliant.
CV0008007	Version 11.03 Corporate Suite Additional Protocols*	PASS	v11.03	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CV0008008	IP Access Suite (4M PCMCIA) V12.0 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008009	Remote Office Suite (4M PCMCIA) V12.0 includes IP Access plus DLSw for Ethernet, Token Ring, and SDLC, IPX, AppleTalk	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008011	IP Access Suite (8M PCMCIA) 12.0	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008012	Remote Office Suite (8M PCMCIA) 12.0	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008013	Corporate Suite (8M PCMCIA) includes all V12.0 Software	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008015	IP Access Suite (16M PCMCIA) 12.0	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008016	Remote Office Suite (16M PCMCIA) 12.0	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008017	Corporate Suite (16M PCMCIA) includes all V12.0 Software	FAIL	12.01	N/A	N/A	Upgrade to BayRS 12.0 Rev2 release available by 1/1/98, to be Year2000 compliant.
CV0008019	BaySecure Firewall - 1 Agent License for BayStack ARN Systems. Requires Version 12.10 or higher.	PASS	v12.10	N/A	N/A	
CV0008020	IP Access Suite (8M PCMCIA) 12.10	PASS	12.2	N/A	N/A	
CV0008020	IP Access Suite (8M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
CV0008021	Remote Office Suite (8M PCMCIA) 12.10	PASS	12.2	N/A	N/A	
CV0008021	Remote Office Suite (8M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
CV0008022	Corporate Suite (8M PCMCIA) includes all V12.10 Software	PASS	12.2	N/A	N/A	
CV0008022	Corporate Suite (8M PCMCIA) includes all V12.20 Software.	PASS	v12.20	N/A	N/A	
CV0008023	IP Access Suite (16M PCMCIA) 12.10	PASS	12.2	N/A	N/A	
CV0008023	IP Access Suite (16M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
CV0008024	Remote Office Suite (16M PCMCIA) 12.10	PASS	12.2	N/A	N/A	
CV0008024	Remote Office Suite (16M PCMCIA) 12.20.	PASS	v12.20	N/A	N/A	
CV0008025	Corporate Suite (16M PCMCIA) includes all V12.10 Software	PASS	12.2	N/A	N/A	
CV0008025	Corporate Suite (16M PCMCIA) includes all V12.20 Software.	PASS	v12.20	N/A	N/A	
CV0008026	Version 12.10 Corporate Suite Additional Protocols - CD-ROM*	PASS	v12.10	N/A	N/A	
CV0008026	Version 12.20 Corporate Suite Additional Protocols - CD-ROM*	PASS	v12.20	N/A	N/A	
CV0008027	IP Access Suite (4M PCMCIA) V12.10 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI	PASS	v12.10	N/A	N/A	
CV0008027	IP Access Suite (4M PCMCIA) V12.10 includes Bridge, IP, WF HDLC Encapsulation, PPP, Frame Relay, ISDN BRI, Dial Back-Up, Dial on Demand, Data Compression, Traffic Prioritization and Filters, X.25, LapB, SMDS and ATM DXI.	PASS	N/A	N/A	N/A	
CV0008029	IP Access Suite (8M PCMCIA) 13.0	PASS	v13.0	N/A	N/A	
CV0008030	Remote Office Suite (8M PCMCIA) 13.0	PASS	v13.0	N/A	N/A	
CV0008031	Corporate Suite (8M PCMCIA) includes all V13.0 Software	PASS	v13.0	N/A	N/A	
CV0008032	IP Access Suite (16M PCMCIA) 13.0	PASS	v13.0	N/A	N/A	
CV0008033	Remote Office Suite (16M PCMCIA) 13.0	PASS	v13.0	N/A	N/A	
CV0008034	Corporate Suite (16M PCMCIA) includes all V13.0 Software	PASS	v13.0	N/A	N/A	
CV0008035	Version 13.0 Corporate Suite Additional Protocols - CD-ROM**	PASS	v13.0	N/A	N/A	
CV0008038	IP Access Suite (8M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
CV0008039	Remote Office Suite (8M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
CV0008040	Corporate Suite (8M PCMCIA) includes all V13.10 Software.	PASS	v13.10	N/A	N/A	
CV0008041	IP Access Suite (16M PCMCIA) 13.10.	PASS	v13.10	N/A	N/A	
CV0008042	Remote Office Suite (16M PCMCIA) 13.10	PASS	v13.10	N/A	N/A	
CV0008043	Corporate Suite (16M PCMCIA) includes all V13.10 Software.	PASS	v13.10	N/A	N/A	
CV0008044	Version 13.10 Corporate Suite Additional Protocols - CD-ROM.	PASS	v13.10	N/A	N/A	
CV0008045	DES - 56 IPSEC Option for BayStack ARN System Software Version 13.10	PASS	v13.10	N/A	N/A	
CV0008046	IP Access Suite (8M PCMCIA) 13.20.	PASS	N/A	N/A	N/A	
CV0008047	Remote Office Suite (8M PCMCIA) 13.20.	PASS	N/A	N/A	N/A	
CV0008047	Remote Office Suite (8M PCMCIA) 13.20.	PASS	N/A	N/A	N/A	
CV0008048	Corporate Suite (8M PCMCIA) includes all V13.20 Software.	PASS	N/A	N/A	N/A	
CV0008048	Corporate Suite (8M PCMCIA) includes all V13.20 Software.	PASS	N/A	N/A	N/A	
CV0008049	IP Access Suite (16M PCMCIA) 13.20.	PASS	N/A	N/A	N/A	
CV0008049	IP Access Suite (16M PCMCIA) 13.20.	PASS	N/A	N/A	N/A	
CV0008050	Remote Office Suite (16M PCMCIA) 13.20	PASS	N/A	N/A	N/A	
CV0008050	Remote Office Suite (16M PCMCIA) 13.20	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CV0008051	Corporate Suite (16M PCMCIA) includes all V13.20 Software.	PASS	N/A	N/A	N/A	
CV0008051	Corporate Suite (16M PCMCIA) includes all V13.20 Software.	PASS	N/A	N/A	N/A	
CV0008052	3DES - IPSEC Option for BayStack ARN System Software Version 13.20.	PASS	N/A	N/A	N/A	
CV0008053	Version 13.20 Corporate Suite Additional Protocols - CD-ROM (See Note 1)	PASS	N/A	N/A	N/A	
CV0008054	ARN Version 11.03 Upgrade Kit -CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
CV0008055	DES - 56 IPSEC Option for BayStack ARN System Software Version 13.20, 13.10.	PASS	N/A	N/A	N/A	
CV0011001	ARN Serial Adapter Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011002	ARN ISDN BRI S/T Adapter Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011003	ARN ISDN BRI U Adapter Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011004	ARN 56/64 DSU/CSU Adapter Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011005	ARN V.34 Modem Adapter Module (North America Only) Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011011	ARN Tri Serial Expansion Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011012	ARN Ethernet Expansion Module Field Upgrade Spare	PASS	12.2	N/A	N/A	
CV0011013	ARN Token Ring Expansion Module Field Upgrade/Spare *	PASS	12.2	N/A	N/A	
CV0011014	ARN Ethernet Tri-Serial Expansion Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011015	ARN Token Ring Tri-Serial Expansion Module Field Upgrade/Spare *	PASS	12.2	N/A	N/A	
CV0011020	ARN V.34 Modem Console Module Field Upgrade/Spare	PASS	12.2	N/A	N/A	
CV0011021	ARN Ethernet DCM Module Field Upgrade/Spare (North America only)	PASS	12.2	N/A	N/A	
CV0011027	32M DRAM	PASS	N/A	N/A	N/A	
CV0011028	BayStack ARN Ethernet Base (0M DRAM) Chassis Spare	PASS	N/A	N/A	N/A	
CV0011033	ARN X.25 PAD Field Upgrade/Spare **	PASS	12.2	N/A	N/A	
CV0011034	ARN T1/FT1 DSU/CSU Adapter Module (North America only) Field Upgrade/Spare**	PASS	12.2	N/A	N/A	
CV0011036	ARN X.25 PAD 8-port Breakout Box ONLY Upgrade/Spare **	PASS	12.2	N/A	N/A	
CV0013035	ARN X.25 PAD Module ONLY Upgrade/Spare **	PASS	12.2	N/A	N/A	
CV1001001	BayStack ARN Ethernet Base Unit (0M DRAM)	PASS	12.2	N/A	N/A	
CV1001002	BayStack ARN Ethernet Base Unit (4M DRAM)	PASS	12.2	N/A	N/A	
CV1001003	BayStack ARN Ethernet Base Unit (8M DRAM)	PASS	12.2	N/A	N/A	
CV1001004	BayStack ARN Ethernet Base Unit (16M DRAM)	PASS	12.2	N/A	N/A	
CV1001005	BayStack ARN Ethernet Base Unit (32M DRAM)	PASS	12.2	N/A	N/A	
CV1001008	BayStack ARN -48VDC Ethernet Base Unit (8M DRAM)	PASS	12.2	N/A	N/A	
CV1001008	BayStack ARN -48VDC Ethernet Base Unit (8M DRAM)	PASS	N/A	N/A	N/A	
CV1001009	BayStack ARN -48VDC Ethernet Base Unit (16M DRAM)	PASS	12.2	N/A	N/A	
CV1001009	BayStack ARN -48VDC Ethernet Base Unit (16M DRAM)	PASS	N/A	N/A	N/A	
CV1001010	BayStack ARN -48VDC Ethernet Base Unit (32M DRAM)	PASS	12.2	N/A	N/A	
CV1001010	BayStack ARN -48VDC Ethernet Base Unit (32M DRAM)	PASS	N/A	N/A	N/A	
CV1001013	BayStack ARN 10/100M-TX UTP Base Unit (8M DRAM)	PASS	12.2	N/A	N/A	
CV1001014	BayStack ARN 10/100M-TX UTP Base Unit (16M DRAM)	PASS	12.2	N/A	N/A	
CV1001015	BayStack ARN 10/100M-TX UTP Base Unit (32M DRAM)	PASS	12.2	N/A	N/A	
CV1001018	BayStack ARN 100M-FX Fiber Base Unit (8M DRAM)	PASS	12.2	N/A	N/A	
CV1001019	BayStack ARN 100M-FX Fiber Base Unit (16M DRAM)	PASS	12.2	N/A	N/A	
CV1001020	BayStack ARN 100M-FX Fiber Base Unit (32M DRAM)	PASS	12.2	N/A	N/A	
CV1101001	BayStack ARN Token Ring Base Unit (0M DRAM)	PASS	12.2	N/A	N/A	
CV1101003	BayStack ARN Token Ring Base Unit (8M DRAM)	PASS	12.2	N/A	N/A	
CV1101004	BayStack ARN Token Ring Base Unit (16M DRAM)	PASS	12.2	N/A	N/A	
CV1101005	BayStack ARN Token Ring Base Unit (32M DRAM)	PASS	12.2	N/A	N/A	
CW2001001	BayStack 301 Ethernet Switch with 22 Switched 10BASE-T Ports and 2 Switched 10BASE-T/100BASE-TX Ports.	PASS	2.1	N/A	N/A	
CX0001001	5005N-8 Slot Ethernet Chassis with one 5391 Remote Access Channelized T1	PASS	5.4	N/A	N/A	
CX0001002	5005N-8 Slot Ethernet Chassis with two 5391 Remote Access Channelized T1	PASS	5.4	N/A	N/A	
CX0001003	5005N-8 Slot Ethernet Chassis with three 5391 Remote Access Channelized T1	PASS	5.4	N/A	N/A	
CX0001004	5000N-14 Slot Ethernet Chassis With four 5391 Remote Access Channelized T1 Modules with 96 V.34 integrated Modems.	PASS	5.4	N/A	N/A	
CX0001005	5000N-14 Slot Ethernet Chassis With five 5391 Remote Access Channelized T1	PASS	5.4	N/A	N/A	
CX0001006	5000N-14 Slot Ethernet Chassis With six 5391 Remote Access Channelized T1 Modules with 144 V.34 integrated Modems.	PASS	5.4	N/A	N/A	
CX0001007	5000N-14 Slot Ethernet Chassis with one 5391 Remote Access Channelized T1 Module with 24 V.34 integrated modems.	PASS	5.4	N/A	N/A	
CX0001008	5000N-14 Slot Ethernet Chassis with two 5391 Remote Access Channelized T1 with 48 V.34 integrated modems.	PASS	5.4	N/A	N/A	
CX0001009	5000N-14 Slot Ethernet Chassis with three 5391 Remote Access Channelized T1 with 72 V.34 integrated modems.	PASS	5.4	N/A	N/A	
CX1001002	5390FE Remote Annex Base Unit	PASS	4.2	N/A	N/A	
CX1004002	5391 Remote Access Channelized T1, T1 CSU/DSU, T1 multiplexor, Multi-processor Remote Access Module with 24 Channels, 24 Modems. Includes Software, CD Rom, and Documentation	PASS	4.2	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
CX1004004	5393 RA Module,Single Slot Digital Only, ISDN/PRI ,0 Modem, T1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004005	5393 RA Module,Single Slot Digital Only, ISDN/PRI ,0 Modem, E1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004006	5393 RA Module,Single Slot Digital Only, ISDN/PRI ,0 Modem, Austel. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004007	5393 RA Module, Dual Slot, ISDN/PRI ,24 Modem, T1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004008	5393 RA Module, Dual Slot, ISDN/PRI ,32 Modem, E1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004009	5393 RA Module, Dual Slot, ISDN/PRI ,32 Modem, Austel. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004010	5393 RA Module, 24 Modem Upgrade, T1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004011	5393 RA Module, 32 Modem Upgrade, E1. Includes Software,CD Rom, and Documentation	PASS	5.4	N/A	N/A	
CX1004019	48 Bay DSP Modem Upgrade Kit for North America (T1) Upgrades CX1004E21 TO CX1004E22.	PASS	5.4	N/A	N/A	
CX1004020	60 Bay DSP Modem Upgrade Kit for (International) Upgrades CX1004B21 TO CX1004B23.	PASS	5.4	N/A	N/A	
CX1004030	Hardware Compression Card Upgrade for 5399 and Remote Access Concentrators	PASS	5.4	N/A	N/A	
CX1004035	Hardware Compression Card for 8000 Remote Access Concentrators	PASS	5.4	N/A	N/A	
CX1004B21	Model 5399 Dual WAN (PRI or Channelized E1) Remote Access Concentrator without Bay DSP modems. Host software and documentation included.	PASS	6	N/A	N/A	
CX1004B23	Model 5399 Dual WAN (PRI or Channelized E1) Remote Access Concentrator with 60 Bay DSP modems. Host software and documentation included.	PASS	6	N/A	N/A	
CX1004B31	Model 5399 Dual WAN W/X2 (PRI or Channelized E1) Remote Access Concentrator with 62 Bay DSP Modems. Host Software and documentation included	PASS	6	N/A	N/A	
CX1004B37	Adapteon 5399 Dual WAN (PRI or Channelized E1) Remote Access Concentrator with 62 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004B40	Adapteon 5399 Dual WAN W/X2 (PRI or Channelized E1) Remote Access Concentrator with 62 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004B42	Adapteon 5399 Dual WAN W/K56Flex (PRI or Channelized E1) Remote Access Concentrator with 62 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004E21	Model 5399 Dual WAN (PRI or Channelized T1) Remote Access Concentrator without Bay DSP modems. Host software and documentation included.	PASS	6	N/A	N/A	
Cx1004E22	5399 Dual Wan 48 modems s/w included	PASS	6	N/A	N/A	
CX1004E32	Model 5399 Dual WAN W/X2 (PRI or Channelized E1) Remote Access Concentrator with 48 Bay DSP Modems. Host Software and documentation included	PASS	6	N/A	N/A	
CX1004E38	Adapteon 5399 Dual WAN (PRI or Channelized T1) Remote Access Concentrator without Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004E39	Adapteon 5399 Dual WAN (PRI or Channelized T1) Remote Access Concentrator with 48 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004E41	Adapteon 5399 Dual WAN W/X2 (PRI or Channelized T1) Remote Access Concentrator with 48 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CX1004E43	Adapteon 5399 Dual WAN W/K56Flex (PRI or Channelized T1) Remote Access Concentrator with 48 Bay DSP modems. Includes Hardware Compression,Host Software and documentation.	PASS	6	N/A	N/A	
CY0011001	Rack Mount Kit for BayStack Model 30T and Model 30F Fast Ethernet Converters.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CY2012001	Model 30T switch-based Fast Ethernet Converter with two configurable 10BASE-T/100BASE-TX ports	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CY3112001	Model 30F switch-based Fast Ethernet Media Converter with one configurable 10BASE-T/100BASE-TX port and one 100BASE-FX port.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
CZ1001001	BayStack Web Cache, stand-alone web cache appliance, 64MB RAM, 4.3GB Hard Disk Drive, Dual Auto-Sensing 10/100MB Ethernet Interfaces	PASS	N/A	N/A	N/A	
DA0011001	CLAM Bridge to Corporate Software Upgrade. Consists of software on 3.5" diskettes and manual.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA0011002	CLAM Router to Bridge Software Upgrade. Consists of software on 3.5" diskettes and manual.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA0011003	Nautica 200 IP Router Software.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DA1501?05	CLAM 850 Bridge. Includes: CLAM hardware equipped with Bridge software; integral ISDN BRI interface card(S/T Interface); ISDN cable; 10BaseT LAN cable, DB9 adapter for management connection; AC adapter; and manual.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?06	CLAM 850 Router. Includes: CLAM hardware equipped with Router software; integral ISDN BRI interface card(S/T Interface); ISDN cable; 10BaseT LAN cable, DB9 adapter for management connection; AC adapter; and manual.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?07	CLAM 854 Bridge with Voice same as DA1501X05 but with addition of the Voice card.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?08	CLAM 854 Router with Voice same as DA1501X06 but with addition of the Voice card.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?09	CLAM 820 TCP/IP, ISDN Router. Similar to CLAM 850 (DA1501X06) but TCP/IP routing only	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?10	CLAM 824 TCP/IP ISDN Router with Voice Similar to CLAM 854 (DA1501X08) but TCP/IP routing only	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?14	Nautica 200 TCP/IP Router. Single Basic rate ISDN S/T Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, Power Supply and manual on CD-ROM. (European version)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501?16	Nautica 250 TCP/IP Router. Single Basic rate ISDN S/T Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, Power Supply and manual on CD-ROM.	PASS	N/A	N/A	N/A	
DA1501B18	Nautica 250 TCP/IP Router. Single Basic rate ISDN S/T Interface with Ipsec Software. Includes NauticaRS 5.5, Nautica Watch, Nautica Wizard, Nautica Bridge and doc on CD-ROM. (Northern Europe)	PASS	N/A	N/A	N/A	
DA1501C18	Nautica 250 TCP/IP Router. Single Basic rate ISDN S/T Interface with Ipsec Software. Includes NauticaRS 5.5, Nautica Watch, Nautica Wizard, Nautica Bridge and doc on CD-ROM. United Kingdom. (United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
DA1501D14	Nautica 200 TCP/IP Router. Single Basic rate ISDN S/T Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, Power Supply and manual on CD-ROM.	PASS	N/A	N/A	N/A	
DA1501E02	CLAM 860 Router. Same as CLAM 850 Router for North America but with Internal NT-1.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501E04	CLAM 864 Router. Same as CLAM 854 Router for North America but with Internal NT-1.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501E14	NAUTICA 200 base system with ISDN BRI S/T interface.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501E15	Nautica 200 TCP/IP Router. Single Basic rate ISDN U Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, AC Power Supply and manual on CD-ROM. (North American version)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501E15	NAUTICA 200 base system with ISDN BRI U interface (for use in USA only).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA1501E17	Nautica 250 TCP/IP Router. Single Basic rate ISDN U Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, AC Power Supply and manual on CD-ROM. (North American version)	PASS	N/A	N/A	N/A	
DA1501E19	Nautica 250 TCP/IP Router. Single Basic rate ISDN U Interface with Ipsec Software. Includes NauticaRS 5.5, Nautica Watch, Nautica Wizard, Nautica Bridge and doc on CD-ROM. North America (North America)	PASS	N/A	N/A	N/A	
DA1501F14	Nautica 200 TCP/IP Router. Single Basic rate ISDN S/T Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, Power Supply and manual on CD-ROM.	PASS	N/A	N/A	N/A	
DA1501F16	Nautica 250 TCP/IP Router. Single Basic rate ISDN S/T Interface. Two analog voice ports. Single 10BaseT port. Manager port. Includes ISDN cable, 10BaseT cable, management cable, Power Supply and manual on CD-ROM. (Australia)	PASS	N/A	N/A	N/A	
DA3501?01	CLAM 841 WAN Router X.21 Interface (incl Frame Relay Release 3 Routing Software WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?02	CLAM 842 WAN Router V.24 Interface (incl Frame Relay Release 3 Routing Software WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?03	CLAM 843 WAN Router V.35 Interface (incl Frame Relay Release 3 Routing Software WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?04	CLAM 851 ISDN (S/T Interface) and WAN Router X.21 Interface (incl Frame Relay Release 3 Routing Software, WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?05	CLAM 852 ISDN (S/T Interface) and WAN Router V.24 Interface (incl Frame Relay Release 3 Routing Software WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?06	CLAM 853 ISDN (S/T Interface) and WAN Router V.35 Interface (incl Frame Relay Release 3 Routing Software, WAN cable not included)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?10	CLAM 811 WAN Router X.21 interface TCP/IP Routing only. (similar to DA3501X01 incl TCP/IP, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?11	CLAM 812 WAN Router V.24 interface TCP/IP Routing only. (similar to DA3501X02 incl TCP/IP, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DA3501?12	CLAM 813 WAN Router V.35 interface TCP/IP Routing only. (similar to DA3501X03 incl TCP/IP, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?13	CLAM 821 TCP/IP ISDN Router (S/T Interface) and WAN X.21 interface. (similar to DA3501X04 incl TCP/IP routing only, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?14	CLAM 822 TCP/IP ISDN Router (S/T Interface) and WAN V.24 interface. (similar to DA3501X05 incl TCP/IP routing only, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501?15	CLAM 823 TCP/IP ISDN Router (S/T Interface) and WAN V.35 interface. (similar to DA3501X06 incl TCP/IP routing only, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501E08	CLAM 862 ISDN (U interface) and WAN Router V.24 Interface. Includes Frame Relay Routing Software. WAN cable not included.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501E09	CLAM 863 ISDN (U interface) and WAN Router V.35 Interface. Includes Frame Relay Routing Software. WAN cable not included.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501E17	CLAM 832 TCP/IP ISDN Router (U Interface) and WAN V.24 interface. (incl TCP/IP routing only, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501E18	CLAM 833 TCP/IP ISDN Router (U Interface) and WAN V.35 interface. (incl TCP/IP routing only, Frame Relay, WAN cable not included).	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3501T18	CLAM 833 TCP/IP ISDN and WAN Router. Small Office Home Office Router, ISDN BRI (U), single V.35 x 10BaseT. Supports IP routing, Frame Relay, PPP leased line and dial PPP. Includes current version NauticaRS, 10BaseT cable, management cable, AC power sup	PASS	N/A	N/A	N/A	
DA3711001	CLAM Bridge Voice Upgrade Card, USA (mu-law)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3711002	CLAM Bridge Voice Upgrade Card, Euro (A-law)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3711003	CLAM Router Voice Upgrade Card, USA (mu-law)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DA3711004	CLAM Router Voice Upgrade Card, Euro (A-law)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB0002?01	Nautica 4000 base system	PASS	N/A	N/A	N/A	
DB0002D01	Factory Configurable Nautica 4000 base system	PASS	N/A	N/A	N/A	
DB0002F01	Factory Configurable Nautica 4000 base system	PASS	N/A	N/A	N/A	
DB0004001	Nautica 4000 Expansion module. Supports 2 base modules, each 4000 base system supports 2 Expansion modules. European version.	PASS	N/A	N/A	N/A	
DB0004002	Nautica 4000 Expansion module. Supports 2 base modules, each 4000 base system supports 2 Expansion modules. North American version.	PASS	N/A	N/A	N/A	
DB0004003	Factory Configurable 16 MB Memory Upgrade for Nautica 4000.	PASS	N/A	N/A	N/A	
DB0011002	NAUTICA Radius Secure Authentication Server Software for Windows '95	PASS	N/A	N/A	N/A	
DB0011003	NAUTICA Micromanager for Windows	PASS	N/A	N/A	N/A	
DB0011004	MARLIN Bridge to Router Software Upgrade (all models). Consists of software on 3.5" diskettes and manuals.	FAIL	v4.1	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB0011005	MARLIN Router to Bridge Software Upgrade (all models). Consists of software on 3.5" diskettes and manuals.	FAIL	v4.1	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB0011011	Field/Upgrades Spare Nautica 4000 Expansion module. Supports 2 base modules, each 4000 base system supports 2 Expansion modules. European version.	PASS	N/A	N/A	N/A	
DB0011013	Field/Upgrade Spare Nautica 4000 Expansion module. Supports 2 base modules, each 4000 base system supports 2 Expansion modules. North American version.	PASS	N/A	N/A	N/A	
DB0011014	Nautica Router Software Upgrade for Nautica 200, CLAM, Marlin, and Nautica 4000, and Nautica Bridge Software Upgrade for CLAM and Marlin Only.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB0011015	Field Upgrade/Spare 16MB Memory Upgrade for Nautica 4000.	PASS	N/A	N/A	N/A	
DB0011016	Nautica Router Software Upgrade to Ipsec for Nautica 250 and Nautica 4000. Includes NauticaRS 5.5 with support for IPsec, Nautica Watch, Nautica Wizard and documentation on CD-ROM. (See Note 1)	PASS	N/A	N/A	N/A	
DB0011D12	Field Upgrade/Spare Nautica 4000 base system.	PASS	N/A	N/A	N/A	
DB0011F12	Field Upgrade/Spare Nautica 4000 base system.	PASS	N/A	N/A	N/A	
DB1001?02	MARLIN 1000 Bridge/X.21, with a single X.21 WAN port operating to E1 speeds and a single LAN port (both AUI and 10BaseT connectors). Incl.: Bridge sw; X.21 cable; mgmt cable with DB9 and DB25 interfaces; power cable; manual.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1001?03	MARLIN 1000 Router/X.21. Same as MARLIN 1000 Bridge/X.21, but with Router software.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1001?04	MARLIN 1000 Bridge/V.35, with a single V.35 WAN port operating to T1 speeds and a single LAN port (both AUI and 10BaseT connectors provided). Incl.: Bridge sw; V.35 cable; mgmt cable with DB9 and DB25 interfaces; power cable; manual.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1001?05	MARLIN 1000 Router/V.35. Same as ML1000-NA/B, but with Router software.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DB1501706	MARLIN 2100 Bridge/X.21. Same as MARLIN 1000 Bridge/X.21 but with an ISDN BRI module and ISDN cable. BRI module fits on motherboard. Two 64 kbps B channels supported.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501707	MARLIN 2200 Bridge/X.21. Same as MARLIN 1000 Bridge/X.21 but with 2 ISDN BRI modules and ISDN cables. Incl. MARLIN BRI expansion card equipped w/ 1 BRI module and fitting kit. Other BRI module fits on motherboard. Four 64 kbps B channels supported.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501708	MARLIN 2300 Bridge/X.21. As MARLIN 1000 Bridge/X.21 but with 3 ISDN BRI modules and ISDN cables. Incl. MARLIN BRI expansion card with 2 BRI modules, blanking plate and support. Other BRI module fits on motherboard. Six 64 kbps B channels supported.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501709	MARLIN 2100 Router/X.21. Same as MARLIN 2100 Bridge/X.21, but with Router software.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501710	MARLIN 2200 Router/X.21. Same as MARLIN 2200 Bridge/X.21, but with Router software.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501711	MARLIN 2300 Router/X.21. Same as MARLIN 2300 Bridge/X.21, but with Router software.*	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501712	MARLIN 2100 Bridge/V.35. Same as MARLIN 1000 Bridge but with an ISDN BRI module and ISDN cable. BRI module fits on motherboard. Two 64 kbps B channels supported.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501713	MARLIN 2200 Bridge/V.35. Same as MARLIN 1000 Bridge/V.35 but with 2 ISDN BRI modules and ISDN cables. Incl. MARLIN BRI expansion card equipped w/ 1 BRI module and fitting kit. Other BRI module fits on motherboard. Four 64 kbps B channels supported.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501714	MARLIN 2300 Bridge/V.35. As MARLIN 1000 Bridge/V.35 but with 3 ISDN BRI modules and ISDN cables. Incl. MARLIN BRI expansion card with 2 BRI modules, blanking plate and support. Other BRI module fits on motherboard. Six 64 kbps B channels supported.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product.
DB1501715	MARLIN 2100 Router/V.35. Same as MARLIN 2100 Bridge/V.35, but with Router software.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501716	MARLIN 2200 Router/V.35. Same as MARLIN 2200 Bridge/V.35, but with Router software.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501717	MARLIN 2300 Router/V.35. Same as MARLIN 2300 Bridge/V.35, but with Router software.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant.
DB1501718	MARLIN 3000 Router/X.21. 30 channel PRI in Europe. 23 channel PRI/excludes CSU in North America.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant. Product Discontinued July 1997.
DB1501723	MARLIN 3000 Bridge/X.21. 30 channel PRI in Europe. 23 channel PRI/excludes CSU in North America.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product. Discontinued July 1997.
DB1501724	Nautica 4000 preconfigured system. 4 BRI-S/T base modules. ETSI ISDN. Includes Power cord	PASS	N/A	N/A	N/A	
DB1501726	Nautica 4000 preconfigured system. 4 BRI-S/T modules. 8 modems. ETSI ISDN. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501001	MARLIN 3000 Router/V.35 fitted with PRI module 23 CH US version only, excluding CSU.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant. Product Discontinued July 1997.
DB1501030	Nautica 4000 preconfigured system. 4 BRI-U base modules (Internal NT-1). North American ISDN. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501031	Nautica 4000 preconfigured system. 4 BRI-U modules (Internal NT-1). 8 modems. North American ISDN. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501034	Nautica 4000 preconfigured system, Ethernet, 1 PRI-30 base module, 20Mb DRAM, includes power cord. Europe only.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1501035	Nautica 4000 preconfigured system, Ethernet, 1 PRI-30 base module, 20Mb DRAM, includes power cord. UK only.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1501036	Nautica 4000 preconfigured system. Ethernet, 1 PRI-23 base module with internal CSU, 20 Mb DRAM, includes power cord. North America only.	PASS	N/A	N/A	N/A	
DB1501037	Nautica 4000 preconfigured system. Ethernet, 1 PRI-30 base module, 8 modems, 20 Mb DRAM, includes power cord. Europe only.	PASS	N/A	N/A	N/A	
DB1501038	Nautica 4000 preconfigured system. Ethernet, 1 PRI-30 base module, 8 modems, 20 Mb DRAM, includes power cord. UK only.	PASS	N/A	N/A	N/A	
DB1501039	Nautica 4000 preconfigured system. Ethernet, 1 PRI-23 base module with internal CSU, 8 modems, 20 Mb DRAM, includes power cord. North America only.	PASS	N/A	N/A	N/A	
DB1501D24	Nautica 4000 preconfigured system. 4 BRI-S/T base modules. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501D26	Nautica 4000 preconfigured system. 4 BRI-S/T modules. 8 modems. Includes Power cord.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DB1501E19	MARLIN 3000 Router/V.35 fitted with PRI module 23 CH US version only. (includes external CSU not approved for use in Canada)	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica 4.123R router image, available by 1/21/98, to be Year2000 compliant. Product Discontinued July 1997.
DB1501E21	Marlin 3000 Bridge/V.35 with PRI module 23 CH, excluding external CSU.	FAIL	v4.x	N/A	N/A	Upgrade to the Nautica bridge image 4.37R Product. Discontinued July 1997.
DB1501F24	Nautica 4000 preconfigured system. 4 BRI-S/T base modules. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501F26	Nautica 4000 preconfigured system. 4 BRI-S/T modules. 8 modems. Includes Power cord.	PASS	N/A	N/A	N/A	
DB1501F40	Nautica 4000 preconfigured system. Ethernet, 1 PRI-30 base module, 8 modems, 20 Mb DRAM, includes power cord. Australia only.	PASS	N/A	N/A	N/A	
DB1501F41	Nautica 4000 preconfigured system, Ethernet, 1 PRI-30 base module, 20Mb DRAM, includes power cord. Australia only.	PASS	N/A	N/A	N/A	
DB1504001	European "S/T" BRI base module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1504002	North American "S/T" BRI base module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1504003	North American "U" BRI base module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1504004	Factory Configurable Australian "S/T" BRI base module	PASS	N/A	N/A	N/A	
DB1504006	Factory Configurable Nautica 30 channel ETSI PRI module for Europe.	PASS	N/A	N/A	N/A	
DB1504007	Factory Configurable Nautica 23 channel PRI module with internal CSU for North America.	PASS	N/A	N/A	N/A	
DB1504008	Factory Configurable Nautica 30 channel Austel PRI module for Australia.	PASS	N/A	N/A	N/A	
DB1511704	MARLIN 1000 to 2100 upgrade, to support two 64 kbps B channels. Consists of one BRI module (fits on motherboard) and one ISDN cable.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1511705	MARLIN 2100 to 2200 upgrade, to support an additional two 64 kbps B channels (making four in total). Consists of MARLIN BRI expansion card equipped with one BRI module, blanking plate and support, and one ISDN cable.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1511706	MARLIN 2100 to 2300 upgrade, to support an additional four 64 kbps B channels (making six in total). Consists of MARLIN BRI expansion card equipped with two BRI modules, blanking plate and support, and two ISDN cables.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1511707	MARLIN 2200 to 2300 upgrade, to support an additional two 64 kbps B channels (making six in total). Consists of BRI module to add to already installed MARLIN BRI expansion card, replacement blanking plate, and one ISDN cable.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1511003	MARLIN 3000 PRI Software Channel Upgrade Key (per single Channel)	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
DB1511008	MARLIN 3000 PRI module 23 CH, Upgrade Card, US version. (Includes external CSU not approved for use in Canada)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued July 1997.
DB1511009	MARLIN 3000 PRI module 30 CH, NET5 Card (Pan-European version)	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued July 1997.
DB1511022	MARLIN 3000 PRI module 23 CH, Upgrade Card, US version. External CSU n	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued July 1997.
DB1511030	Field Upgrade/Spare Australian "S/T" BRI base module	PASS	N/A	N/A	N/A	
DB1511031	Field Upgrade/Spare Japanese "S/T" BRI base module	PASS	N/A	N/A	N/A	
DB1511032	Field Upgrade/Spare Quad Modem expansion module. Expansion from 8 to 12 or 12 to 16 modems. For all countries.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB1511033	Field Upgrade/Spare Nautica 30 channel ETSI PRI module for Europe.	PASS	N/A	N/A	N/A	
DB1511034	Field Upgrade/Spare Nautica 23 channel PRI module with internal CSU for North America.	PASS	N/A	N/A	N/A	
DB1511035	Field Upgrade/Spare Nautica 30 channel Austel PRI module for Australia.	PASS	N/A	N/A	N/A	
DB2104001	Factory Configurable Nautica WAN Module - V.35	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB2104002	Factory Configurable Nautica WAN Module - V.11	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB2104003	Factory Configurable Nautica WAN Module - V.24	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB2104005	Factory Configurable Modular QUAD WAN Module - V.11.	PASS	N/A	N/A	N/A	
DB2111001	MARLIN WAN4 Upgrade V.24, 4 port wide area card operating up to aggregate 2 Mbps throughput. Includes custom cable	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued December 1997.
DB2111002	MARLIN WAN4 Upgrade V.35, 4 port wide area card operating up to aggregate 2 Mbps throughput. Includes custom cable	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued December 1997.
DB2111003	MARLIN WAN4 Upgrade V.11, 4Port wide area card operating up to aggregate 2Mbps throughput. Includes custom cable.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues. Product Discontinued December 1997.
DB2111007	Field Upgrade/Spare Nautica WAN Module - V.11	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DB2111008	Field Upgrade/Spare Nautica WAN Module - V.24	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB2111009	Field Upgrade/Spare Nautica WAN Module - V.35	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DB2111010	Field Upgrade/Spare Nautica QUAD WAN Module - V.11.	PASS	N/A	N/A	N/A	
DB2118004	X.21 Quad cable for Nautica 4000.	PASS	N/A	N/A	N/A	
DB3804001	Quad Modem (analog channel) base module. Expansion from 0 to 4 or 4 to 8 modems. For Europe	PASS	N/A	N/A	N/A	No Issues
DB3804002	Quad Modem (analog channel) base module. Expansion from 0 to 4 or 4 to 8 modems. For North America.	PASS	N/A	N/A	N/A	No Issues
DB3804003	Modular QUAD Modem expansion module. Expansion from 8 to 12 or 12 to 16 modems. For all countries.	PASS	N/A	N/A	N/A	No Issues
DC0008001	Switch Node Software includes: 8MB Flash card with TCP/IP, Port/Protocol type VLANs, 802.1q trunking, 802.1d Bridging, IP AutoLearn, IP Routing/RIP/RIPv2, OSPF, SNMP Agent.	PASS	N/A	N/A	N/A	No Issues
DC3602001	Switch Node Chassis, Internal Power Supply, Rack Mount Kit, without power cord	PASS	N/A	N/A	N/A	No Issues
DC3602B01	Switch Node Chassis, Internal Power Supply, rack mount Kit, with power cord for 110VAC	PASS	N/A	N/A	N/A	No Issues
DC3602C01	Switch Node Chassis, Internal Power Supply, Rack mount kit, with power cord for 110VAC	PASS	N/A	N/A	N/A	No Issues
DC3602D01	Switch Node Chassis, Internal Power Supply, Rack mount kit, with power cord for 220VAC	PASS	N/A	N/A	N/A	No Issues
DC3602E01	Switch Node Chassis, Internal Power Supply, Rack mount kit, with power cord for 220VAC	PASS	N/A	N/A	N/A	No Issues
DC3602F01	Switch Node Chassis, Internal Power Supply, rack mount kit, with power cord for 220VAC	PASS	N/A	N/A	N/A	No Issues
DC3604002	CPU Module with 16 MB Memory Installed	PASS	N/A	N/A	N/A	No Issues
DC3604003	CPU Module with 32 MB Memory Installed	PASS	N/A	N/A	N/A	No Issues
DC3611006	Redundant Power Interface Module	PASS	N/A	N/A	N/A	No Issues
DC3611008	16 port 10BaseT Net Module with 2MB SRAM on board	PASS	N/A	N/A	N/A	No Issues
DC3611010	8 Port 10BaseFL Net Module with 2MB SRAM on board	PASS	N/A	N/A	N/A	No Issues
DC3611012	2 Port 100BaseTX Net Module With 2MB SRAM on board	PASS	N/A	N/A	N/A	No Issues
DC3611014	2 Port 100Base-FX Switch Node Module	PASS	N/A	N/A	N/A	No Issues
DC3611016	1MB Expansion Memory, SRAM SIMM-For All Other Enet Modules	PASS	N/A	N/A	N/A	No Issues
DC3611017	2MB Expansion Memory, SRAM SIMM-For All Other Enet Modules	PASS	N/A	N/A	N/A	No Issues
DC3611035	16 Port 10/100BASE-TX Autosense Net Module with 2MB SRAM on board	PASS	N/A	N/A	N/A	No Issues
DC3611036	2MB Expansion Memory, SRAM SIMM-For 2 Port 100BaseTX Net Module only	PASS	N/A	N/A	N/A	No Issues
DD3804001	Penril P3428-0002 V.34/33.6K Stand alone managed modem, LCD front panel, 2/4-wire operation, 117VAC	PASS	N/A	N/A	N/A	No Issues
DD3804002	Penril P3428-0004 V.34/33.6K Rack mount managed modem with LCD, 2/4-wire operation,	PASS	N/A	N/A	N/A	No Issues
DD3804003	Penril P3428-0006 V.34/33.6K Low-profile managed rack mount modem, LED front panel, 2/4-wire operation,	PASS	N/A	N/A	N/A	No Issues
DD3804004	Penril P3192-0002 V.32/19.2K Stand alone managed modem, LCD front panel, 2/4-wire operation, 117VAC	PASS	N/A	N/A	N/A	No Issues
DD3804005	Penril P3192-0004 V.32/19.2K Rack mount managed modem with LCD front panel, 2/4-wire operation,	PASS	N/A	N/A	N/A	No Issues
DD3804006	Penril P3192-0006 V.32/19.2K Low-profile managed modem, 2/4-wire operation,	PASS	N/A	N/A	N/A	No Issues
DD3804A15	Penril P3192-5002-999 V.32/19.2K Stand Alone Managed Modem, LCD front panel, 2/4-wire operation, World Version	PASS	N/A	N/A	N/A	No Issues
DD3804A16	Penril P3192-5004-999 V.32/19.2K Rack mount managed modem with LCD, 2/4-wire operation, World Version	PASS	N/A	N/A	N/A	No Issues
DD3804A17	Penril P3192-5006-999 V.32/19.2K Low-profile rack mount managed modem, 2/4-wire operation, World version	PASS	N/A	N/A	N/A	No Issues
DD3804A21	Penril P3428-5002-999 V.34/33.6K Stand Alone Managed Modem, LCD front panel, 2/4-wire operation, World Version	PASS	N/A	N/A	N/A	No Issues
DD3804A22	Penril P3428-5004-999 V.34/33.6K Rack mount managed modem with LCD, 2/4-wire operation, World version	PASS	N/A	N/A	N/A	No Issues
DD3804A23	Penril P3428-5006-999 V.34/33.6K Low-profile rack mount managed modem, 2/4-wire operation, World version	PASS	N/A	N/A	N/A	No Issues
DD3804B07	Penril P3428-5002-049 V.34/33.6K Stand alone managed modem, LCD front panel, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804B08	Penril P3428-5004-049 V.34/33.6K Rack mount managed modem with LCD, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804B09	Penril P3428-5006-049 V.34/33.6K Low-profile rack mount managed modem, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804B10	Penril P3192-5002-049 V.32/19.2K Stand alone managed modem, LCD front panel, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804B11	Penril P3192-5004-049 V.32/19.2K Rack mount managed modem with LCD, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804B12	Penril P3192-5006-049 V.32/19.2K Low-profile rack mount managed modem, 2/4-wire operation, German	PASS	N/A	N/A	N/A	No Issues
DD3804C07	Penril P3428-5002-044 V.34/33.6K Stand alone managed modem, LCD front panel, 2/4-wire operation, BAPT approved, UK	PASS	N/A	N/A	N/A	No Issues
DD3804C08	Penril P3428-5004-044 V.34/33.6K Rack mount managed modem with LCD, 2/4-wire operation, BAPT approved, UK	PASS	N/A	N/A	N/A	No Issues
DD3804C09	Penril P3428-5006-044 V.34/33.6K Low-profile rack mount managed modem, 2/4-wire operation, BAPT approved, UK	PASS	N/A	N/A	N/A	No Issues
DD3804C10	Penril P3192-5002-044 V.32/19.2K Stand alone managed modem, LCD front panel, 2/4-wire operation, BAPT approved, UK	PASS	N/A	N/A	N/A	No Issues

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DD3804C11	Penril P3192-5004-044 V.32/19.2K Rack mount managed modem with LCD, 2/4-wire operation, BABT approved, UK	PASS	N/A	N/A	N/A	No Issues
DD3804C12	Penril P3192-5006-044 V.32/19.2K Low-profile rack mount managed modem, 2/4-wire operation, BABT approved UK	PASS	N/A	N/A	N/A	No Issues
DD3804F07	Penril P3428-5002-061 V.34/33.6K Stand alone managed modem, LCD front panel, 2/4-wire operation, Austel approved, Australia	PASS	N/A	N/A	N/A	No Issues
DD3804F08	Penril P3428-5004-061 V.34/33.6K Rack mount managed modem with LCD, 2/4-wire operation, Austel approved, Australia	PASS	N/A	N/A	N/A	No Issues
DD3804F09	Penril P3428-5006-061 V.34/33.6K Low-profile rack mount managed modem, 2/4-wire operation, Austel approved, Australia	PASS	N/A	N/A	N/A	No Issues
DD3804F18	Penril P3192-5002-061 V.32/19.2K Stand Alone Managed Modem, LCD front panel, 2/4-wire operation, Austel approved, Australia	PASS	N/A	N/A	N/A	No Issues
DD3804F19	Penril P3192-5004-061 V.32/19.2K Full Height LCD Managed Rack Mount Modem, 2/4-wire operation, Austel approved, Australia	PASS	N/A	N/A	N/A	No Issues
DD3804F20	Penril P3192-5006-061 V.32/19.2K Low Profile Rack Mount Managed Modem, 2/4-wire operation, Austel approved Australia	PASS	N/A	N/A	N/A	No Issues
DD3804V07	Penril P3428-0002-602 V.34/33.6K Stand alone managed modem,LCD Front Panel,2/4-wire operation,Latin America	PASS	N/A	N/A	N/A	No Issues
DD3804V09	Penril P3428-0006-601 V.34/33.6K,Low Profile Rack Mount managed modems,2/4-wire operation,Latin America	PASS	N/A	N/A	N/A	No Issues
DD3811001	Penril P6100-03 Series 6000 Software: Modem management software for V.34/33.6K and V.32/19.2K modems,	PASS	3.03	N/A	N/A	With Limitations - See report for software work around
DD3811002	Penril P6100-05 Series 6000 Upgrade Software,	PASS	3.03	N/A	N/A	With Limitations - See report for software work around
DD3811003	Penril P6100-09 SNMP Proxy: Runs in conjunction with Series 6000 system to deliver SNMP trap support to a V.34/33.6K and/or V.32/19.2K Penril modem network,	PASS	N/A	N/A	N/A	No Issues
DD3811004	16-slot rack enclosure, -48VDC	PASS	N/A	N/A	N/A	No Issues
DD3811005	ALX RE 16-Slot Rack Enclosure with NetMux and Make Busy Card, -48 VDC	PASS	N/A	N/A	N/A	No Issues
DD3811006	Penril P1616-03 16-slot rack enclosure, 117VAC,	PASS	N/A	N/A	N/A	No Issues
DD3811007	ALX RE 16-Slot Rack Enclosure with NetMux and Make Busy Card, 117 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811009	Penril P5500-14, DL/LL Card 16 Kit	PASS	N/A	N/A	N/A	No Issues
DD3811011	Penril P5502-14, MB Option Card 16S Kit	PASS	N/A	N/A	N/A	No Issues
DD3811012	Penril P5503-02, Rack Adapters, 23 inch, 2 each	PASS	N/A	N/A	N/A	No Issues
DD3811013	Penril P5507-04, Blank Panel Set, 16 slot, 8 each	PASS	N/A	N/A	N/A	No Issues
DD3811014	Penril P5507-14, Blank Panel Spacer Set, 8 each	PASS	N/A	N/A	N/A	No Issues
DD3811016	Penril P5516R-16 NetMux, 16-slot Kit,	PASS	N/A	N/A	N/A	No Issues
DD3811017	Penril P5530-02, PS Module 117 VAC Spare	PASS	N/A	N/A	N/A	No Issues
DD3811018	Penril P5531-02 PS Module -48 VDC Spare (for DD3811004)	PASS	N/A	N/A	N/A	No Issues
DD3811019	Penril P1608-01, Datalink rack enclosure 110 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811020	Penril P1608-02, Datalink rack enclosure -48 VDC	PASS	N/A	N/A	N/A	No Issues
DD3811021	Penril P5500-01, Dial Line Modular Jack Card	PASS	N/A	N/A	N/A	No Issues
DD3811022	Penril P5501-01, Leased line Breakout Card	PASS	N/A	N/A	N/A	No Issues
DD3811023	Penril P5502-04, Test/Busy Card	PASS	N/A	N/A	N/A	No Issues
DD3811025	Penril P5507-03, Blank Panel Set, 4 each	PASS	N/A	N/A	N/A	No Issues
DD3811027	Penril P5508R-16, NetMux V2, 8-slot Kit	PASS	N/A	N/A	N/A	No Issues
DD3811028	Penril P1638-1, Datalink, 8 Slot Rack Enclosure 220 VAC, International	PASS	N/A	N/A	N/A	No Issues
DD3811032	Penril P1636-01 16-slot rack enclosure 230VAC	PASS	N/A	N/A	N/A	No Issues
DD3811037	Penril P1638-02 8-Slot Rack Enclosure 230 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811039	Penril P1636-02 16-Slot Rack Enclosure 230 VAC, CE Approved,	PASS	N/A	N/A	N/A	No Issues
DD3811040	Penril P1616-33 16-Slot Rack Enclosure 220 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811041	Penril P5533-03, Spare Power Supply Module 220 VAC (for DD3811040)	PASS	N/A	N/A	N/A	No Issues
DD3811042	Penril P5533-06, Spare Power Supply Module 230 VAC (for DD3811032)	PASS	N/A	N/A	N/A	No Issues
DD3811043	Penril P5516R-15 NetMux, 16-slot CE Kit	PASS	N/A	N/A	N/A	No Issues
DD3811044	RE 16-Slot Rack Enclosure with NetMux and Make Busy Card, 220 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811045	DLX RE 16-Slot BABT Rack Enclosure with NetMux, 230 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811046	RE 16-Slot Rack Enclosure CE with NetMux CE, 230 VAC	PASS	N/A	N/A	N/A	No Issues
DD3811047	Penril P5505-04 Rackmount(with LCD)to Standalone Upgrade Kit,Includes 117VAC adapter	PASS	N/A	N/A	N/A	No Issues
DD3811048	Penril P5525-01 Firmware Upgrade Kit for NetMux	PASS	N/A	N/A	N/A	No Issues
DD3811049	Penril P5527-0103-101 Firmware Upgrade Kit for V.32/19.2K Modems	PASS	N/A	N/A	N/A	No Issues
DE3313001	DOCSIS LCn Provisioning Server - MSWindows95-based, system for Bay Networks DOCSIS devices	PASS	N/A	N/A	N/A	
DE3801E01	DOCSIS Compliant Headend Termination System, DC, Domestic	PASS	N/A	N/A	N/A	
DE3801E02	DOCSIS Compliant Headend Termination System, AC, Domestic	PASS	N/A	N/A	N/A	
DE3804005	LCPET-21 Personal User 750 MHz - 10Base-T Domestic version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804006	LCPET-22 Personal User 750 MHz - 10Base-T International version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DE3804011	LCbEA-21 User Bridge 750 MHz (AUI) Domestic version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804012	LCbEA-22 User Bridge 750 MHz (AUI) International version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804013	LChEA-21 Headend Ref. Node Kit 750 MHz - 10Base5 Domestic Version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804014	LChEA-22 Headend Ref. Node Kit 750 MHz - 10Base5 International Version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804017	LCT90-01 550 MHz Translator 115V/60Hz	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3804020	LCT91-01 550MHz Translator Domestic Version	PASS	N/A	N/A	N/A	
DE3804021	LCT91-02 550MHz Translator International Version	PASS	N/A	N/A	N/A	
DE3804022	LCT75-01 550-750MHz Translator Domestic Version	PASS	N/A	N/A	N/A	
DE3804023	LCT75-02 550-750MHz Translator International Version	PASS	N/A	N/A	N/A	
DE3804E25	DOCSIS Compliant 16 User CATV Subscriber Interface - Domestic	PASS	N/A	N/A	N/A	
DE3810001	SRC02-05 PC Based SNMP Manager	PASS	N/A	N/A	N/A	The SNMPc is year 2K compliant. However, there are two areas (logfile and trend view) that display the date incorrectly, this will be fixed later this year with a free download patch.
DE3810004	SRC05-01 On Net Server for DOS/Windows	PASS	N/A	N/A	N/A	No Issues
DE3810005	SRC05-02 On Net Kernel for DOS/Windows	PASS	N/A	N/A	N/A	No Issues
DE3810006	LCnPM-01 LANcity Network Utility Provisioning Server PC Based S/W	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3810007	SRC01-05 Low-Split Diplex Filter	PASS	N/A	N/A	N/A	No Issues
DE3810009	2132-0019 Management S/W Tools, Package Kit. Includes DE3810001 PC Bases SNMP, DE3810004 On Net Server, DE3810005 On Net Kernel, & DE3810006 LCn Utility	PASS	N/A	N/A	N/A	No Issues
DE3811002	Rack Mount Kit	PASS	N/A	N/A	N/A	No Issues
DE3815001	LCM30-12 LCh Headend Equipment Manual	PASS	N/A	N/A	N/A	No Issues
DE3837033	LCeEA-31 Dual Headend Ref. Node 750 MHz - 10Base5 (AUI) Domestic version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3837034	LCeEA-32 Dual Headend Ref. Node 750 MHz - 10Base5 (AUI) International version	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues
DE3837035	Power Cord: AC Cord, 125V, 10A (applies to LCP/b/h/e) Domestic Only	PASS	N/A	N/A	N/A	No Issues
DE3837036	Power Supply: External, 22W, 5 pin (applies to LCP)	PASS	N/A	N/A	N/A	No Issues
DF1901001	Model 2216T Ethernet Switch with sixteen 10BASE-T ports and one 100BASE-TX port	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DG0002001	W1003301 - 48 Volt DC Chassis (Includes 128KB Flash Memory, 6 Universal V.24 Ports).	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002002	W7702301 - 48 volt DC chassis (includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002003	W5001301 - 48 Volt DC Chassis (includes 486-T2 50 CPU w/16MB memory)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002004	W5001501 - Dual 48 Volt Chassis (includes 486-T2 50 CPU w/16MB memory)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002B05	W1002302EU - 110/220 Volt Chassis (Includes 128KB Flash Memory, 6 Universal V.24 Ports). Northern Europe	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002B06	W7702202EU - 110/220 Volt Chassis (includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI) Northern Europe	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002B07	W5001202EU - 110/220 Volt Chassis (includes 486-T2 50 CPU w/16MB memory) Northern Europe	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002C05	W1002302GB - 110/220 Volt Chassis (Includes 128KB Flash Memory, 6 Universal V.24 Ports).United Kingdom and Ireland	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002C06	W7702202GB - 110/220 Volt Chassis (Includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI)United Kingdom and Ireland	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002C07	W5001202GB - 110/220 Volt Chassis (includes 486-T2 50 CPU w/16MB memory) United Kingdom and Ireland	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002E05	W1001301NA - 110/220 Volt Chassis (Includes 128KB Flash Memory,6 Universal V.24 Ports) North America	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002E06	W7702101NA - 110/220 Volt Chassis (Includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI) North America	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002E07	W5001101NA - 110/220 Volt Chassis (includes 486-T2 50 CPU w/16MB memory) North America	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002G05	W1002302DN - 110/220 Volt Chassis (Includes 128KB Flash Memory,6 Universal V.24 Ports) Denmark	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002G06	W7702202DN - 110/220 Volt Chassis (Includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI) Denmark	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002G07	W5001202DN - 110/220 Volt Chassis (includes 486-T2 50 CPU w/16MB memory) Denmark	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002K05	W1002302IT - 110/220 Volt Chassis (Includes 128KB Flash Memory,6 Universal V.24 Ports) Italy	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DG0002K06	W7702202IT - 110/220 Volt Chassis (Includes 16MB memory, 2MB PCMCIA card, 4 UNIVERSAL v.24 PORTS, 2 VHSL (to be specified), 1 AUI) Italy	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0002K07	W5001202IT - 110/220 Volt Chassis (includes 486-T2 50 CPU w/16MB memory) Italy	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0004001	5394 ACN 24 Port T1	PASS	N/A	N/A	N/A	No Issues
DG0004002	5394 ACN 24 Port E1	PASS	N/A	N/A	N/A	No Issues
DG0011001	W1999201 - SW/AS/SNA/DSP w/Type 5 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011002	W1J99201 - SW/AS/SNA/TP w/Type 3 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011003	W1P99201 - SW/AS/FR w/Type 7 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011004	W1033002 - Flash Personality board w/Type 5 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011005	W1033003 - Flash Personality board w/Type 3 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011006	W1033005 - Flash Personality board w/Type 7 software	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011007	7710-011 - V.11 Interface module set	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011008	7710-024 - V.24 Interface module set	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011009	7710-035 - V.35 Interface module set	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011010	7703-001 - Quad CCM, V.24 DDB15	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011011	7704-001 - Single BRI Module	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011012	7705-002 - Voice/Fax FXO-E Module	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011013	7705-004 - Voice/Fax FXS-E Module	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011014	7705-006 - Voice/Fax E&M-E Module	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011015	7706-016 - Bay ACN500/486-T2 and Bay ACN200 16 MB replacement	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011016	W7H09P401 - PCMCIA w/7H09 software (SW/AS/SNA/DSP/TP/FR/IP/BR) (ISDN N1-1)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011017	W7H19P401 - PCMCIA w/7H19 software (SW/AS/SNA/DSP/TP/FR/IP/BR) (EURO)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011018	7709-000 - Power Module, AC	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011019	7709-002 - Power Module, 48V DC	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011020	7700-100 - Fan Assy (kit of 2)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011021	W7731000 - Shipping Carton (Qty 5)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011034	W7H09P201 - SW/AS/SNA/DSP/TP/FR/IP/BR (ISDN NI-1)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0011035	W7H19P201 - SW/AS/SNA/DSP/TP/FR/IP/BR (EURO/1TR6/VN3)	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0018017	5003-014 - Octal DMA III (8port) V.24 CAM, DB-25S PSW	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0018018	5012-001 - T1 CSU/DSU CEM/CAM	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DG0018019	5012-002 - E1 CSU/DSU CEM/CAM	PASS	N/A	N/A	N/A	Y2k Compliant based on Vendor Testing - Telematics
DH0008001	Software, Unlimited use of NetID products for managing up to 2500 IP addresses. Includes support for multiple DNS and DHCP servers, Web Gateways and NetID Administrators: extend NetID by adding 5000 address licenses.	FAIL	v2.x	N/A	N/A	Upgrade to NETID version 3.0 available by 1/1/98, to be Year2000 compliant.
DH0008002	Software, NetID 5000 Address License	FAIL	v2.x	N/A	N/A	Upgrade to NETID version 3.0 available by 1/1/98, to be Year2000 compliant.
DH0008003	Software, NetID Runtime Database for NT. Oracle7 Workgroup Server for NT. Price is per concurrent database user with a minimum of 5.	FAIL	v2.x	N/A	N/A	Upgrade to NETID version 3.0 available by 1/1/98, to be Year2000 compliant.
DH0008004	Software, NetID Runtime Database for Solaris (Workgroup). Oracle7 Workgroup Server for Solaris. The price is per concurrent user with a minimum of 5.	FAIL	v2.x	N/A	N/A	Upgrade to NETID version 3.0 available by 1/1/98, to be Year2000 compliant.
DH0008005	Software, NetID Runtime Database for Solaris (Enterprise). Oracle7 Enterprise Server for Solaris. The Price is per concurrent user with a minimum of 5.	FAIL	v2.x	N/A	N/A	Upgrade to NETID version 3.0 available by 1/1/98, to be Year2000 compliant.
DH0008025	Software, NetID 4.0 Unlimited use of NetID products for managing up to 2500 IP addresses. Includes support for multiple DNS and DHCP servers, Application Servers and NetID Administrators.	PASS	v4.0	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DH0008026	Software, NetID 4.0 Unlimited use of NetID products for managing up to 2500 IP addresses. Includes support for multiple DNS and DHCP servers, Application Servers and NetID Administrators. Includes runtime Database for NT. Oracle8 Workgroup Server for NT	PASS	v4.0	N/A	N/A	
DH0008027	Software, NetID 1500 4.0 Limited use of NetID products on Microsoft Windows NT for managing up to 1500 IP addresses. Includes support for multiple DNS and DHCP servers, Application Servers and NetID Administrators: Includes runtime Database for NT. Oracle	PASS	v4.0	N/A	N/A	
DH0008028	Software, NETID V4.0 Runtime Database for Solaris (Workgroup). Oracle8 Workgroup Server for Solaris licensed for 5 concurrent database users.	PASS	v4.0	N/A	N/A	
DH0008029	Software, NETID V4.0 Runtime Solaris (Enterprise). Oracle8 Enterprise Server for Solaris licensed for 5 concurrent database users.	PASS	v4.0	N/A	N/A	
DH0008030	Software, NetID 2500 Address License for V4.0	PASS	v4.0	N/A	N/A	
DH0008031	Software, NetID 25000 Address License for V4.0	PASS	v4.0	N/A	N/A	
DH0008032	Software License for each Additional Concurrent Database user for NetID Runtime Database for Solaris Enterprise.	PASS	N/A	N/A	N/A	
DH0008033	Software, NetID 5000 Address License for V4.0	PASS	v4.0	N/A	N/A	
DH0008034	Software License for each Additional Concurrent Database user for NetID Runtime Database for NT.	PASS	N/A	N/A	N/A	
DH0008035	Software License for each Additional Concurrent Database user for NetID Runtime Database for Solaris.	PASS	N/A	N/A	N/A	
DJ0011001	Accelar 1200/1250 4MB PCMCIA flash memory card	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1401701	XLR1050 base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software.	PASS	v12.10	N/A	N/A	
DJ1401702	XLR1051 base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software.	PASS	v12.10	N/A	N/A	
DJ1401704	XLR1050-A base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software.	PASS	v12.10	N/A	N/A	
DJ1401705	XLR1051-A base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software.	PASS	v12.10	N/A	N/A	
DJ1401A06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1401A08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1401A09	XLR740 Server Switch. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1401A11	XLR750 Server Switch, includes Rich Mode URL Parsing. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1401B06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DJ1401B08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software.	PASS	N/A	N/A	N/A	
DJ1401B09	XLR740 Server Switch. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DJ1401B11	XLR750 Server Switch, includes Rich Mode URL Parsing. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DJ1401C06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord used in the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1401C08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software. (Includes power cord used in the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1401C09	XLR740 Server Switch. (Includes power cord used in the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1401C11	XLR750 Server Switch, includes Rich Mode URL Parsing. (Includes power cord used in the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1401D06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord used in Japan)	PASS	N/A	N/A	N/A	
DJ1401D08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software. (Includes power cord used in Japan)	PASS	N/A	N/A	N/A	
DJ1401D09	XLR740 Server Switch. (Includes power cord used in Japan)	PASS	N/A	N/A	N/A	
DJ1401D11	XLR750 Server Switch, includes Rich Mode URL Parsing. (Includes power cord used in Japan)	PASS	N/A	N/A	N/A	
DJ1401E06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DJ1401E08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1401E09	XLR740 Server Switch. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1401E11	XLR750 Server Switch, includes Rich Mode URL Parsing. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1401F06	XLR1050-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1401F08	XLR1051-B base unit with 12 10/100BASE-TX ports and one 1000Base-SX Ethernet interface with LinkSafe, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1401F09	XLR740 Server Switch. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1401F11	XLR750 Server Switch, includes Rich Mode URL Parsing. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1402?03	Accelar 1100 base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, no power cord	PASS	N/A	N/A	N/A	No issues
DJ1402?04	Accelar 1100R base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies, and no power cord	PASS	N/A	N/A	N/A	No issues
DJ1402?05	Accelar 1150 base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application, and Schuko power cord.	PASS	N/A	N/A	N/A	No Issues
DJ1402?06	Accelar 1150R base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software, and Schuko power cord.	PASS	N/A	N/A	N/A	No Issues
DJ1402?07	Accelar 1150-A base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software.	PASS	N/A	N/A	N/A	
DJ1402?08	Accelar 1150R-A base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software.	PASS	N/A	N/A	N/A	
DJ1402?10	Accelar 1100-A base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software.	PASS	N/A	N/A	N/A	
DJ1402?11	Accelar 1100R-A base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies.	PASS	N/A	N/A	N/A	
DJ1402001	Accelar 1200 8 slot chassis, requires at least one XLR1298PS power supply and one XLR1297SF CPU module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1402002	Accelar 1250 4 slot chassis, requires one XLR1298PS power supply and one XLR1297SF CPU module.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1402A13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1402A14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1402A15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1402A16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
DJ1402B13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
DJ1402B14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
DJ1402B15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
DJ1402B16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
DJ1402C13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1402C14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1402C15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DJ1402C16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
DJ1402D13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
DJ1402D14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
DJ1402D15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
DJ1402D16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
DJ1402E13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1402E14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1402E15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1402E16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DJ1402F13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1402F14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1402F15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1402F16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet Ports, redundant power supplies, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DJ1404001	XLR1297SF CPU module for Accelar 1200 & 1250 modular chassis, includes device manager application software	PASS	N/A	N/A	N/A	No issues
DJ1404002	XLR1201SX One port 1000BASE-SX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404003	XLR1202SX Two port 1000BASE-SX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404004	XLR1202SR Two port 1000BASE-SX Gigabit Ethernet interface module with LinkSafe redundant physical layer	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404005	XLR1201LX One port 1000BASE-LX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404006	XLR1202LX Two port 1000BASE-LX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404007	XLR1202LR Two port 1000BASE-LX Gigabit Ethernet interface module with LinkSafe redundant physical layer	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404008	XLR1216TX 16 port autosensing 10BASE-T/100BASE-TX Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404009	XLR1208FX 8 port 100BASE-FX Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404010	XLR1101SX One port 1000BASE-SX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404011	XLR1102SX Two port 1000BASE-SX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404012	XLR1102SR Two port 1000BASE-SX Gigabit Ethernet interface module with LinkSafe redundant physical layer	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404013	XLR1101LX One port 1000BASE-LX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404014	XLR1102LX Two port 1000BASE-LX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404015	XLR1102LR Two port 1000BASE-LX Gigabit Ethernet interface module with LinkSafe redundant physical layer	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404016	XLR1108TX 8 port autosensing 10BASE-T/100BASE-TX Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404017	XLR1104FX 4 port 100BASE-FX Ethernet interface module	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1404021	XLR1202XD Two port Long Distance Gigabit Ethernet interface module. For use only with other Accelar XD interfaces.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DJ1404022	XLR1102XD Two port Long Distance Gigabit Ethernet interface module. For use only with other Accelar XD interfaces.	PASS	N/A	N/A	N/A	
DJ1404023	XLR1201SX-A 1 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404024	XLR1202SR-A 2 port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
DJ1404025	XLR1202SX-A 2 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404026	XLR1201LX-A 1 port 1000BASE-LX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404027	XLR1202LX-A 2 port 1000BASE-LX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404028	XLR1202LR-A 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
DJ1404029	XLR1216TX-A 16 port autosensing 10BASE-T/100BASE-TX Ethernet interface module	PASS	N/A	N/A	N/A	
DJ1404030	XLR1208FX-A 8 port 100BASE-FX Ethernet interface module	PASS	N/A	N/A	N/A	
DJ1404031	XLR1216FX-A 16 port 100BASE-FX Fast Ethernet Mini MT-RJ interface module	PASS	N/A	N/A	N/A	
DJ1404032	XLR1216TF-A 14 10/100BASE-TX and 2 100BASE-FX Fast Ethernet ports with Mini MT-RJ connectors.	PASS	N/A	N/A	N/A	
DJ1404033	XLR1202XD-A 2 port Long Distance Gigabit Ethernet interface module. For use only with other Accelar XD and XD-A interfaces	PASS	N/A	N/A	N/A	
DJ1404034	XLR1101SX-A 1 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404035	XLR1102SX-A 2 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404036	XLR1102SR-A 2 port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
DJ1404037	XLR1101LX-A 1 port 1000BASE-LX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404038	XLR1102LX-A 2 port 1000BASE-LX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404039	XLR1102LR-A 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
DJ1404040	XLR1108TX-A 8 port autosensing 10BASE-T/100BASE-TX Ethernet interface	PASS	N/A	N/A	N/A	
DJ1404041	XLR1104FX-A 4 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404042	XLR1108FX-A 8 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404043	XLR1102XD-A 2 port long distance Gigabit Ethernet interface module. For use only with other Accelar XD & XD-A interfaces.	PASS	N/A	N/A	N/A	
DJ1404053	XLR1202SR-B 2 port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
DJ1404054	XLR1202SX-B 2 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404056	XLR1202LX-B 2 port 1000BASE-LX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404057	XLR1202LR-B 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
DJ1404058	XLR1216TX-B 16 port autosensing 10BASE-T/100BASE-TX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404059	XLR1208FX-B 8 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404060	XLR1216FX-B 16 port 100BASE-FX Fast Ethernet Mini MT-RJ interface module.	PASS	N/A	N/A	N/A	
DJ1404061	XLR1216TF-B 14 10/100BASE-TX and 2 100BASE-FX Fast Ethernet ports with Mini MT-RJ connectors.	PASS	N/A	N/A	N/A	
DJ1404062	XLR1202XD-B 2 port 100BASE-LX long distance Gigabit Ethernet interface module. For use only with other Accelar XD and XD-A interfaces.	PASS	N/A	N/A	N/A	
DJ1404064	XLR1102SX-B 2 port 1000BASE-SX Gigabit Ethernet interface module	PASS	N/A	N/A	N/A	
DJ1404065	XLR1102SR-B 2 port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
DJ1404067	XLR1202LX-B 2 port 1000BASE-LX Gigabit Ethernet interface module for the XLR 1100.	PASS	N/A	N/A	N/A	
DJ1404068	XLR1102LR-B 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
DJ1404069	XLR1108TX-B 8 port autosensing 10BASE-T/100BASE-TX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404070	XLR1104FX-B 4 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
DJ1404071	XLR1108FX-B 8 port 100BASE-FX Fast Ethernet Mini MT-RJ interface module.	PASS	N/A	N/A	N/A	
DJ1404072	XLR1102XD-B 2 port long distance Gigabit Ethernet interface module. For use only with other Accelar XD-B interfaces.	PASS	N/A	N/A	N/A	
DJ1404073	XLR1298SF CPU module for Accelar 1200 & 1250 modular chassis, includes d	PASS	N/A	N/A	N/A	
DJ1404074	XLR1208FL-B 8 port 10BASE-FL Ethernet interface module with ST connectors.	PASS	N/A	N/A	N/A	
DJ1405701	XLR1298PS Power supply for Accelar 1200 and 1250 modular chassis switches	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DJ1405003	XLR1296PS 48V DC Power Supply for Accelar 1200 and 1250 modular chassis	PASS	N/A	N/A	N/A	
DJ1410001	Accelar system software and device manager application software kit (includes installation guide and documentation CDROM).	PASS	N/A	N/A	N/A	
DJ1410001-2.0	Accelar 1000 series system software and device manager application software kit (includes installation guide and documentation CD-ROM). Version 2.0	PASS	N/A	N/A	N/A	
DJ1410001-2.0.1	Accelar 1000 series system software and device manager application software kit (includes installation guide and documentation CD-ROM). Version 2.0.1.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DJ1410002-2.1	Accelar 740 system software kit (includes installation guide and documentation CD-ROM). Version 2.1.	PASS	N/A	N/A	N/A	
DJ1410003-2.1	Accelar 750 system software kit (includes installation guide and documentation CD-ROM). Version 2.1.	PASS	N/A	N/A	N/A	
DJ1410005-2.1	Accelar 740 to 750 product upgrade kit (includes upgrade CD-ROM, installation guide and documentation CD-ROM). Version 2.1	PASS	N/A	N/A	N/A	
DK0004001	MX200 Stratum 3-4 Module (order one or two)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK0004002	MX200 CPU Module (minimum 1 required)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK0008001	System Software Release 2.0 (required, one copy per chassis)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK0008002	SNMP Management (required, one copy per chassis)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK0008003	Frame Relay (optional, one copy per module supporting Frame Relay)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1004001	Ethernet Module provides one 10/100Base-T (autosensing) and four 10Base T i	PASS	N/A	N/A	N/A	
DK1302001	MX200 ATM Access Concentrator (12-slot) 19" Rackmount	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1302002	MX200 ATM Access Concentrator (12-slot) Table-Top	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1302003	MX200 ATM Access Concentrator (16-slot) 23" Rackmount	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1302004	MX50 (110V) ATM Access Concentrator (4-slot) includes PS, CPU, Stratum 3-	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1302007	MX200 Bundle (inc. 19" chassis, System & SNMP Software, documentation, console cable, Blank PS & Stratum faceplates)--Must order one or two of each (separately): AC Power Supply, Stratum Clock, CPU	PASS	N/A	N/A	N/A	
DK1302008	MX200 Bundle (inc. 23" chassis, System & SNMP Software, documentation, console cable, Blank PS & Stratum faceplates)--Must order one or two of each (separately): DC Power Supply, Stratum Clock, CPU	PASS	N/A	N/A	N/A	
DK1302009	MX50 (110V DC) Bundle (includes MX50, System & SNMP Software, documentation, console cable)	PASS	N/A	N/A	N/A	
DK1304001	OC-3c (Multi-Mode) LAN Module (ST) provides ATM connection	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1304002	OC-3c (Multi-Mode) LAN Module (ST) with Traffic Shaping	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1304003	OC-3c (Single-Mode) LAN Module (SC) with Traffic Shaping	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK1304005	OC-3c (Single-Mode) WAN Module (SC) with UBR Traffic Shaping	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK2104001	DS1/T1 Module (ATM Cell Bearing) provides 6 (RJ-45) T1 interfaces	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK2104002	DS1/T1 Module (Circuit Emulation Services) provides 6 (RJ-45) T1 interfaces	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK2104003	Enhanced DS1 Module (Frame Relay) provides 6 (RJ-45) T1 interfaces	PASS	N/A	N/A	N/A	
DK2104004	DS3/T3 Module provides two 45 Mbps (dual BNC) connections	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK2104008	Multi-Serial Module provides six interfaces up to 2.048 Mbps (aggregate 3 Mbps)	PASS	N/A	N/A	N/A	Yurie Systems, Inc.
DK2104009	High Speed Module provides connection at up to 30 Mbps	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
DK3030	Model 3030-Based Demo Kit comprised of Models 3030-04-HW, 3368, 3313S-04, 3505, 3513, SL351X-A, 600, 636-03, 928 (3), 955 (3), and 903A-3.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
DK3704001	Voice 2-Wire Station Module provides 8 (RJ11) analog telephone FXS interfaces	PASS	N/A	N/A	N/A	
DK3704002	Voice 2-Wire Office Module provides 4 (RJ-11) analog telephone FXO interfaces	PASS	N/A	N/A	N/A	
DM0004002	128 MB RAM Upgrade (FACTORY INSTALL), for use/sale in the Contivity Extranet Switch 4500 Only.	PASS	N/A	N/A	N/A	
DM0005003	Contivity Extranet Switch 4500 Power supply.	PASS	N/A	N/A	N/A	
DM0008001	Contivity Extranet Switch 1500 Check Point Inspection Module (See Note 1)	PASS	N/A	N/A	N/A	
DM0008002	Contivity Extranet Switch 2x00 Platform Check Point Inspection Module. (See Note 1)	PASS	N/A	N/A	N/A	
DM0008003	Contivity Extranet Switch 4x00 Platform Check Point Inspection Module. (See Note 1)	PASS	N/A	N/A	N/A	
DM0008004	Contivity Extranet Switch Check Point Management Console Software, Enterprise. (See Note 2)	PASS	N/A	N/A	N/A	
DM0008005	Contivity Extranet Switch Check Point Management Console Software, Medium. (See Note 2)	PASS	N/A	N/A	N/A	
DM0008006	Contivity Extranet Switch Check Point Management Console Software, Light. (See Note 2)	PASS	N/A	N/A	N/A	
DM0008007	Contivity Extranet Switch Check Point Management Console Software, Upgrade from Light License to Enterprise License. (See Note 2)	PASS	N/A	N/A	N/A	
DM0008008	Contivity Extranet Switch Check Point Management Console Software, Upgrade from Medium License to Enterprise License. (See Note 2)	PASS	N/A	N/A	N/A	
DM0011012	Extranet Switch 2000 Software and Documentation Set (40-Bit) France.	PASS	N/A	N/A	N/A	
DM0011014	Extranet Switch 4000 Software and Documentation Set (40-Bit) France.	PASS	N/A	N/A	N/A	
DM0011016	Extranet Switch 1000 Software and Documentation Set (128-Bit) North American.	PASS	N/A	N/A	N/A	
DM0011018	Extranet Switch 1000 Software and Documentation Set (56-Bit) International.	PASS	N/A	N/A	N/A	
DM0011020	Extranet Switch 1000 Software and Documentation Set (40-Bit).	PASS	N/A	N/A	N/A	
DM0011022	Contivity Extranet Switch 1000 Netscape Directory Server add-on 40-Bit Encryption.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM0011023	Contivity Extranet Switch 1000 Netscape Directory Server add-on 128-Bit Encryption.	PASS	N/A	N/A	N/A	
DM0011024	Contivity Extranet Switch 2000 Netscape Directory Server add-on 40-Bit Encryption.	PASS	N/A	N/A	N/A	
DM0011025	Contivity Extranet Switch 2000 Netscape Directory Server add-on 128-Bit Encryption.	PASS	N/A	N/A	N/A	
DM0011026	Contivity Extranet Switch 4000 Netscape Directory Server add-on 40-Bit Encryption.	PASS	N/A	N/A	N/A	
DM0011027	Contivity Extranet Switch 4000 Netscape Directory Server add-on 128-Bit Encryption.	PASS	N/A	N/A	N/A	
DM0011028	Netscape LDAP Server 10-Incident Support Package	PASS	N/A	N/A	N/A	
DM0011029	Contivity Extranet Switch 1000 Software Upgrade Kit V2.0 (40-Bit) France.	PASS	N/A	N/A	N/A	
DM0011029	Contivity Extranet Switch 1000/1500 Software V2.10 (40-Bit).	PASS	N/A	N/A	N/A	
DM0011030	Contivity Extranet Switch 1000 Software Upgrade Kit V2.0 (56-Bit) International.	PASS	N/A	N/A	N/A	
DM0011030	Contivity Extranet Switch 1000/1500 Software V2.10 (56-Bit).	PASS	N/A	N/A	N/A	
DM0011031	Contivity Extranet Switch 1000 Software Upgrade Kit V2.0 (128-Bit) U.S. and Canada.	PASS	N/A	N/A	N/A	
DM0011031	Contivity Extranet Switch 1000/1500 Software V2.10 (128-Bit).	PASS	N/A	N/A	N/A	
DM0011032	Contivity Extranet Switch 1000 Software Upgrade Kit V2.0 (128-Bit) U.S. and Canada.	PASS	N/A	N/A	N/A	
DM0011032	Contivity Extranet Switch 2000 Software V2.10 (40-Bit).	PASS	N/A	N/A	N/A	
DM0011033	Contivity Extranet Switch 2000 Software Upgrade Kit V2.0 (56-Bit) International.	PASS	N/A	N/A	N/A	
DM0011033	Contivity Extranet Switch 2000 Software V2.10 (56-Bit).	PASS	N/A	N/A	N/A	
DM0011034	Contivity Extranet Switch 2000 Software Upgrade Kit V2.0 (128-Bit) U.S. and Canada.	PASS	N/A	N/A	N/A	
DM0011034	Contivity Extranet Switch 2000 Software V2.10 (128-Bit).	PASS	N/A	N/A	N/A	
DM0011035	Contivity Extranet Switch 4000 Software Upgrade Kit V2.0 (40-Bit) France.	PASS	N/A	N/A	N/A	
DM0011035	Contivity Extranet Switch 4000 Software V2.10 (40-Bit).	PASS	N/A	N/A	N/A	
DM0011036	Contivity Extranet Switch 4000 Software Upgrade Kit V2.0 (56-Bit) International.	PASS	N/A	N/A	N/A	
DM0011036	Contivity Extranet Switch 4000 Software V2.10 (56-Bit).	PASS	N/A	N/A	N/A	
DM0011037	Contivity Extranet Switch 4000 Software Upgrade Kit V2.0 (128-Bit) U.S. and Canada.	PASS	N/A	N/A	N/A	
DM0011037	Contivity Extranet Switch 4000 Software V2.10 (128-Bit).	PASS	N/A	N/A	N/A	
DM0011038	Contivity Extranet Switch 4000 3.2gb Replacement Hard Drive.	PASS	N/A	N/A	N/A	
DM0011039	128 MB RAM Upgrade (FIELD INSTALL), For use/sale in Contivity Extranet Switch 4500 only.	PASS	N/A	N/A	N/A	
DM0011040	Contivity Extranet Switch 4000 4.3GB Replacement Hard Drive.	PASS	N/A	N/A	N/A	
DM1004002	10/100 Ethernet Card (FACTORY INSTALL), for use in the Contivity Extranet Switch 2500/4500 only. (See Note 3)	PASS	N/A	N/A	N/A	
DM1011002	10/100 Ethernet Card (Field INSTALL), for use in the Contivity Extranet Switch 2500/4500 only. (See Note 4)	PASS	N/A	N/A	N/A	
DM1401705	Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-bit) Encryption, Unlimited licenses for IPsec Client S/W, (Includes documentation). France.	PASS	N/A	N/A	N/A	
DM1401706	Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (40-bit) Encryption, Unlimited licenses for IPsec Client S/W, (Includes documentation) France.	PASS	N/A	N/A	N/A	
DM1401707	Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). U.S. and CANADA.	PASS	N/A	N/A	N/A	
DM1401708	Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). International.	PASS	N/A	N/A	N/A	
DM1401711	Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). France.	PASS	N/A	N/A	N/A	
DM1401712	Contivity Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). U.S. and CANADA.	PASS	N/A	N/A	N/A	
DM1401713	Contivity Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 40-Bit Encryption). International	PASS	N/A	N/A	N/A	
DM1401714	Contivity Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 40-Bit Encryption). France	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401?15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, (Includes documentation and Netscape Directory Server 128-Bit Encryption.) U.S. and CANADA.**	PASS	N/A	N/A	N/A	
DM1401?16	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-bit) Encryption, (Includes documentation and Netscape Directory Server 40-Bit Encryption.) International	PASS	N/A	N/A	N/A	
DM1401?17	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-bit) Encryption, (Includes documentation and Netscape Directory Server 40-Bit Encryption.) France.	PASS	N/A	N/A	N/A	
DM1401?18	Contivity Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption, (Includes documentation and Netscape Directory Server 128-Bit Encryption.) U.S. and CANADA.	PASS	N/A	N/A	N/A	
DM1401?19	Contivity Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Server S/W with (56-bit) Encryption, (Includes documentation and Netscape Directory Server 40-Bit Encryption.) International.	PASS	N/A	N/A	N/A	
DM1401?20	Contivity Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (40-bit) Encryption, (Includes documentation and Netscape Directory Server 40-Bit Encryption.) France.	PASS	N/A	N/A	N/A	
DM1401A01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A02	Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with International (56-bit) Encryption, Unlimited license for IPsec Client S/W, (Includes documentation).	PASS	N/A	N/A	N/A	
DM1401A03	CES4000, 200MHz Pentium Pro, 3 PCI Expans. Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Dom. (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (No power cord included).	PASS	N/A	N/A	N/A	
DM1401A04	Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply and Storage Sys, Server S/W with International (56-bit) Encryption, Unlimited license for IPsec Client S/W, (Includes documentation).	PASS	N/A	N/A	N/A	
DM1401A15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes docu. and Netscape Directory Server 128-Bit Encryption). See Note 1. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A27	Contivity Extranet Switch 2500, 400 Tunnels, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W, (Includes documentation) (See Note 1)	PASS	N/A	N/A	N/A	
DM1401A28	Contivity Extranet Switch 2500, 400 Tunnels, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-bit) Encryption, Unltd license for IPsec Client S/W, (Includes Documentation). (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A30	Contivity Extranet Switch 2500, 400 Tunnels, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, (Incl: documentation and Netscape Directory Server 128-Bit Encryption). (See Note 1) (No power cord included)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401A31	Contivity Extranet Switch 2500, 400 Tunnels, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-bit) Encryption, (Incl: documentation and Netscape Directory Server 56-Bit Encryption). (See Note 1) (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A33	Contivity Extranet Switch 4500, 5000 Tunnels, 3 PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Dual Red. P Supply & Storage Sys, Svr S/W w/128-bit Encryption, Unltd license for IPsec Client S/W, (Incl: document)(See Note 1) (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A34	Contivity Extranet Switch 4500, 5000 Tunnels, 3 PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Dual Red. Pwr Supply & Storage Sys, Svr S/W with (56-bit) Encryption, Unltd license for IPsec Client S/W. Incl: documentation. (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A36	Contivity Extranet Switch 4500, 5000 Tunnels, 3 PCI Expansion slots, Dual Red. Pwr Supply & Storage Sys, Svr S/W with (128-bit) Encryption. Incl: documentation & Netscape Directory Server 128-Bit Encryption. (See Note 1) (No power cord included)	PASS	N/A	N/A	N/A	
DM1401A37	Contivity Extranet Switch 4500, 5000 Tunnels, Three PCI Expansion slots, Server S/W with (56-bit) Encryption, (Includes documentation and Netscape Directory Server 56-Bit Encryption). (No power cord included)	PASS	N/A	N/A	N/A	
DM1401B01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DM1401B23	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DM1401B24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Northern Europe)	PASS	N/A	N/A	N/A	
DM1401B25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DM1401B26	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (40-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 40-Bit Encryption). (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DM1401C01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	
DM1401C03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	
DM1401C15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401C18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	
DM1401C21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	
DM1401C22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in the United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
DM1401C24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (UK and Ireland)	PASS	N/A	N/A	N/A	
DM1401C25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in the United Kingdom and Ireland)	PASS	N/A	N/A	N/A	
DM1401D01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in Japan)	PASS	N/A	N/A	N/A	
DM1401D24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Japan)	PASS	N/A	N/A	N/A	
DM1401D25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in Japan)	PASS	N/A	N/A	N/A	
DM1401E02	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-bit) Encryption, Unlimited license for IPsec Client S/W, (Includes documentation) International.	PASS	N/A	N/A	N/A	
DM1401E04	Contivity Extranet Switch 4000, 200 MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (56-bit) Encryption, Unlimited license for IPsec Client S/W, (Includes documentation) International	PASS	N/A	N/A	N/A	
DM1401E08	Contivity Extranet Switch 1000, 266 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). International.	PASS	N/A	N/A	N/A	
DM1401E21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation).** (Includes North American power cord)	PASS	N/A	N/A	N/A	
DM1401E22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes North American power cord)	PASS	N/A	N/A	N/A	
DM1401E24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 128-Bit Encryption).** (Includes North American power cord)	PASS	N/A	N/A	N/A	
DM1401E25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes North American power cord)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401F01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes docu.). See Note 1. (Australia, New Zealand, China)	PASS	N/A	N/A	N/A	
DM1401F03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Australia, New Zealand)	PASS	N/A	N/A	N/A	
DM1401F15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes docu. and Netscape Directory Server 128-Bit Encryption). See Note 1. (Australia, New Zealand)	PASS	N/A	N/A	N/A	
DM1401F18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Australia, New Zealand, China)	PASS	N/A	N/A	N/A	
DM1401F21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Australia, New Zealand, China)	PASS	N/A	N/A	N/A	
DM1401F22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes Australian power cord, also commonly used in New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	
DM1401F24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Australia, New Zealand, China)	PASS	N/A	N/A	N/A	
DM1401F25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes Australian power cord, also commonly used in New Zealand and the People's Republic of China)	PASS	N/A	N/A	N/A	
DM1401G01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in Denmark)	PASS	N/A	N/A	N/A	
DM1401G24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Denmark)	PASS	N/A	N/A	N/A	
DM1401G25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in Denmark)	PASS	N/A	N/A	N/A	
DM1401H01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	
DM1401H03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	
DM1401H15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401H18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	
DM1401H21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	
DM1401H22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in India/South Africa)	PASS	N/A	N/A	N/A	
DM1401H24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (India/So. Africa)	PASS	N/A	N/A	N/A	
DM1401H25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in India/South Africa)	PASS	N/A	N/A	N/A	
DM1401K01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in Italy)	PASS	N/A	N/A	N/A	
DM1401K24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Italy)	PASS	N/A	N/A	N/A	
DM1401K25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in Italy)	PASS	N/A	N/A	N/A	
DM1401L01	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in Switzerland)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DM1401L24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Switzerland)	PASS	N/A	N/A	N/A	
DM1401L25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in Switzerland)	PASS	N/A	N/A	N/A	
DM1401W01	Contivity Extranet Switch 2000, 180MHz Pentium Pro, Three PCI Expansion slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption, Unlimited license for IPsec Client S/W (Includes documentation). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W03	CES4000, 200MHz Pentium Pro, 3 PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Dual Redundant Pwr Supply & Storage Sys, Server S/W w/Domestic (128-bit) Encrypt., Unlimited licenses for IPsec Client S/W (Incl. docu.). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W15	Contivity Extranet Switch 2000, 180 MHz Pentium Pro, Three PCI Expansion Slots, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-bit) Encryption (Includes documentation and Netscape Directory Server 128-Bit Encryption). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W18	Contivity Extranet Switch 4000, 200MHz Pentium Pro, 3 PCI Expansion slots, Dual Redundant Pwr Supply and Storage Sys, Server S/W with (128-bit) Encryption (Includes documentation and NDS 128Bit Encryption). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W21	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W22	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, Unlimited License for IPsec client S/W, (Includes Documentation). (Includes power cord commonly used in Israel)	PASS	N/A	N/A	N/A	
DM1401W24	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (128-Bit) Encryption (Includes Documentation and Netscape Directory Server, 128-Bit Encryption). See Note 1. (Israel)	PASS	N/A	N/A	N/A	
DM1401W25	Contivity Extranet Switch 1500, 300 MHz Pentium II, Dual 10/100 Ethernet LAN Ports, Server S/W with (56-Bit) Encryption, (Includes Documentation and Netscape Directory Server, 56-Bit Encryption). (Includes power cord commonly used in Israel)	PASS	N/A	N/A	N/A	
DM2104002	T3/HSSI Card (FACTORY INSTALL)	PASS	N/A	N/A	N/A	
DM2104003	T3/HSSI Card with Interface Cable (FACTORY INSTALL) Contivity Extranet Switch 4500 Option Only.	PASS	N/A	N/A	N/A	
DM2111002	T3/HSSI Card (FIELD INSTALL)	PASS	N/A	N/A	N/A	
DM2111003	T3/HSSI Card with Interface Cable (FIELD INSTALL). Contivity Extranet Switch 4500 Option Only.	PASS	N/A	N/A	N/A	
DN3214001	DCE Manager for HP Openview - Unix	PASS	N/A	N/A	N/A	
DN3800701	5216 Standalone RADSL CPE - Single user, 1Mbps, 10BaseT Connector (RJ45), optional POTS splitter (RJ11)	PASS	N/A	N/A	N/A	
DN3800702	5246 Standalone RADSL CPE - IP Bridged Model, supports up to 32 users, 2.56 Mbps, 10BaseT Connector (RJ45), optional POTS splitter (RJ11)	PASS	N/A	N/A	N/A	
DN3800001	5216 Standalone RADSL CPE - Single user, 1Mbps, 10BaseT Connector (RJ45), optional POTS splitter (RJ11), 90V, Table Top	PASS	N/A	N/A	N/A	
DN3800002	5246 Standalone RADSL CPE - IP Bridged Model, supports up to 32 users, 2.56 Mbps, 10BaseT Connector (RJ45), optional POTS splitter (RJ11), 90V, Table Top	PASS	N/A	N/A	N/A	
DN3804002	8540, 4 port RADSL blade for DSLAM - (works with 5100,5200 series RADSL CPE)	PASS	N/A	N/A	N/A	
DP0002001	Nortel Networks Versalar 15000 12 slot chassis including one AC power supply and air flow modules	PASS	N/A	N/A	N/A	
DP0002003	Nortel Networks Versalar 15000 12 slot chassis including one DC power supply and air flow modules	PASS	N/A	N/A	N/A	
DP0008001	BayRS-Provider Mode Software Version V1.0.0.0 for Versalar 15000 (includes 16 MB Flash Card and documentation set on CD ROM)	PASS	N/A	N/A	N/A	
DP0008001	Carrier Routing Services Software Version 1.1.0.0 for Versalar 15000 (includes 16 MB Flash Card and documentation set on CD ROM)	PASS	N/A	N/A	N/A	
DP0011001	Channelized Access Processor (CAP) for FT1, T1, T3	PASS	N/A	N/A	N/A	
DP0011002	ATM Trunk Processor OC-12c (ATP-OC12)	PASS	N/A	N/A	N/A	
DP0011003	System Services Processor (SSP) with 128MB memory	PASS	N/A	N/A	N/A	
DP0011004	System Services Processor (SSP) with 256MB memory	PASS	N/A	N/A	N/A	
DP0011005	Internet Forwarding Processor (IFP) with RSP	PASS	N/A	N/A	N/A	
DP0011006	System Services Processor 128 to 256MB Memory Upgrade Kit	PASS	N/A	N/A	N/A	
DP0011009	SSP-E (Ethernet) Interface Card	PASS	N/A	N/A	N/A	
DP0011010	SSP-C (Console) Interface Card	PASS	N/A	N/A	N/A	
DP0011013	1xOC-12c/STM-4 Trunk Interface Single Mode (IR)	PASS	N/A	N/A	N/A	
DP0011014	1xOC-12c/STM-4 Trunk Interface Multi-mode	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DP0011015	Versalar 15000 AC Power Supply	PASS	N/A	N/A	N/A	
DP0011016	6xT-3 (Hex T3) Channelized Access Interface	PASS	N/A	N/A	N/A	
DP0011017	Versalar 15000 12 Slot Spare Chassis with mid-plane and fan board (no power supply)	PASS	N/A	N/A	N/A	
DP0011018	Versalar 15000 DC Power Supply	PASS	N/A	N/A	N/A	
DP0011019	Versalar 15000 Cooling Module	PASS	N/A	N/A	N/A	
DP0011020	Versalar 15000 Air Flow Module for Processor slot	PASS	N/A	N/A	N/A	
DP0011021	Versalar 15000 Air Flow Module for Interface slot	PASS	N/A	N/A	N/A	
DP0011022	Versalar 15000 23" Rack Mount Kit	PASS	N/A	N/A	N/A	
DP0011023	Versalar 15000 Bezel Kit	PASS	N/A	N/A	N/A	
DP0011024	Versalar 15000 AC Input Module	PASS	N/A	N/A	N/A	
DP0011025	Versalar 15000 Power Supply Blank Converter	PASS	N/A	N/A	N/A	
DP0011026	Versalar 15000 DC Input Module	PASS	N/A	N/A	N/A	
DP0011028	Versalar 15000 Access Redundancy Module (ARM)	PASS	N/A	N/A	N/A	
DP0011029	Versalar 15000 Cable Management Bracket	PASS	N/A	N/A	N/A	
DP0011030	Clear DS3 Access Processor (CAP-DS3)	PASS	N/A	N/A	N/A	
DP0011031	Channelized DS3 and Clear DS3 Access Processor (CAP-M13/DS3) for FT1, T1, T3 and 1:N redundancy	PASS	N/A	N/A	N/A	
DP0015002	Versalar 15000 V1.0.0.0 On-Line Documentation Set CD-ROM.	PASS	N/A	N/A	N/A	
DP0015003	Versalar 15000 V1.1.0.0 On-Line Documentation Set CD-ROM.	PASS	N/A	N/A	N/A	
DP0020001	Versalar 15000 US Power Cord 15A/208-220V, NA	PASS	N/A	N/A	N/A	
DQ1301001	Centillion Integrator 400 for Voice/Video. Includes 4 Circuit Emulation DS1 and 1 OC-3c ATM ports, and power supply.	PASS	N/A	N/A	N/A	
DQ1302001	Centillion 1600 10G ATM Core Switch including Chassis, Power Supply, 10G Fabric, Processor Module and PNNI License.	PASS	N/A	N/A	N/A	No Issues
DQ1302002	Centillion 1600 10G ATM Core Switch including Chassis, Dual Redundant Power Supplies, Dual Redundant 10G Fabrics, Processor Modules and PNNI License.	PASS	N/A	N/A	N/A	No Issues
DQ1302003	Centillion 1400 5G ATM Core Switch including Chassis, Power Supply, 5G Fabric and Processor Module, and PNNI License.	PASS	N/A	N/A	N/A	No Issues
DQ1302004	Centillion 1400 5G ATM Core Switch including 8 Slot Chassis, Dual Redundant Power Supplies, Dual Redundant 5G Fabrics and Processor Modules, and PNNI License.	PASS	N/A	N/A	N/A	No Issues
DQ1302005	Centillion 1200 2.5G ATM Core Switch including 4 Slot Chassis, Power Supply, 2.5G Fabric and Processor Module, and PNNI License.	PASS	N/A	N/A	N/A	No Issues
DQ1304001	Single Port OC-12c Intermediate Reach, Single Mode Fiber Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304002	Single Port OC-3c Long Reach, Single Mode Fiber Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304003	4 Port OC-3c Short Reach, Single Mode Fiber Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304004	4 Port OC-3c Multi Mode Fiber Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304005	4 Port 155Mbps UTP Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304006	2 Port DS3 COAX WAN Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304007	2 Port E3 COAX WAN Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304008	4 Port DS1 WAN Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304009	4 Port E1 WAN Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304010	4 Port DS1 Circuit Emulation Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304011	4 Port E1 Circuit Emulation Module for the Centillion 1600, 1400, and 1200 ATM Switches.	PASS	N/A	N/A	N/A	No Issues
DQ1304016	LANE Server Card for C1000 switches - provides all LANE LECS LES/BUS functions.	PASS	N/A	N/A	N/A	
DQ1311001	Centillion 1600 10G Fabric, Processor Module.	PASS	N/A	N/A	N/A	No Issues
DQ1311007	Centillion 1400 5G Fabric, Processor Module.	PASS	N/A	N/A	N/A	No Issues
DQ1311011	Centillion 1200 2.5G Fabric, Processor Module.	PASS	N/A	N/A	N/A	No Issues
DQ1311015	Centillion 1200 Ethernet Out-of-Band Port Card.	PASS	N/A	N/A	N/A	No Issues
DR4001001	Baystack 660 Wireless PC Card 2Mbps Direct Sequence IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN U.S., Canada and Australia.	PASS	N/A	N/A	N/A	
DR4001002	Baystack 660 Wireless Access Point 2Mbps Direct Sequence IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN U.S., Canada and Australia.	PASS	N/A	N/A	N/A	
DR4001003	Baystack 650 Wireless PC Card 1Mbps Frequency Hopping IEEE 802.11. THIS UNIT ONLY FOR SALE IN Austria, Belgium, Denmark, Finland, Germany, Ireland, Luxembourg, Netherlands, Norway, Sweden, Switzerland and United Kingdom.	PASS	N/A	N/A	N/A	
DR4001004	Baystack 650 Wireless PC Card 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN Spain.	PASS	N/A	N/A	N/A	
DR4001005	Baystack 650 Wireless PC Card 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN France.	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
DR4001006	Baystack 650 Wireless PC Card 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN U.S., Canada and Australia.	PASS	N/A	N/A	N/A	
DR4001007	Baystack 650 Wireless Access Point 1Mbps Frequency Hopping 802.11 compliant. THIS UNIT ONLY FOR SALE IN Austria, Belgium, Denmark, Finland, Germany, Luxembourg, Netherlands, Norway, Sweden and Switzerland.	PASS	N/A	N/A	N/A	
DR4001008	Baystack 650 Wireless Access Point 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN Spain.	PASS	N/A	N/A	N/A	
DR4001009	Baystack 650 Wireless Access Point 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN France.	PASS	N/A	N/A	N/A	
DR4001010	Baystack 650 Wireless Access Point 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN United Kingdom and Ireland.	PASS	N/A	N/A	N/A	
DR4001011	Baystack 650 Wireless Access Point 1Mbps Frequency Hopping IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN U.S., Canada and Australia.	PASS	N/A	N/A	N/A	
DR4001019	BayStack 660 Wireless Access Point 2MMbps Direct Sequence IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN AUSTRALIA.	PASS	N/A	N/A	N/A	
DR4001020	BayStack 650 Wireless Access Point 2MMbps Direct Sequence IEEE 802.11 compliant. THIS UNIT ONLY FOR SALE IN AUSTRALIA.	PASS	N/A	N/A	N/A	
DR4001034	BayStack 660 Wireless Starter Kit-2Mbps Direct Sequence IEEE 802.11, includes Access Point and one PC Card. This starter kit only for sale in United States and Canada.	PASS	N/A	N/A	N/A	
DR4001039	BayStack 650 Wireless Starter Kit, 1Mbps Frequency Hopping IEEE 802.11. This unit only for sale in the United States and Canada.	PASS	N/A	N/A	N/A	
DR4001040	BayStack 660 Wireless PC Card 2 Mbps Direct Sequence IEEE 802.11 compliant. This unit only for sale in United Kingdom, Ireland, Austria, Germany, and Netherlands.	PASS	N/A	N/A	N/A	
DR4001041	BayStack 660 Wireless Access Point 2 Mbps Direct Sequence IEEE 802.11 compliant. This unit only for sale in United Kingdom and Ireland.	PASS	N/A	N/A	N/A	
DR4001042	BayStack 660 Wireless Access Point 2 Mbps Direct Sequence IEEE 802.11 compliant. This unit only for sale in Austria, Germany, and Netherlands.	PASS	N/A	N/A	N/A	
DS1402001	Accelar 8010 10 slot chassis. Includes chassis, dual backplane, two fan trays, RS232 cable for management console, rack mount kit, and cable guide kit. Requires at least one power supply, up to three power supplies supported.	PASS	N/A	N/A	N/A	
DS1404006	8132TX Edge Switch Module. 32 port 10/100Base-TX, 1 MDA Slot, Console port.	PASS	N/A	N/A	N/A	
DS1404010	8132TX Edge Switch Module bundled with Accelar 8000 Edge Switch Software License and Software Kit (includes license, software, Device Manager, and all documentation. One Software License required per chassis. Version 1.0	PASS	N/A	N/A	N/A	
DS1405A01	8001PS 100-240 VAC Power Supply. At least one power supply required per Accelar 8000 chassis. (No power cord included)	PASS	N/A	N/A	N/A	
DS1405B01	8001PS 100-240 VAC Power Supply. At least one power supply required per Accelar 8000 chassis. (Includes European Schuko power cord common in Austria, Belgium, Finland, France, Germany, The Netherlands, Norway, and Sweden)	PASS	N/A	N/A	N/A	
DS1405C01	8001PS 100-240 VAC Power Supply. At least one power supply required per Accelar 8000 chassis. (Includes power cord used in the UK and Ireland)	PASS	N/A	N/A	N/A	
DS1405D01	8001PS 100-240 VAC Power Supply, at least one power supply required per Accelar 8000 chassis. (Includes power cord used in Japan)	PASS	N/A	N/A	N/A	
DS1405E01	8001PS 100-240 VAC Power Supply. At least one power supply required per Accelar 8000 chassis. (Includes North American power cord)	PASS	N/A	N/A	N/A	
DS1405F01	8001PS 100-240 VAC Power Supply. At least one power supply required per Accelar 8000 chassis. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
DS1410001-1.0	Accelar 8000 Edge Switch Software License and Software Kit (Includes license, software, Device Manager, and all documentation). One Software License required per chassis. Version 1.0	PASS	N/A	N/A	N/A	
DS1411001	Fan tray (spare) for Accelar 8010 10 slot chassis.	PASS	N/A	N/A	N/A	
DS2033001	8100-2FX 2-port 100BASE-FX MDA (for Accelar 8000 Edge Switches).	PASS	N/A	N/A	N/A	
DS2033002	8100-4FX 4-port 100BASE-FX MDA (for Accelar 8000 Edge Switches)(Mini MT RJ connectors).	PASS	N/A	N/A	N/A	
DS2033003	8100-4TX 4-port 10BASE-T/100BASE-TX MDA (for Accelar 8000 Edge Switches).	PASS	N/A	N/A	N/A	
FRS/*	FrameRunner	PASS	N/A	N/A	N/A	Dates/Year not used in product. No action required.
L271X-A	Model L271X-A License for Advanced IP Network Management Agent for Model 271x.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L3174-A	Model L3174-A 3174 Optional Frame Relay Feature adds support of Frame Relay networks to Model 3174 Workstation Controller Module. Supports DSPU, SNA Gateway, SRB and IP Routing functions.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
L3395-B	Model L3395-B TN3270 Software License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L3395-C	Model L3395-C XRemote Software License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L3395-D	Model L3395-D ARAP Software License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L3395-E	Model L3395-E Multisessions Software License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L3395-F	Model L3395-F IPX Software License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L5390-01	Advanced features software license for the 5390 Communications Server base unit. Advanced features support TN3270, Apple, and IPX environments.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
L5390-02	Model L5390-02 LAT software license for the 5390 Communications Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L5390-03	Model L5390-03 IPX Software license for the 5390 Communications Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L5390-04	Model L5390-04 ARA and TN3270 Software license for the 5390 Communications Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
L670-01	Model L670-01 License for 5 additional support staff clients for FaultMan for UNIX. Model 670 Release 1.0 FaultMan for UNIX required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
L670-03	Model L670-03 License for 1 additional support staff client for FaultMan for UNIX. Model 670 Release 1.0 FaultMan for UNIX required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
L671-01	Model L671-01 Distributed License for PolicyMan for UNIX. Model 671 Release 1.0 PolicyMan for UNIX required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
L672-01	Model L672-01 Distributed License for TrendMan for UNIX. Model 672 Release 1.0 TrendMan for UNIX required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
L727-03	Model L 727-03 X.25/Frame Relay/SMDs Software License Option for Model 3800A.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
M625-1	Migration from LattisViews 1.0 to Optivity 1.1 for HP OpenView (UNIX). Requires HP OpenView Network Node Manager.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
M626-1	Migration from LattisViews 1.0 to Optivity 1.1 for IBM NetView/6000.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
MR-2	FrontRunner	PASS	N/A	N/A	N/A	Dates/Year not used in product. No action required.
N/A	VoxBox	Discontinued	N/A	N/A	N/A	Dates/Year not used in product. No action required.
N/A	X.25 Switches or PADs (MicomBox, LX PAD)	Discontinued	N/A	N/A	N/A	No upgrade planned (manufacture discontinued).
N/A	Statistical Multiplexers (MicomBox, LCI, Val-U-Mux, Line Saver)	Discontinued	N/A	N/A	N/A	No upgrade planned (manufacture discontinued).
N/A	Instagate 1500	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Instalink 460	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Instamux 470/480	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Instantet 6000	Discontinued	N/A	N/A	N/A	No upgrade planned.
N/A	Micro 100	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 400/420/430	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 4000 series modems	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 600	Discontinued	N/A	N/A	N/A	No upgrade planned.
N/A	Micro 700	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 750	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 800/8000	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N/A	Micro 850/8500	Discontinued	N/A	N/A	N/A	Dates/Year not used in product.
N11	Data Collection Module (DCM) for Distributed 5000 NMM	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
NETM*	NetMan Rel. 1.0 thru 2.3	FAIL	1.0-2.3	N/A	N/A	Upgrade to Rel. 2.4 (Q4 '98) required at standard upgrade cost.
NETM*	NetMan Rel. 2.4	PASS	2.4	N/A	N/A	Upgrade available Q4 '98.
NTBQ98AA	V.35 Cable Back to Back - 6ft.	PASS	N/A	N/A	N/A	
NTBQ99AA	V.35 Cable Back to Back - 15ft.	PASS	N/A	N/A	N/A	
PMG703	G.703 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
PMRS232	RS232 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
PMRS449	RS449 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
PMT1	T1 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
PMV35	V.35 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
PMX21	X.21 Personality Module for Model 3356 Ethernet Remote Bridge.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
RMAD1411002	Model 5000BH full chassis upgrade **. Upon return of the replaced 5000N/NT/AH chassis a credit of \$1,500 will be applied.***	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
RMAD1411004	Model 5000BH with FDDI full chassis upgrade **. Upon return of the replaced 5000F chassis a credit of \$1,500 will be applied.***	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
RMAD2211004	Model 5000C full chassis upgrade. List price of \$2,245 net, after customer credit of \$750 applied on return of the replaced 5000AH/F/BH/N/NT/ chassis.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
SL2310-A	License for Advanced Network Management Agent for Model 2310.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
SL2810-A	License for Advanced Network Management Agent for Model 2810.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
SU3395-A	Model SU3395-A LAT Upgrade License for Terminal Server.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
U3040	Model U3040 provides an upgrade for Model 3040 customers to the larger 240Mb Hard Drive and Solaris 1.1 software available on the Model 3040S.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U5390-FE	Model U5390-FE 2Mb Flash EPROM option kit.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
U600	Upgrade from Lattis EZ-View Version 1.x or 2.x to Lattis EZ-View Version 2.2 (Windows 3.1 required).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U620-1	Upgrade from Optivity 2.0 for NMS to Optivity 2.1 for NMS. Requires NMS 2.0.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U620-2	Upgrade from Optivity 1.0 for NMS to Optivity 2.1 for NMS. Includes Upgrade from Novell NMS Runtime v1.15 to NMS 2.0.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U625-1	Upgrade from Optivity 4.0 to Optivity 4.1 for HP OpenView Network Node Manager. Requires HP OpenView Network Node Manager 3.X.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U625-7	Upgrade from HP OpenView Network Node Manager 3.3 to 4.0 for SunOS and Solaris					Hewlett-Packard Product
U625-8	Upgrade from HP OpenView Network Node Manager 3.3 to 4.0 for HP-UX					Hewlett-Packard Product
U626-1	Upgrade from Optivity 4.0 to Optivity 4.1 for IBM NetView/6000. Requires IBM NetView/6000 2.X.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U626-4	Upgrade to IBM NetView/6000 4.1 for AIX from 3.1.					IBM
U636-03	Upgrade from LattisNet Manager for DOS 4.x to Optivity 4.4 for HP OpenView/Windows. Windows 3.1 required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U637-1	Upgrade from Optivity 4.0 for SunNet Manager (637-1 or 637-2) to Optivity 4.1 for SunNet Manager.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U637-4	Upgrade from SunNet Manager 2.x to 2.2 for SunOS / Solaris 1.x.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U637-8	Upgrade from SunNet Manager 2.x to 2.2 for Solaris 2.x.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U651-01	Model U651-01 NETMAP for IBM OS/2 Upgrade from Version 2.x to Version 3.0. Requires IBM NetView/PC and TCP/IP Software (See Product Data Sheet for Version Compatibility).	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U673	Model U673 MeterMan for UNIX (SunNet Manager) Upgrade from Release 1.0 to Release 2.0.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U695	Model U695 RouterMan for UNIX (Sun, HP, or IBM) Upgrade from Release 1.0 to Release 2.1.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U696	Model U696 Upgrade from PathMan Release 1.0 to Release 2.0. Model 637-2 Optivity for UNIX Release 3.0 with SunNet Manager Release 2.0 required.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U698	Upgrade Sun/UNIX Network Management Application for ATM. Upgrade from Release 1.x to 2.0.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U761	Model U761 Switched Virtual Channel Connection Management System for LattisCell ATM switches. Upgrade from Release 1.0 to Release 1.1.	Discontinued	N/A	N/A	N/A	Untested/Product discontinued prior to January 1, 1997
U776-01	Model U776-01 Version 9.0 Upgrade Kit for the 5390. Order one kit per unit for new boot PROMs. Also includes 9.0 Software CD, CD documentation, and client software for IPX environments.	PASS	N/A	N/A	N/A	Product does not contain clock feature, no year 2000 issues.
UGDJ1401A06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1401A08	XLR 1050-B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1401B06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1401B08	XLR 1051B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1401C06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1401C08	XLR 1051B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1401D06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
UGDJ1401D08	XLR 1051B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
UGDJ1401E06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
UGDJ1401E08	XLR 1051B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
UGDJ1401F06	XLR 1050B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
UGDJ1401F08	XLR 1051B base unit with 12 10/10BASE-TX ports and one 1000Base-SX Ethernet interface, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
UGDJ1402A13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1402A14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1402A15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1402A16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (No power cord included)	PASS	N/A	N/A	N/A	
UGDJ1402B13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1402B14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1402B15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1402B16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (Includes European Schuko power cord)	PASS	N/A	N/A	N/A	
UGDJ1402C13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1402C14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1402C15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1402C16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1402D13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes power cord for the UK and Ireland)	PASS	N/A	N/A	N/A	
UGDJ1402D14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
UGDJ1402D15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
UGDJ1402D16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (Includes power cord for Japan)	PASS	N/A	N/A	N/A	
UGDJ1402E13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
UGDJ1402E14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes North American power cord)	PASS	N/A	N/A	N/A	
UGDJ1402E15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	
UGDJ1402E16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (Includes North American power cord)	PASS	N/A	N/A	N/A	

Bay Networks, a Nortel Networks Division
Year 2000 product matrix

Order No.	Product Description	PASS / FAIL	Software Version	Firmware Level	Hardware Revision	Remarks
UGDJ1402F13	Accelar 1100-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports. Includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	<p>Upgrade to Rel. 5.3 available at cost of service, but not required.</p> <p>Upgrade available</p> <p>Dependant on operating software. Upgrade operating software if necessary.</p> <p>Dependant on operating software. Upgrade operating software if necessary.</p>
UGDJ1402F14	Accelar 1100R-B base unit with 2 slots and 16 autosensing 10BASE-T/100BASE-TX Ethernet ports, includes device manager application software, redundant power supplies. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
UGDJ1402F15	Accelar 1150-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
UGDJ1402F16	Accelar 1150R-B base unit with 2 slots and 4 1000BASE-SX Gigabit Ethernet ports, redundant power supplies, includes device manager application software. (Includes Australian power cord, also used in New Zealand and the PRC)	PASS	N/A	N/A	N/A	
UGDJ1404053	XLR1202SR-B 2-port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
UGDJ1404054	XLR1202SX-B 2 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404056	XLR1202SX-B 2 port 1000BASE-SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404057	XLR1202LR-B 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
UGDJ1404058	XLR1216TX-B 16 port autosensing 10BASE-T/100BASE-TX Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404059	XLR1208FX-B 8 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404060	XLR1216FX-B 16 port 100BASE-FX Fast Ethernet Mini MT-RJ interface module.	PASS	N/A	N/A	N/A	
UGDJ1404061	XLR1216TF-B 14 10/100BASE-TX and 2 100BASE-FX Fast Ethernet ports with Mini MT-RJ connectors.	PASS	N/A	N/A	N/A	
UGDJ1404062	XLR1202XD-B 2 port 100BASE-LX long distance Gigabit Ethernet interface module. For use only with other Accelar XD and XD-A interfaces.	PASS	N/A	N/A	N/A	
UGDJ1404064	XLR1102SX-B 2-Port 1000BASE/SX Gigabit Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404065	XLR1102SR-B 2 port 1000BASE-SX Gigabit Ethernet interface module with Linksafe Redundant Layer.	PASS	N/A	N/A	N/A	
UGDJ1404067	XLR1102LX-B 2 port 1000BASE-LX Gigabit Ethernet interface module for the XLR 1100.	PASS	N/A	N/A	N/A	
UGDJ1404068	XLR1102LR-B 2 port 1000BASE-LX Gigabit Ethernet interface module with Linksafe redundant physical layer.	PASS	N/A	N/A	N/A	
UGDJ1404069	XLR1108TX-B 8 port autosensing 10BASE-T/100BASE-TX Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404070	XLR1104FX-B 4 port 100BASE-FX Ethernet interface module.	PASS	N/A	N/A	N/A	
UGDJ1404071	XLR1108FX-B 8 port 100BASE-FX Fast Ethernet Mini MT-RJ interface module.	PASS	N/A	N/A	N/A	
UGDJ1404072	XLR1102XD-B 2 port long distance Gigabit Ethernet interface module. For use only with other Accelar XD-B interfaces.	PASS	N/A	N/A	N/A	
VFM-*	Voice/Fax Multiplier (V/FM) Rel. 1.0, 2.0	PASS	1.*-2	N/A	N/A	
VFM-*	Voice/Fax Multiplier (V/FM) Rel. 2.1	PASS	2.1	N/A	N/A	
VIP-*	V/IP Gateway Rel. 1.x or 2.0	PASS	1.*-2	N/A	N/A	
VISION/**	MICOM Vision Manager/ MICOM Vision Manager 2	PASS	N/A	N/A	N/A	